Pormerly 9-331) DEPARTMENT OF THE INTERIOR (Other later letter) BUREAU OF LAND MANAGEMENT DD	Expires August 31, 1985 5. LEABE DERIGNATION AND SERIAL NO. NMO5020
SUNDRY NOTICES AND REPORTS ON WELES 10 (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
I. OIL THE GAS TO THE CONTRACT OF THE CONTRACT	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR ARROWHEAD OIL CORPORATION	8. PARM OR LEASE NAME H.E. YATES A FED.
3. ADDRESS OF OPERATOR BOX 548, ARTESIA, NM 88210	9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FNL, 2310' FWL	N. HACKBERRY YATES S-R 11. BBC., T., R., M., OR BLK. AND BURNEY OR AREA Sec 29-T19S-R31E
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, ET, CR., etc.) 34/8 GL	12. COUNTY OR PARISH 18. STATE
16. Check Appropriate Box To Indicate Nature of Notice, Report, or O	Eddy N.M.
	ENT ESPOST OF:
TEST WATER SHUT-OFF PRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS (Other) WATER SHUT-OFF FRACTURE TREATMENT ABANDON® (Other) (Other) (Note: Report results Completion or Recompletion To describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates.)	ALTERING CARING ARANDOSMENTO of multiple completion on Well tion Report and Log form.)
WE PROPOSE TO PLUG & ABANDON AS FOLLOWS: 8 5/8 csg is set @ 706' w/50 sax cement; 2 7/8 csg 2330' w/150 sax cement. We will circulate hole w/mu Spot a 400' plug @ 2300' back to 1900', tag, cut 2 set 100' plug in and out of stub, tag, set 100' plu Set 15 sx plug @ surface. Install dry hole marker,	1d laden fluid. 7/8 csg @ 1800', 1g @ 750'-650', tag.
JAN 27 1 O. C. I ARTESIA, C	986 D.

*See Instructions on Reverse Side