

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
En , Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

MAR 19 1991

O. C. D.

ARTESIA, OFFICE

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.  
NM 0107697

7. Lease Name or Unit Agreement Name

Jones Federal

8. Well No.

2

9. Pool name or Wildcat

Lusk Strawn

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

FINA OIL & CHEMICAL COMPANY

3. Address of Operator

Box 2990, Midland, TX 79702-2990

4. Well Location

Unit Letter G : 1650 Feet From The North Line and 1650 Feet From The East Line  
Section 25 Township 19S Range 31E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
KB 3543' (12.5' AGL)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP Plus 10' Cmt Plug above Fish @ 7070' to Isolate Strawn Perfs @ 11414-456'.  
Determine Free-Pt. of 5-1/2" csg. & pull as much pipe as possible.  
Set 100' Cmt Plug w/50' above & below top of 5-1/2" csg.  
Set 8-5/8" CIBP + 10' Cmt. Plug above hole in csg. @ 3752' to isolate bad section.  
Set 10' Cmt. Plug @ surface.  
Cut csg. off @ 3" below Ground Level & weld steel cap on 13-3/8" csg.  
Erect Permanent Steel Marker.  
Restore location to natural state.

Note: Hole will be filled w/9.5# mud in all space not filled w/Cmt.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Neva Herndon*

TITLE

Petrotechnical Associate

DATE

3-15-91

TYPE OR PRINT NAME

Neva Herndon

TELEPHONE NO. 915 688-0608

(This space for State Use)

APPROVED BY

*Rogers*

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: