Submit 3 Copies to Appropriate District Office

State of New Mexico l gy, Minerals and Natural Resources Departme

Form	C-103
Revis	ed 1-1-89

DISTRICT I

OIL CONSERVATION DIVISION

F.O. Dawer DD, Artesia, NM 88210	FEB 1 4 1991 O. C. D. ARTESIA, OFFICE SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: ORL ORL ORL ORL ORL ORL ORL OR	P.O. Box 1980, Hobbs, NM 882		P.O. Box 20		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS PORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PILUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: ONE WILL OR TO DEEPEN OR PILUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Well: ONE WILL OR THIS POWN FOR THE WEST OF HERM 2. Name of Operator 1. Type of Well: ONE WILL OR THIS POWN FOR THE WEST OF HERM 1. Line and Good Form The West Line 1. Well Location 1. Well Location 1. Township 20S Range 24E NMPM Eddy County 10. Elevation (Show whether Dr., REB. RT, GR. etc.) Section 1 Township 20S Range 24E NMPM Eddy County 10. Elevation (Show whether Dr., REB. RT, GR. etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING CASING TEST AND CEMENT JOB OTHER: PULL OR ALTER CASING OTHER PERFORMED ABANDON HERE PErforate holes in existing zone X DIFFER Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPR-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS OFFICE	DISTRICT II P.O. Drawer DD, Artesia, NM 8	8210 S	Santa Fe, New Mexico	5 87504-2088 FEB 1 4 1991	5. Indicate Type of Lease STATE FEE X
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ONLY WELL ON SUCH PROPOSALS.) 2. Name of Operator 105 South 4th St., Artesia, NM 88210 3. Address of Operator 105 South 4th St., Artesia, NM 88210 4. Well Lossidos Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 1 Township 20S Range 24E NMPM Eddy County 10. Elevation (Show whether DP, RKB, RT, GR, sic.) 3624 ' CR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDON SAING TEST AND CEMENT JOB OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent datas), and give pertinent datas, including estimated data of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TH with the gand packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: ON WELL ST	DISTRICT III 1000 Rio Brazos Rd., Aztec, NM	87410			6. State Oil & Gas Lease No.
2. Name of Operator 2. Name of Operator 3. Address of Operator 105 South 4th St., Artesia, NM 88210 4. Well Location Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 1 Township 205 Range 24E NMPM Eddy County 10. Elevation (Show whather DF, RKB, RT, GR, etc.) 3624' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT TEMPORARILY ABANDON THE PERFORM OF ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed worth) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) THE with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	2. Name of Operator 2. Name of Operator 3. Address of Operator 105 South 4th St., Artesia, NM 88210 3. Address of Operator 105 South 4th St., Artesia, NM 88210 4. Well Location Unit Letter D: 660 Feet From The North Line and 660 Feet From The West Line Section 1 Township 20S Range 24E NMFM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3624 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: CASING TEST AND CEMENT JOB COHMENT OF HERE Perforate holes in existing zone X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEB RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	(DO NOT USE THIS FORM DIFFEREN	FOR PROPOSALS IT RESERVOIR. US	TO DRILL OR TO DEEPE SE "APPLICATION FOR P	ELLS EN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
Remedial Work Plug and Abandon Remedial Work Altering Casing	Section 1 Township 20S Range 24E NMPM Eddy County	1. Type of Well: OIL WELL XX	GAS WELL	OTHER		Foster AN Com
North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 105 South 4th St., Artesia, NM 88210 South 150 Sout	10.5 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 10.5 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn 10.5 South 4th St., Artesia, NM 88210 North Dagger Draw Upper Penn North Line and 660 Feet From The West Line Section 1 Township 20S Range 24E NMPM Eddy County 10. Elevation (Show whather DF, RKB, RT, GR, etc.) 3624' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: Perforate holes in existing zone X OTHER: Perforate holes in existing zone X OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	2. Name of Operator	CORPORATION			1
Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 1 Township 20S Range 24E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3624' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 1 Township 20S Range 24E NMPM Eddy County 10. Elevation (Show whather DF, RKB, RT, GR, etc.) 3624 ' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	3. Address of Operator				1
Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 1 Township 20S Range 24E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3624' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT THE Perforate holes in existing zone X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line Section 1 Township 20S Range 24E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3624' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone X OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.		., Artesia,	NM 88210		North Dagger Draw Upper Penn
10. Iowanny 10. Io	10. 10.	Τ.	: 660 Feet 1	From The North	Line and660	Feet From The West Line
10. Iowanny 10. Io	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3624' GR	1		205	Page 24E	NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone X 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: Perforate holes in existing zone X OTHER:	Section ¹	Town	18h1p 200 10. Elevation (Show wheth		V/////////////////////////////////////
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: Perforate holes in existing zone Tother: Perforate holes in existing zone Tother: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone X OTHER: OTHER: Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.					<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: Perforate holes in existing zone Tother: Perforate holes in existing zone Tother: Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone X OTHER: OTHER: Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.		Chaple Approp	riate Boy to Indicate	e Nature of Notice, R	Report, or Other Data
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone X OTHER: OTHER: Perforate holes in existing zone X OTHER: OTHE	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: Perforate holes in existing zone 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.				SLIF	RSECUENT REPORT OF:
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: Perforate holes in existing zone 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: Perforate holes in existing zone 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	NOTICE	OF INTENTIO	אכו אכ:	_	
PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: Perforate holes in existing zone 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	PERFORM REMEDIAL WORK	Ç 🔲 PLI	UG AND ABANDON	-	
OTHER: Perforate holes in existing zone 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	OTHER: Perforate holes in existing zone 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	TEMPORARILY ABANDON	Сн	IANGE PLANS	-	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	PULL OR ALTER CASING			CASING TEST AND C	EMENT JOB L
Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.			<u> </u>	-	
Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	Propose to: 1) Tag cement @ ±7873'. Drill out cement to 7830'. 2) Perforate Canyon Dolomite as follows: (4" casing gun, .50" holes) 7810, 12, 14, 16, 18, 20' (2 SPF-12 holes) 3) TIH with tbg and packer. Set packer @ ±7800'. 4) Treat down tubing @ ± 1 BPM with 2500 gals 20% HCL acid. 5) Swab and evaluate.	12. Describe Proposed or Compwork) SEE RULE 1103.	pleted Operations (Cle	arly state all pertinent detail.	s, and give pertinent dates, inc	luding estimated date of starting any proposed
		2) 3) 4) 5)	Perforate C 7810, 12, 1 TIH with tb Treat down Swab and ev	anyon Dolomite 4, 16, 18, 20' g and packer. tubing @ ± 1 BP raluate.	as follows: (4 (2 SPF-12 holes) Set packer @ ±78	00'.

tion above is True and complete to the best of my knowled	ge and belief.	0 10 01
To Dougles	mme Production Supervisor	DATE
1		TELEPHONE NO. 505/748-14
Juanita Goodlett		
ORIGINAL SIGNED BY		
MIKE WILLIAMS		FEB 2 2 1991
SUPERVISOR, DISTRICT IY	_ TME	DATE
ANY:		
	Juanita Goodlett ORIGINAL SIGNED BY MIKE WILLIAMS SUPERVISOR, DISTRICT 19	Juanita Goodlett ORIGINAL SIGNED BY MIKE WILLIAMS SUPERVISOR, DISTRICT IS THE