		11.U.U.U.	J. CUPY	C	:SF
Form 9-331 (May 1963	(May 1963) UI LIED STATES DEPARTMENT OF THE INTER GEOLOGICAL SURVEY		SUBMIT IN TRIPLACATE (Other instructions on re- Verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND BERIAL NO. NM-05470-C	
	SUNDRY NOT not use this form for propo Use "APPLIC	State of the second sec	ON WELLS back to a different reservoir. proposals.)	6. IF INDIAN, ALLOTTEI	S OR TRIBE NAME
1. VIL X GAS UTHER WELL OTHER 2. NAME OF OPERATOR				7. UNIT AGREEMENT NAME	
2. NALL OF OFFRATOR Phillips Petroleum Company 3. ADDRESS OF OFFRATOR				Simon-A 9. Well NO.	
Room 401, 4001 Penbrook St, Odessa, TX 79762 EIA. DF 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements." See also space 17 below.) At surface				2 10. FIELD AND POOL, OF WILDCAT Lusk, Strawn	
	(Unit P) 660'	FS&E lines		11. SEC., T., B., M., OR E SURVEY OR AREA	
14. PERMIT	NA	15. ELEVATIONS (Show whether DE	F, RT, GR, etc.)	14, 195, 3 12. COUNTY OB PARISH	1E 13. STATE
		3558' DF		Eddy	NM
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
TEST	I1	PULL OR ALTER CASING		ENT REPORT OF:	[]
		MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CA	
shoor	OR ACIDIZE	ABANDON®	SHOOTING OR ACIDIZING	ABANDONMEN	
RFLIAIR	(CHANGE PLANS	(Other)		
 (Other) Install artificial lift eqpt X (Norr: Report results of multiple completion on Well Completion or Recompletion Report on form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine at test includes stand date of starting any nent to this work.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertine at test includes stand date of starting any nent to this work.) 					
prope	sed work. If well is directic to this work.) *	mally drilled, give subsurface loca	it details, and give pertinent differences tions and measured and true vertice	inc milig stims ind date	of starting any and zones perti-
Propose: AUG 21 1979					
1. Install surface beam pumping eqpt. U.S. GEULUGICAL SURVEY ARTESIA, NEW MEXICO					
2. MI WS unit, install BOP. If necessary, hot oil well to cut paraffin and swab back. Kill well.					
3. Pull tbg.					
4. Run in w/stg npl, 2-3/8" tbg and tbg anchor. Set tbg at approximately 11400' w/seating npl on bottom and tbg anchor approx. 50' above perfs, set w/19,000# tension. Top 3000' of tbg to be 2-7/8".					
5. Run rods and 1-1/16" insert pump. Test well, restore to production status.					
					·
Series 900 BOP, 3000# WP, double, w/one set blind rams, one set pipe rams					
			lior Reservoir Enginee	r date <u>8-7-</u>	79
(1010-0)	ace for Federal or State office	e use)	HER DEPTRICT LENGINGER		. 34 ^{.0}
CONDITIONS OF APPROVAL, IF ANY:					

*See Instructions on Reverse Side