

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Plugged and Abandoned	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator TEXAS PACIFIC OIL COMPANY	5. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 1069 - Hobbs, New Mexico	7. Unit Agreement Name
4. Location of Well UNIT LETTER F 1650 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 20-S RANGE 25-E NMPM.	8. Farm or Lease Name Buchanan Gas Com.
	9. Well No. 1
	10. Field and Pool, or Wildcat Dagger Draw Morrow Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3530' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Above well was plugged and abandoned 11-3-66 as follows:

1. Set 50 sks. cement 9355-9255'.
2. Set 50 sks. cement 8750-8650'.
3. Set 50 sks. cement 7830-7730'.
4. Set 50 sks. cement 5675-5575'.
5. Set 50 sks. cement 2200-2100'.
6. Set 75 sks. cement 1300-1200'.
7. Set 10 sks. cement at surface.

Will notify you when dry hole marker is installed and location cleaned for inspection.

(this report rec'd 5-15-67)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by SIGNED <u>Sheldon Ward</u>	TITLE <u>Area Superintendent</u>	DATE <u>12-12-66</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>AUG 14 1967</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

DEC 13 1966

O. C. C.
ARTESIA, OFFICE