

NO. OF COPIES RECEIVED	7
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	5

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. OG 272	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name N/A
2. Name of Operator SOUTHWEST PRODUCTION CORPORATION	8. Farm or Lease Name LOWE STATE
3. Address of Operator P. O. BOX 936 ROSWELL, NEW MEXICO 88201	9. Well No. 1
4. Location of Well UNIT LETTER G, 1980' FEET FROM THE North LINE AND 1980 FEET FROM THE EAST LINE, SECTION 11 TOWNSHIP 19S RANGE 28E NMPM.	10. Field and Pool, or Wildcat E. MILLMAN
15. Elevation (Show whether DF, RT, GR, etc.) GR - 3435	12. County EDDY

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to shoot 4½" casing at 1450' and pull same.

Place sixty (60) sacks of cement plug - 2294' to 1750'.
(Top perforation 1803')

Place fifteen (15) sacks of cement plug in bottom of surface casing - 624' to 564'.

Place ten (10) sacks cement plug in top and install dry hole marker.

Level and clean location.

RECEIVED

JUL 13 1967

O. C. C.
ADMINISTRATIVE SECTION

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Walter Clements, Jr. TITLE MANAGER DATE 7/12/67

WALTER CLEMENTS, JR.

APPROVED BY W. A. Grasset TITLE OIL AND GAS INSPECTOR DATE JUL 13 1967

CONDITIONS OF APPROVAL, IF ANY:

Intervals between plugs filled w/ mud
100' Plug at stub of 4½" casing
100 " " base of surface casing ~~411~~ 575-675