

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 064877-F

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR C. W. TRAINER		8. FARM OR LEASE NAME Joyce
3. ADDRESS OF OPERATOR P. O. Box 1100, Hobbs, New Mexico		9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FN & 660' FWL		10. FIELD AND POOL, OR WILDCAT Shugart Queen
14. PERMIT NO.		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 12-19S-31E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3611.8 GL		12. COUNTY OR PARISH Eddy
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input checked="" type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We stopped producing this 5 barrel a day well on April 19, 1967, and I now propose to plug and abandon as follows:

1. Spot 35 sx. cement plug in 4 1/2" casing across perms 3463 - 3506.
2. Shoot 4 1/2" at 2460' (top of cement) and pull.
3. Spot 35 sx. cement plug in and out of 4 1/2" casing stub.
4. Shoot 8 5/8" as deep as free & pull. Temp. Survey showed 790' Top of Cement.
5. Spot 35 sx. cement plug in and out of 8 5/8" stub.
6. Spot 35 sx. cement plug 675' - 750' (in and out of 11 3/4" pipe).
7. Set regulation 4" pipe marker in 10 sx. cement in top of 11 3/4" casing.
8. Clean and level wellsite and tank battery site.

I plan to start this work about May 1, 1967.

RECEIVED

RECEIVED
APR 26 1967
U. S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

C. W. Trainer

TITLE Owner - Operator

DATE April 25, 1967

(This space for Federal or State office use)

APPROVED
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
APR 28 1967
R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side