NO. OF COPIES RECEIVED () DISTRIBUTION ANTA FE // FILE						
ANTA FE		HENICO OU CONSE	DVATION COMMISS		- 20 - C1-	5-21140
FILE	· · · · · ·	MEXICO OIL CONSE		ΨED	Revised 1-1-6	5
· · · · · · · · · · · · · · · · · · ·			REDE	-	5A. Indicate	Type of Lease
11.5.13.5.					STATE	FEE X
	-P		MAR 2 2	1974		& Gas Lease No.
LAND OFFICE			140 0 1		.5. Sidle Off (a Gus Leuse No.
OPERATOR /				-		
			<u> </u>		-{///////	
	N FOR PERMIT TO	DRILL, DEEPEN,	OR PLANSTBACK			
1a. Type of Work					7. Unit Agree	ement Name
DRILL X		DEEPEN	PLI	ЈО ВАСК		
b. Type of Well					8. Farm or Le	
OIL GAS WELL X	OTHER		ZONE	ZONE	Howell.	
2. Name of Operator					9. Well No.	
L	David Fasken				_	
3. Address of Operator		11 11	- 70701		10. Field and	d Pool, or Wildcat
608 First National	Bank Building	, Midland, Texa	AS /9/UL		Morrow	
4. Location of Well	ER LOC	ATED 1980'	FEFT FROM THE NOT	h LIN	• //////	
ONTE EFFE						
AND 2310' FEET FROM	THE East LIN	EOFSEC. 29	TWP. 20-S RGE.	25-E NMP	• <i>UIIIII</i>	
<u> ann ann ann ann ann ann ann ann ann an</u>	THIMMIN .	mmmm	MUIIIIII	IIIIII	12. County	VIIIIII
		///////////////////////////////////////			Eddy	
44444444444444	//////////////////////////////////////	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	ttttttttt	iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	TIMITI I	i i i i i i i i i i i i i i i i i i i
				////////		
********	/////////////////////////////////////	{////////////////////////////////////	19. Proposed Depth	19A. Format	ion	20. Rotary or C.T.
			98001	Morro	w	Rotary
21. Elevations (Show whether DF	RT. etc.) 21A. Kind	& Status Plug. Bond	21B. Drilling Contract			. Date Work will start
3542 9,		_	Warton Drlg.			h 28, 1974
23.	500		The cost manys			
SIZE OF HOLE	SIZE OF CASING	48#	200'	2	00	EST. TOP Surface
12-1/4"	<u>8-5/8"</u> 4-1/2"	24# & 32#	3200'		00	Surface
7-7/8"	4-1/2"	11.6#	9800'		50	7000'
1 m drill 17-	1/2" hole to 20	0' w/soud mud	- set and cem	ent 13-3/	'8" casing	at 200'.
2. Install 13-3	/8" X 12" 3000	W.P. casinghea	d and Double	Ram Hydra	ulic BOP.	
	" hole to 3200"	Set and cem	ent 8-5/8" ca	sing at i	200.	
2 mail 11 12_1 //	IDTE M JEON					
2 Prod 1 1 1 2 1 //	# 2000 V 124	- 3000 WD Cagi	nonead spool	with 12"	X 3000 WP	Shaffer Type
3. Drill $12-1/4$	" - 3000 X 12"	- 3000 WP Casi	nghead spool	with 12"	X 3000 MP	Shaffer Type
3. Drill 12-1/4 4. Nipple up 10	12 ¹¹ 12 ¹¹	- 3000 WP Casi x 3000 WP Hudr	nghead spool il GK Strippe	with 12" r Type B(X 3000 WP)P.	
3. Drill 12-1/4 4. Nipple up 10 "E" Double R 5. Drill 7-7/8"	am BOP and 12" hole to T.D. w	- 3000 WP Casi x 3000 WP Hudr	nghead spool il GK Strippe	with 12" r Type B(X 3000 WP)P.	
 3. Drill 12-1/4 4. Nipple up 10 "E" Double R 5. Drill 7-7/8" 6. DST all pay 	am BOP and 12" hole to T.D. w zones.	- 3000 WP Casi x 3000 WP Hudr	nghead spool il GK Strippe	with 12" r Type B(X 3000 WP)P.	
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at 	am BOP and 12" hole to T.D. w zones. T.D.	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri	nghead spool il GK Strippe ne to 9100' a	with 12" r Type B(X 3000 WP)P.	
 3. Drill 12-1/4 4. Nipple up 10 "E" Double R 5. Drill 7-7/8" 6. DST all pay 7. Run logs at 8. Set 4-1/2" c 	am BOP and 12" 'hole to T.D. w zones. T.D. asing at 9800'	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri	nghead spool il GK Strippe ne to 9100' a	with 12" r Type B(x 3000 wp MP. blids mud	to 9800'.
 3. Drill 12-1/4 4. Nipple up 10 "E" Double R 5. Drill 7-7/8" 6. DST all pay 7. Run logs at 8. Set 4-1/2" c 9. Run temperat 	am BOP and 12" 'hole to T.D. w zones. T.D. asing at 9800' are survey.	- 3000 WP Casi X 3000 WP Hydr nith 4% KCl bri w/450 sx. ceme	nghead spool il GK Strippe ne to 9100' a	with 12" r Type B(x 3000 wp MP. blids mud	to 9800'.
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - 	am BOP and 12" hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up wellr	- 3000 WP Casi X 3000 WP Hydr nith 4% KCl bri w/450 sx. ceme	nghead spool il GK Strippe ne to 9100' a	with 12" r Type B(X 3000 WP DP. Dlids mud	to 9800'.
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - 	am BOP and 12" hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up wellr	- 3000 WP Casi X 3000 WP Hydr nith 4% KCl bri w/450 sx. ceme	nghead spool il GK Strippe ne to 9100' a	with 12" r Type B(X 3000 WP Dids mud APPR FOR 90	COVAL VALID DAYS UNLESS
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w 	am BOP and 12" 'hole to T.D. w zones. T.D. casing at 9800' are survey. nipple-up wellf with packer.	- 3000 WP Casi X 3000 WP Hydr nith 4% KCl bri w/450 sx. ceme	nghead spool il GK Strippe ne to 9100' a	with 12" r Type B(X 3000 WP Dids mud APPR FOR 90	COVAL VALID DAYS UNLESS
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - 	am BOP and 12" 'hole to T.D. w zones. T.D. casing at 9800' are survey. nipple-up wellf with packer.	- 3000 WP Casi X 3000 WP Hydr nith 4% KCl bri w/450 sx. ceme	nghead spool il GK Strippe ne to 9100' a	with 12" r Type B(X 3000 WP Dids mud APPR FOR 90	COVAL VALID DAYS UNLESS
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w 	am BOP and 12" 'hole to T.D. w zones. T.D. casing at 9800' are survey. nipple-up wellf with packer.	- 3000 WP Casi X 3000 WP Hydr nith 4% KCl bri w/450 sx. ceme	nghead spool il GK Strippe ne to 9100' a	with 12" r Type B(X 3000 WP Dids mud APPR FOR 90	COVAL VALID DAYS UNLESS
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate and 	am BOP and 12" 'hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up wellh with packer. ad test.	- 3000 WP Casi X 3000 WP Hydr nith 4% KCl bri w/450 sx. ceme wead and tree.	nghead spool il GK Strippe ne to 9100' a ent.	with 12" r Type BC nd low so	APPR FOR 90 DRILLING EXPIRES	to 9800'. ROVAL VALID DAYS UNLESS G COMMENCED, 2-2-74
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate an 	am BOP and 12" 'hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up well with packer. ad test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY.	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme wead and tree.	nghead spool il GK Strippe ne to 9100' a ent.	with 12" r Type BC nd low so	APPR FOR 90 DRILLING EXPIRES	to 9800'. ROVAL VALID DAYS UNLESS G COMMENCED, 2-2-74
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate an 	am BOP and 12" ' hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up wellt with packer. A test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme wead and tree.	nghead spool il GK Strippe ne to 9100' a ent.	with 12" r Type BC nd low so	APPR FOR 90 DRILLING EXPIRES	to 9800'. ROVAL VALID DAYS UNLESS G COMMENCED, 2-2-74
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate an 	am BOP and 12" ' hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up wellt with packer. A test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme wead and tree.	nghead spool il GK Strippe ne to 9100' a ent.	with 12" r Type BC nd low so	X 3000 WP DP. DIIds mud APPR FOR 90 DRILUNG EXPIRES	to 9800'. OVAL VALID DAYS UNLESS G COMMENCED, -25-74
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate an 	am BOP and 12" ' hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up wellt with packer. A test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme wead and tree.	nghead spool il GK Strippe ne to 9100' a ent.	with 12" r Type BC nd low so	X 3000 WP DP. Dlids mud APPR FOR 90 DRILUNG EXPIRES	to 9800'. ROVAL VALID DAYS UNLESS G COMMENCED, 2-2-74
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate an 	am BOP and 12" hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up well with packer. ad test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme wead and tree.	nghead spool il GK Strippe ne to 9100' a ent.	with 12" r Type BC nd low so	X 3000 WP DP. DIIds mud APPR FOR 90 DRILUNG EXPIRES	to 9800'. OVAL VALID DAYS UNLESS G COMMENCED, -25-74
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate an 	am BOP and 12" hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up well with packer. ad test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme read and tree.	nghead spool il GK Strippe ne to 9100' a ent. OR PLUG BACK, GIVE DA knpwledge and belief.	with 12" r Type BC nd low so	X 3000 WP DP. Dlids mud FOR 90 DRILUNG EXPIRES - PRODUCTIVE ZONG Date Man	to 9800'. OVAL VALID DAYS UNLESS G COMMENCED, -25-74 e AND PROPOSED NEW PR TCh 21, 1974
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate an 	am BOP and 12" hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up well with packer. ad test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme read and tree.	nghead spool il GK Strippe ne to 9100' a ent. OR PLUG BACK, GIVE DA knpwledge and belief.	with 12" r Type BC nd low so	X 3000 WP DP. Dlids mud FOR 90 DRILUNG EXPIRES - PRODUCTIVE ZONG Date Man	to 9800'. OVAL VALID DAYS UNLESS G COMMENCED, -25-74
 Drill 12-1/4 Nipple up 10 "E" Double R Drill 7-7/8" DST all pay Run logs at Set 4-1/2" c Run temperat Set slips - Run tubing w Perforate an 	am BOP and 12" hole to T.D. w zones. T.D. asing at 9800' are survey. nipple-up well with packer. ad test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme wead and tree.	nghead spool il GK Strippe ne to 9100' a ent. OR PLUG BACK, GIVE DA knpwledge and belief.	with 12" r Type BC nd low so	X 3000 WP DP. Dlids mud FOR 90 DRILUNG EXPIRES - PRODUCTIVE ZONG Date Man	to 9800'. OVAL VALID DAYS UNLESS G COMMENCED, -25-74 e AND PROPOSED NEW PR TCh 21, 1974
 3. Drill 12-1/4 4. Nipple up 10 "E" Double R 5. Drill 7-7/8" 6. DST all pay 7. Run logs at 8. Set 4-1/2" c 9. Run temperati 10. Set slips - 11. Run tubing w 12. Perforate and 	am BOP and 12" hole to T.D. w zones. T.D. casing at 9800' cure survey. nipple-up well with packer. ad test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com- ing State Use	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme read and tree.	nghead spool il GK Strippe ne to 9100' a ent. OR PLUG BACK, GIVE DA knpwledge and belief.	TA ON PRESENT	X 3000 WP DP. Dlids mud FOR 90 DRILLING EXPIRES PRODUCTIVE ZONI Date Man	to 9800'. ROVAL VALID DAYS UNLESS G COMMENCED, 2-25-74 e and proposed new pr rch 21, 1974 AR 2 5 1974
 3. Drill 12-1/4 4. Nipple up 10 "E" Double R 5. Drill 7-7/8" 6. DST all pay 7. Run logs at 8. Set 4-1/2" c 9. Run temperation 10. Set slips - 11. Run tubing with the set of the set of	am BOP and 12" hole to T.D. w zones. T.D. casing at 9800' cure survey. nipple-up well with packer. ad test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com- ing State Use	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme bead and tree.	nghead spool il GK Strippe ne to 9100' a ent. or PLUG BACK, GIVE DA knpwledge and belief. Agent	TA ON PRESENT	X 3000 WP DP. Dlids mud FOR 90 DRILLING EXPIRES PRODUCTIVE ZONG Date Date DATE DATE	to 9800'. ROVAL VALID DAYS UNLESS G COMMENCED, 25-74 e and proposed new pr cch 21, 1974 R 2 5 1974 .C.C. in sufficien
 3. Drill 12-1/4 4. Nipple up 10 "E" Double R 5. Drill 7-7/8" 6. DST all pay 7. Run logs at 8. Set 4-1/2" c 9. Run temperation 10. Set slips - 11. Run tubing with the second second	am BOP and 12" hole to T.D. w zones. T.D. casing at 9800' cure survey. nipple-up well with packer. ad test. ROPOSED PROGRAM: IF TER PROGRAM, IF ANY. ion above is true and com- ing State Use	- 3000 WP Casi X 3000 WP Hydr rith 4% KCl bri w/450 sx. ceme pead and tree.	nghead spool il GK Strippe ne to 9100' a ent. OR PLUG BACK, GIVE DA knpwledge and belief.	TA ON PRESENT	X 3000 WP DIICLS MUCH FOR 90 DRILLING EXPIRES PRODUCTIVE ZONG DATE MA DATE MA DATE MA	to 9800'. ROVAL VALID DAYS UNLESS G COMMENCED, 2-25-74 e and proposed new pr rch 21, 1974 AR 2 5 1974