

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1124.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Gulf Oil Corporation

3. ADDRESS OF OPERATOR
P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
2310' FSL & 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3440' GL

RECEIVED BY
FEB 12 1986
OCCB
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL NO.
0554950A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Jones Federal (NCT-A)

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Cemetery Grayburg

11. SEC. T. R. M. OR R.L. AND SURVEY OR AREA
Sec 14-T20S-R25E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

POH with production equipment. Set CIBP at 1000', cap with 35' cement. Set CIBP at 700', test 500#. Circulate hole with abandonment mud. Spot 40' cement on CIBP. Pumped 10 sack surface plug. Set dry hole marker. Clean and clear location. P&A 10-20-82.

RECEIVED

NOV 17 1982

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

Post ID-2
2-11-83
P&A

18. I hereby certify that the foregoing is true and correct

SIGNED RL Pike TITLE Area Engineer DATE 11-12-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 2-7-86

CONDITIONS OF APPROVAL, IF ANY: