

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	/
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION
RECEIVED

APR 29 1982

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK AN EXISTING RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5. State Oil & Gas Lease No.
2. Name of Operator Mewborne Oil Company /		7. Unit Agreement Name
3. Address of Operator P. O. Box 7698 Tyler, Texas 75701		8. Farm or Lease Name Foster
4. Location of Well UNIT LETTER <u>J</u> <u>2130</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>20S</u> RANGE <u>24 E</u> N.M.P.M.		9. Well No. 1
15. Elevation (Show whether DF, RT, GR, etc.) 3730 GR		10. Field and Pool, or Wildcat Foster Ranch - Morrow
12. County Eddy		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. 4-16-82 Set C.I.B.P. 8800
2. 4-17-82 25 sack plug at 8,800' to cap C.I.B.P.
3. Mixed mud and circulated casing.
4. 4-20-82 35 sack plug at 5,520'. 50 in and 50 out of sub.
5. 4-20-82 Tagged top of plug at 5374'
6. 4-21-82 35 sack plug at 4841'.
7. 4-21-82 35 sack plug at 3696'.
8. 4-21-82 35 sack plug at 2004'.
9. 4-21-82 35 sack at 1295'. 50' below 8 5/8 shoe. Tagged plug at 1,110'.
10. 4-22-82 35 sack at 370'.
11. Cut off well head and place a 10 sack surface plug and dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dulra Heard TITLE Production Clerk DATE 4-26-82

APPROVED BY T. R. E. Thompson TITLE OIL AND GAS INSPECTOR DATE JUN 18 1982

CONDITIONS OF APPROVAL, IF ANY: