
Submit 3 Copies to Appropriate District Office

State of New Mexico . Energy, Minerals and Natural Resources Department



DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

[]			
	5.	In	

3	U·	-0	1;) – 2	3930)	
	_						

WELL API NO.

DISTRICT II	Santa Fe, New Mexico	87504F3008FEU		
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of	STATE Y FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		NOV 1 8 1991	6. State Oil & Ga	
		0.6.0	в-8096	
	S AND REPORTS ON WEL			
(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN R. USE "APPLICATION FOR PEI	OR PLUG BACK TO A	7. Lease Name or	Unit Agreement Name
	FOR SUCH PROPOSALS.)	LAN I	Ì	
1. Type of Well:			1	
OFF X MET CONT.	OTHER		Conoco "7"	'State
2. Name of Operator		1	8. Well No.	
Mitchell Energy Corporati	on		7	
3. Address of Operator	1- my 77307	•	9. Pool name or V	
P. O. Box 4000, The Wood!	ands, IX //36/		E. MIIIma	n (Queen-Greyburg)
Unit Letter G 1980	For From The North	Line and 1980	Feet From	The East Line
	1001100			
Section 7	Township 19S Ra	nge 29E	NMPM	Eddy County
	10. Elevation (Show whether			<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
	3379.			<i>XIIIIIIIIIII</i>
• •	ropriate Box to Indicate I		•	
NOTICE OF INTEN	ITION TO:	SUB	SEQUENT F	REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	cons	PLUG AND ABANDONMENT
- CARCHARILY ABARDON	Charlos			PLUG KNU KOKNOCHMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB	
OTHER:		OTHER:		
12. Describe Proposed or Completed Operations	(Clearly state all pertinent details, an	d give pertinent dates, inclu	dine estimated date o	f starting any proposed
work) SEE RULE 1103.	(• • • • • • • • • • • • • • • • • • •		•	,
Plug and Abandon as per the	e following procedur	:e:		
1	-	<i>a5</i>	5X9,	
POOH w/rods, pump, ar	nd 2 3/8" tbg. RIH w	/tbg and set 35	cmt plug	in 4 1/2" csg above
top perf (2069'). Tag plu	g. Spot 25 sx plug	@ top of Queen	(1753').	Spot 25 sx plug at
base of salt (650'). Spot	25 sx plug @ 8 5/8"	'shoe (399') ar	nd tag. Spo	ot 10 sx cmt plug @
surface. Weld on cap and	erect permanent abar	idonment marker.	. Load hole	e with gelied brine
between all plugs.				
•				
I hereby certify that the information above is true and o	remolete to the heat of my knowledge and	belief.		
()) 3/				11/10/01
SIGNATURE ame Corno		<u>Engineer</u>		DATE
James Blount TYPEOR PRINT NAME				TELEPHONE NO.
+ As noted a	thous			
(This space for State Use)				
		etak talen 14. jan 11. ilian	LASPECTOD	11 01-91

Plugging

CONDITIONS OF APPROVAL, IF ANY: