

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other Instructions on reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NUMBER
NM-2538

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Prickly Pear Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

No. Shugart Y-SR-Q-G

11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA

Sec. 12 T18S R31E

12. COUNTY OR PARISH 13. STATE

Eddy

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

FEB 13 1992

O. C. D.
ARTESIA OFFICE

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Yates Energy Corporation

3. ADDRESS OF OPERATOR

P. O. Box 2323 Roswell, New Mexico 88202-2323

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

400' FNL & 2310' FWL

14. PERMIT NO.

30-015-26445

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3778.2 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set a CIBP @ 3450' and dumped 35' cement on plug.
2. Hole was circulated w/55 bbls 9.0# gal mud.
3. Spotted a 100' plug (7 sxs. cement) from 407' to 307'
4. Spotted a 50' plug (5 sxs. cement) from 50' to surface.
5. Cut csg 36" below ground level, welded a steel plate and dry hole marker on stub.
6. Cleaned location and cut off rig anchors.
7. Weld on plate and dry hole marker, rig down pulling unit, cut off all guy line anchors, clean location.

Well Plugged and Abandoned 01/22/92.

Applicant is responsible for well bore,
Liability under this is retained until
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sharon B. Hamel

TITLE

Landman

DATE

01/31/92

(This space for Federal or State office use)

APPROVED BY

Sharon B. Hamel

TITLE

DATE

2/11/92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side