

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL  
(Other Instructions  
reverse side)

RECEIVED

E\*  
F\*

Form approved  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.  
91-016916

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Saladar Unit

8. FARM OR LEASE NAME

9. WELL NO.

9

10. FIELD AND POOL, OR WILDCAT

Saladar - Yates

11. SEC., T., R., M., OR BLM. AND  
SURVEY OR AREA

Sec. 33, T20S, R28E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

NOV 20 '89

1. TYPE OF WELL ☐ OIL WELL ☐ GAS WELL ☒ OTHER Injection Well

2. NAME OF OPERATOR

Barber Oil, Inc.

3. ADDRESS OF OPERATOR

P.O. Box 1658 Carlsbad, NM 88221-1658

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface

Unit Letter (O)

660' FSL and 2310' FEL

15. ELEVATIONS (Show whether DP, ST, GR, etc.)

3205 GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

WATER SHUT-OFF

PULL OR ALTER CASING

FRAC TREAT

MULTIPLE COMPLETE

SHOOTING OR ACIDIZE

ABANDON\*

CHANGE PLANT

CHANGE PLANT

WATER SHUT-OFF

FRAC TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form)

16. FULLY PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)

PLUG AND ABANDON - Propose to pull tubing and packer. Go back in hole with tubing  
to one foot off bottom of T.D. (Approx. 674'). Circulate hole full of cement. Pull  
tubing out of hole and fill void left by tubing with cement. Cut casing off below  
plow depth, cap well and set marker. Clean location.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE President

DATE 11/15/89

(Leave space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side