

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

215F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT..." for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		2. NAME OF OPERATOR Strata Production Company		3. ADDRESS OF OPERATOR 700 Petroleum Bldg. Roswell, New Mexico 88210		4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 990' FNL & 2080' FWL 2030/S 860/W		5. LEASE DESIGNATION AND SERIAL NO NM-83580		6. IF INDIAN, ALLOTTEE OR TRIBE NAME		7. UNIT AGREEMENT NAME		8. FARM OR LEASE NAME Aguila Federal		9. WELL NO. #1		10. FIELD AND POOL OR WIERCAT Woodcat 135 Winchester Delaware		11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA Sec. 4. T20S R28E		12. COUNTY OR PARISH Eddy		13. STATE NM	
14. PERMIT NO. API-30-015-26430		15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3298'		16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)																			

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON*
CHANGE PLANE

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) Temporary Abandoned T/A

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

- 1) Move in service rig. Hughs Services on location. Circ. with Pkr. Fluid at 6190'. Lay down tubing. Rig-up HLS and TIH with 5 1/2" CIBP. Set at 6100'. TOH. TIH with bailors and dump 35' cement on top. TOH. Disp. hole and test to 700# for 15 min. OK. Rel. pressure and nipple up well head. Release rig.
Attached copy of pressure chart.

Approval of Temporary
Abandonment Expires

3/23/96

NMOCD

APPROVED FOR 12 MONTH PERIOD

ENDING 3/23/93

18. I hereby certify that the foregoing is true and correct

SIGNED Frank A. Morgan

TITLE Vice-President Field Ops.

DATE 3/25/92

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE 4/1/92

*See Instructions on Reverse Side

