

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

C/SF
JP

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-22474
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Big Chief Com.
8. Well No. 1
9. Pool name or Wildcat Dublin Ranch Morrow
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,095' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator DINERO OPERATING COMPANY
3. Address of Operator P.O. BOX 10505 MIDLAND, TEXAS 79702
4. Well Location Unit Letter F : 1980' Feet From The North Line and 1980' Feet From The West Line Section 22 Township 22 Range 28 NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,095' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Circulated hole with Salt Gel mud. Set 60 ft. plug across Perf. 9596'-9618'. Set 120 ft. plug across perf. at 9520'-9523'. tagged. Set 110 ft. plug at 8000 ft. Set 115 ft. plug at 7000 ft. and 120 ft. plug at 6000 ft. Set 105 ft. plug at 5000 ft and 220 ft. plug across DV Tool at 3800'-4000' and tagged. Set 100 ft. plug at 3000 ft. Set 120 ft. plug at 2510'-2610' and tagged. Set 1050 ft. plug at surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlie Williams by JB TITLE Production Superintendent DATE 10/15/01
TYPE OR PRINT NAME Charlie Williams TELEPHONE NO. 915-684-5544

(This space for State Use)

APPROVED BY Benny Bump TITLE Compliance Officer DATE 11-20-01
CONDITIONS OF APPROVAL, IF ANY: