## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form	C	-10	3
Revis	ed	1-1	-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WE	ELL API NO.	
	30-015-26583	
5.	Indicate Type of Lease STATE	FEE XX
	SIAIE	ا يمييون منده

Santa Fe, New Mexico CS 504 2088 5. Indicate Type of Lase STATE   FEE WY  NO. Devemon DD. Assessia, NM 87210  DISTRICTING  SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMAT" (FORM—Crof) FOR SUCH PROPOSALS.)  1. Type of Well:  See:	DICTRICT II		Come Es New Maries	97504 2000	30-015-26583
SUNDRY NOTICES AND REPORTS ON WELLS   COMMENCE THIS FORM FOR PROPOSALS TO PRILL OR TO SEEREN OR PLUG BACK TO A DEFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.    Type of Well:	DISTRICT II P.O. Drawer DD, A	rtesia, NM 88210	Santa Fe, New Mexico	FEB 25°1991	5. Indicate Type of Lease STATE FEE XX
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERIOR RESERVOR, USE 'APPLICATION FOR FERMIT' (FORM C-101) FOR SUCH PROPOSALS)  1. Type of Well:  WILL		L, Aziec, NM 87410			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERIOR RESERVOR, USE 'APPLICATION FOR FERMIT' (FORM C-101) FOR SUCH PROPOSALS)  1. Type of Well:  WILL		SUNDRY NOTICES	S AND REPORTS ON WE	LLS	
ORL WELL OTHER Pardue -C-, 8808 JV-P  2. Name of Operator BTA Oil Producers  3. Address of Operator 104 S. Pecos, Midland, TX 79701  4. Well Location Unit Letter N: 611 Feet From The South Line and 1504 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  2977' GR 2988' RKB  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB X  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name		
BTA 011 Producers  3. Address of Operator 104 S. Pecos, Midland, TX 79701  4. Well Location Unit Letter N: 611 Feet From The South Line and 1504 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County    10. Elevation (Show whether DF, RKE, RT, GR, etc.)   2977' GR 2988' RKB   11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB   OTHER:    12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.		GAS WELL	OTHER		Pardue -C-, 8808 JV-P
3. Address of Operator 104 S. Pecos, Midland, TX 79701  4. Well Location Unit Letter N: 611 Feet From The South Line and 1504 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2977' GR 2988' RKB  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB X  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Dr1g 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then dr1d shoe, Dr1g 7-7/8" hole.	2. Name of Operat	lor /			1
4. Well Location Unit Letter N: 611 Feet From The South Line and 1504 Feet From The West Line Section 11 Township 23S Range 28E NMPM Eddy County  10. Elevation (Show whether DF, RKE, RT, GR, etc.)  2977' GR 2988' RKB  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB X  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Dr1g 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then dr1d shoe, Dr1g 7-7/8" hole.					
Well Location   Unit Letter N : 611   Feet From The South   Line and 1504   Feet From The West   Line	1		70701		
Unit Letter N : 611 Feet From The South Line and 1504 Feet From The West Line  Section 11 Township 23S Range 28E NMPM Eddy County  10. Elevation (Show whether DF, RRB, RT, GR, etc.)  2977' GR 2988' RKB  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON GRANDED CHANGE PLANS COMMENCE DRILLING OPNS. X PLUG AND ABANDON GRANDED CHANGE PLANS GRANDED CHANGE DRILLING OPNS. X PLUG AND ABANDONMENT GRANDED CHANGE PLANS GRANDED CHANGE DRILLING OPNS. X PLUG AND ABANDONMENT GRANDED CHANGE Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Dr1g 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then dr1d shoe, Dr1g 7-7/8" hole.		ecos, Midland, T	X /9/01		Loving, East (Delaware)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)  2977' GR 2988' RKB  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON GREMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT GRANILY ABANDON GRANILY ABA		er <u>N</u> : <u>611</u>	Feet From The South	Line and150	4 Feet From The West Line
2977' GR 2988' RKB  11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB TOTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	Section	11	Township 23S p	ange 28E	NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  OTHER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	<i>\\\\\\\\</i>		7//X	•	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB X  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Dr1g 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then dr1d shoe, Dr1g 7-7/8" hole.					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB X  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.			•		•
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. X PLUG AND ABANDONMENT  PULL OR ALTER CASING  CASING TEST AND CEMENT JOB X  OTHER:  DIFFERMAN OF Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	N	IOTICE OF INTEN	NTION TO:	SUB	SEQUENT REPORT OF:
CASING TEST AND CEMENT JOB X  OTHER:  OTHER:  OTHER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
OTHER:  12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	PERFORM REME	DIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  2-20-91 Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.					
Spudded 9:00 a.m., Drlg 12-1/4" hole, Cmtd 12 jts 8-5/8" 24# J-55 STC csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's. Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	TEMPORARILY AS	BANDON		COMMENCE DRILLING	G OPNS. X PLUG AND ABANDONMENT
csg @ 526' w/400 sx, PD @ 10:15 p.m., Circ cmt, WOC 6 hrs, Installed csghd & BOP's.  2-21-91 Cleaned out to shoe, Tstd BOP's & csg to 1000 psi for 30 mins on fresh wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	TEMPORARILY AS	BANDON		COMMENCE DRILLING	G OPNS. X PLUG AND ABANDONMENT
wtr, WOC 12 hrs total, then drld shoe, Drlg 7-7/8" hole.	PULL OR ALTER ( OTHER:  12. Describe Propo	CASING   sed or Completed Operations	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE	S OPNS. X PLUG AND ABANDONMENT E
2-22-91 Depth 1413', Drlg 7-7/8" hole.	PULL OR ALTER ( OTHER:  12. Describe Propo work) SEE RU	SANDON CASING CASING Completed Operations TLE 1103.  Spudded 9:00 a csg @ 526' w/40	(Clearly state all pertinent details, a.m., Drlg 12-1/4" h	COMMENCE DRILLING CASING TEST AND CE OTHER:  and give pertinent dates, inclusione, Cmtd 12 jts	EMENT JOB X  EMENT JOB X  Adding estimated date of starting any proposed  S 8-5/8" 24# J-55 STC
	PULL OR ALTER OF THE PROPERTY	CASING  CASING  Seed or Completed Operations TLE 1103.  Spudded 9:00 a csg @ 526' w/40 csghd & BOP's.  Cleaned out to	CHANGE PLANS  (Clearly state all pertinent details, a.m., Drlg 12-1/4" h 00 sx, PD @ 10:15 p	COMMENCE DRILLING CASING TEST AND CE OTHER:  and give pertinent dates, inclusione, Cmtd 12 jts .m., Circ cmt, V	EMENT JOB X  PLUG AND ABANDONMENT  Ading estimated date of starting any proposed  8 8-5/8" 24# J-55 STC  NOC 6 hrs, Installed  if for 30 mins on fresh
	PULL OR ALTER O OTHER:  12. Describe Proportion SEE RU 2-20-91  2-21-91	SANDON  CASING  Seed or Completed Operations TE 1103.  Spudded 9:00 a csg @ 526' w/40 csghd & BOP's.  Cleaned out to wtr, WOC 12 hrs	CHANGE PLANS  (Clearly state all pertinent details, on., Drlg 12-1/4" had not say that the state of the state	COMMENCE DRILLING CASING TEST AND CE OTHER:  and give pertinent dates, inclusione, Cmtd 12 jts .m., Circ cmt, V	EMENT JOB X  PLUG AND ABANDONMENT  ding estimated date of starting any proposed  8 8-5/8" 24# J-55 STC  NOC 6 hrs, Installed  i for 30 mins on fresh
	PULL OR ALTER O OTHER:  12. Describe Proportion SEE RU 2-20-91  2-21-91	SANDON  CASING  Seed or Completed Operations TE 1103.  Spudded 9:00 a csg @ 526' w/40 csghd & BOP's.  Cleaned out to wtr, WOC 12 hrs	CHANGE PLANS  (Clearly state all pertinent details, on., Drlg 12-1/4" had not say that the state of the state	COMMENCE DRILLING CASING TEST AND CE OTHER:  and give pertinent dates, inclusione, Cmtd 12 jts .m., Circ cmt, V	EMENT JOB X  PLUG AND ABANDONMENT  ding estimated date of starting any proposed  8 8-5/8" 24# J-55 STC  NOC 6 hrs, Installed  i for 30 mins on fresh
$\mathcal{A}$	PULL OR ALTER O OTHER:  12. Describe Proportion SEE RU 2-20-91  2-21-91	SANDON  CASING  Seed or Completed Operations TE 1103.  Spudded 9:00 a csg @ 526' w/40 csghd & BOP's.  Cleaned out to wtr, WOC 12 hrs	CHANGE PLANS  (Clearly state all pertinent details, on., Drlg 12-1/4" h 00 sx, PD @ 10:15 p  shoe, Tstd BOP's & stotal, then drld	COMMENCE DRILLING CASING TEST AND CE OTHER:  and give pertinent dates, inclusione, Cmtd 12 jts .m., Circ cmt, V	EMENT JOB X  PLUG AND ABANDONMENT  ding estimated date of starting any proposed  8 8-5/8" 24# J-55 STC  NOC 6 hrs, Installed  if for 30 mins on fresh
	PULL OR ALTER O OTHER:  12. Describe Proportion SEE RU 2-20-91  2-21-91	SANDON  CASING  Seed or Completed Operations TE 1103.  Spudded 9:00 a csg @ 526' w/40 csghd & BOP's.  Cleaned out to wtr, WOC 12 hrs	CHANGE PLANS  (Clearly state all pertinent details, on., Drlg 12-1/4" h 00 sx, PD @ 10:15 p  shoe, Tstd BOP's & stotal, then drld	COMMENCE DRILLING CASING TEST AND CE OTHER:  and give pertinent dates, inclusione, Cmtd 12 jts .m., Circ cmt, V	EMENT JOB X  PLUG AND ABANDONMENT  ding estimated date of starting any proposed  8 8-5/8" 24# J-55 STC  NOC 6 hrs, Installed  if for 30 mins on fresh

I hereby certify that the infe	mustion above is the and springless to the best of my troppledge and belief.  **Regulatory Administrator**	DATE2-22-91
TYPE OR FRINT NAME	Dorothy Houghton	TELEPHONE NO. 915-682-375
(This space for State Use)	ORIGINAL SIGNED BY MIKE WILLIAMS	FEB 2 5 1991
	OLOGONICON DISTRICT III	DATE 1301