
Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department



DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION P.O. Box 2088 RECEIVED

Santa Fe, New Mexico 87504-2088

30-015-27100

5. Indicate Type of Lease

MAY 23.'94

STATE FEE 6. State Oil & Gas Lease No.

1000 NO Distos Nai, Maso, Pair Brito	V-3772					
SUNDRY NOTICES AND REPORTS ON WELLS  ARTESIA OFFICE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name  BR 15 State					
1. Type of Well: OIL OAS WELL X WELL OTHER						
2. Name of Operator	8. Well No.					
Pogo Producing Company	<u> </u>					
3. Address of Operator P.O. Box 10340, Midland, Texas 79702-7340 915-682-682	9. Pool name or Wildcat Wildcat Delaware					
4. Well Location Unit Letter L: 1650 Feet From The South Line and 66						
Section 15 Township 24 South Range 27 East						
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3197.0 GR						
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT					
PULL OR ALTER CASING CASING TEST AND C	T-					
OTHER: TD &	Production Casing X					

LEWLOHAHILT ARANDO	,14 []	CHANGE I EARS	الاا	COMMENSE Brille St. 1151	
PULL OR ALTER CASING	3 🗌			CASING TEST AND CEMENT JOB	
OTHER:				OTHER: TD & Production Casing	X
12. Describe Proposed or ( work) SEE RULE 110	Completed Operation 3.	ns (Clearly state all pertiner	nt details, and	l d give pertinent dates, including estimated date of starting any propose	d
Atlas. Ran 5 5,930'. Stag 13.6 PPG.Drop	" hole to 5 -1/2", 15.5 e Tool @ 3, olug. Ope s. Cement .6 PPG. Pl	,975'. TD reach #, K-55, LT&C co 216'. Howco ce n DV tool with	asing. mented 1050 PS	5 hours CST 10/3/92. Logged with Wester Guide Shoe @ 5,975'. Float Collar @ 1st stage with 540 sx Halliburton Lite GI. Circulate 100 sx excess cement. Conversion Cement @ 12.6 PPG, followed by ed @ 0200 hours CST 10/5/92. Circulate	0 ir- 210
I hereby certify that the info SIGNATURE TYPE OR FRINT NAME	and XL	and complete to the best of my	knowledge and	me Division Operations Manager DATE Jan.	15, 199; 915-682-
(This space for State Use)	SUPERVISO	R. DISTRICT IL	Т	JUN	1 5 1994
CONDITIONS OF AFTROVAL	., IF ANY:				