

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JAN 9 1974

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 14-08-001-303
7. Unit Agreement Name Poker Lake
8. Farm or Lease Name Poker Lake Unit
9. Well No. 37
10. Field and Pool, or Wildcat Corral Canyon
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS, OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator Fred Pool Drilling Company ✓
3. Address of Operator P. O. Box 5321, Midland, Texas 79701
4. Location of Well UNIT LETTER J 1980 FEET FROM THE East LINE AND 1980 FEET FROM THE S LINE, SECTION 8 TOWNSHIP 25S RANGE 30E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3241 G.L.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well not productive of oil or gas
8 5/8" casing at 663' - cement circ.
5 1/2" casing at 3719' - 50 sx cement
3 1/2" liner - 3684' - 3748'
TD - 3756'

Spot 25 sx cement at 3650' - fill hole 10# brine w/ 25 sx salt gel - 100 bbls. - pull approx 3000' - 5 1/2" casing - spot 35 sx plug at 750' - base of salt, spot 35 sx plug at 663' - put 10 sx at surface and marker.

* 35 sx plug at stat 7 5/2" casing

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Frank Shambarger</u>	TITLE <u>Agent</u>	DATE <u>1-7-74</u>
APPROVED BY <u>W. A. Gussert</u>	TITLE <u>Oil and Gas Inspector</u>	DATE <u>JAN 9 1974</u>
CONDITIONS OF APPROVAL, IF ANY: * As noted above		