## U TED STATES SUBMIT IN TRI JATE\* (Other instructions on re-

		Form a	pprove	ed.		
		Budget	Bures	u No	. 42-R	142
j.	LEASE	DESIGN	ATION	AND	PRIAT	NO.

שברו	5. LEASE DESIGNATION AND SERIAL NO.			
SUNDRY	GEOLOGICAL SURV		LC-061716 6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
(Do not use this form for Use "A	proposals to drill or to deepen of PPLICATION FOR PERMIT—" for	r plug back to a different reservoir.		
1. GAS ST	HER	YED I I IJ/	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR		a. c. c.	8. FARM OR LEASE NAME	
J.M. Huber Corp	oration	ATTICITY OFFICE		
3. ADDIESS OF OPERATOR			Superior - USA	
1900 Wilco Build	ding, Midland, Te	exas 79701	1	
4. LOCATION OF WELL (Report loc See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT			
			Washington Ranch Morro	
1900 FMT & 2020	J' FEL, Section 1	11, T-26-S, R-24-E	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA	
· · · ·		RECEIVE	11-26S-24E	
14. PERMIT NO.	15. ELEVATIONS (Show whe	ether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE	
Blanket	3752'	GR FEB 1 1 1977	Eddy N.M.	
16. Chec	k Appropriate Box To India	cate Nature of Notice, Report, or		
	INTENTION TO:	O. C. C <sub>subse</sub>	EQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON* X	SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL	CHANGE PLANS	(Other)		
(Other)	(Note: Report results			
17. DESCHIE PROPOSED OR COMPLET proposed work. If well is nent to this work.) *	ED OPERATIONS (Clearly state all pedirectionally drilled, give subsurfac	ertinent details, and give pertinent date be locations and measured and true verti	pletion Report and Log form.) s, including estimated date of starting any ical depths for all markers and zones perti-	
l. M.I.R.U. Lil	llard Casing Pull	ers.		
2. POH $w/2-7/8$ '	' tubing, Guibers	on Unipackers Vann	Oil Tool 3-1/9"	
berroracting	quis and Ilring	head.		
3. Rig up McCul	llough Tool. Run	and set CIBP @ 7 00	0+ above Morrow	
Perra @ /, IZ	o Dumb 35' sx	cement on top of al	1100	
4. Cut 4½" casi	.ng, 10.5#, K-55 @	@ 6,000' <u>+</u> . Pump 150	(25  sy) 75!  in	
75' out a cu	it Off point	<u>-</u>	(42 PV) 13 TII -	

75' out @ cut off point,
POH w/4½" casing, pump 100' (20 sx) cement plug @ 5,000-5,100',
POH w/4½" casing, pump 100' (20 sx) cement plug @ 3,400-3,500',
POH w/4½" casing, pump 100' (20 sx) cement plug @ 1,900-2,000',
POH w/4½" casing, pump 100' (20 sx) cement plug @ 750- 850', 5. POH w/42" casing, place 20 sx cement @ top surface, 6. Release rig,

7. Clean up location, place well marker.

S	IGNED RODERT D. Harrey, Jr., This space for Federal or State office use)	TITLE Acting Dist. Prod. Mgr.	DATE 1/31/77
	PPROVED BY	TITLE	DATE