

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: Enterprise Field Services, LLC	OGRID: 151618
Contact Name: Thomas Long	Contact Telephone: 505-599-2286
Contact email: tjlong@eprod.com	Incident # (assigned by OCD): NCS1921029796
Contact mailing address: 614 Reilly Ave, Farmington, NM 87401	

Location of Release Source

Latitude **36.81790** Longitude **-107.72946** (NAD 83 in decimal degrees to 5 decimal places)

Site Name Buena Vista Compressor Station	Site Type Natural Gas Compressor Station
Date Release Discovered: 7/25/2019	Serial Number (if applicable): NM 093684

Unit Letter	Section	Township	Range	County
A	13	30N	9W	San Juan

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: BLM)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls):	Volume Recovered (bbls):
<input type="checkbox"/> Natural Gas	Volume Released (Mcf):	Volume Recovered (Mcf):
<input checked="" type="checkbox"/> Other (describe) Fire	Volume/Weight Released (provide units): N/A	Volume/Weight Recovered (provide units) N/A

Cause of Release: On July 25, 2019, lightning struck the emergency shut down vent causing the vent to catch fire at Buena Vista Compressor Station. The fire was extinguished by facility personnel. No injuries, nor equipment damage occurred. No emergency services responded to the incident. No environmental impacts occurred, no remediation was performed and no soil samples were collected. A summary of events, photographs and a map are included with this "Final." C-141.

State of New Mexico
Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	


Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- ☒ A scaled site and sampling diagram as described in 19.15.29.11 NMAC
- ☒ Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- ☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- ☒ Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Jon E. FieldsTitle: Director, EnvironmentalSignature: Date: 8/6/19email: jefields@eprod.comTelephone: (713) 381-6684**OCD Only**Received by: OCDDate: 8/7/19

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by: Date: 8/12/19Printed Name: CoryTitle: Environmental Specialist

Summary of Events
Buena Vista Compressor Station - Emergency Shutdown Vent
UL A Section 13 T30N R9W; 36.81790, -107.72946

On July 25, 2019, lightning struck the emergency shut down vent causing the vent to catch fire at Buena Vista Compressor Station. The fire was extinguished by facility personnel. No injuries, nor equipment damage occurred. No emergency services responded to the incident. No environmental impacts occurred, no remediation was performed and no soil samples were collected.

Enterprise Field Services, LLC
Buena Vista Compressor Station
UL A Section 13 T30N R9W; 36.81790, -107.72946
Emergency Shut Down Vent

7/25/2019



Photo 1: View of the ESD Vent.



Photo 2: View of the ESD Vent.

1-30-2019, R-11-20, 11:00 A.M.
BASIS OF DRAWING: GPS OBSERVATIONS

ESD VENT

LEGEND:




FIGURE 1: SITE MAP

ENTERPRISE FIELD SERVICES, LLC
BUENA VISTA COMPRESSOR STATION
UL A SEC. 13 T30N R9W; 36.81790, -107.72946



DRAWN BY: TJLONG	DATE: 7-30-2019
CHECKED BY: BSTONE	DATE: 7-30-2019
APPROVED BY: BSTONE	DATE: 7-30-2019
PROJ. ID: BUENAVISTACS	SCALE: 1"=80'
DRAWING NUMBER: 1	