Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Departmen

Form C-103 Revised 1-1-89

DISTRICT I.  P.O. Box 1980, Hobbs, NM 88240  OIL CONSERVATION DIVISION  2040 Pacheco St.  DISTRICT II			WELL API NO.				
			30-045-24861				
P.O. Drawer DD, Artesia, NM 88210 Santa Fe, NM 87505			5. Indicate Type	5. Indicate Type of Lease  STATE X FEE			
DISTRICT III				6. State Oil & C			
1000 Rio Brazos Rd., Aztec, NM 87410				LG-3926		i	
SUNDRY NOTICES AND REPORTS ON WELLS							
(DO NOT USE THIS FORM FOR PORPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name	7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS)							
1. Type of Well:	JI) FOR SUCH PROPOSAL	-5)		State of NM 16			
- CAG -				Built of 14141 10			
WELL WELL OTHER				0 777 11 27			
2. Name of Operator				8. Well No.			
Elm Ridge Resources, Inc.  3. Address of Operator				9. Pool name or Wildcat			
PO Box 156 Bloomfield, NM 87413				Nageezi-Gallup			
4. Well Location				: Nageozi - Canup			
Unit Letter C : 890	Feet From The	North	Line and	1920	Feet From The	West Line	
Section 16 Tov		ange 8W		NMPM		San Juan County	
	10. Elevation (			T, GR, etc.)			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO							
notice of in i	ENTION TO:			SUBSEQUEN	II KEPOKI O	/F:	
PERFORM REMEDIAL WORK PLUG AND ABANDON		X	REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT				
PULL OR ALTER CASING			CASING TEST AND CEMENT JOB				
OTHER:			OTHER:			🗆	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed work) SEE RULE 1103.							
Elm Ridge Resources, Inc. plans to Plug and Abandon the above referenced well as follows:							
(Please see attached for procedures)							
(1 loads set distance for procedures)							
				م من المنظمة	1 10 1		
				186	3 10 11 72 73		
				K56789	0 10 11 20		
				E 0.0	\$ 10 11 P		
•					101172 A		
Λ	/			12.75 S	\$10.11 P. 12		
				15. 3. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5. 5.	10 11 72 70 g		
					5 10 11 75 75 75 75 75 75 75 75 75 75 75 75 75		
				15 15 15 15 15 15 15 15 15 15 15 15 15 1	\$10.1175 St. 300		
SIGNATURE My M	alles		TITLE ]	Production Assistant	Sto To Date	09/10/04	
<del></del>	ackey 1		TITLE]	Production Assistant		09/10/04 -632-3476 ext. 201	
TYPE OR PRINT NAME Amy M	Mackey				TELEPHONE NO. 505	·····	
TYPE OR PRINT NAME Amy M  (This space for State Use)	Mackey		977UT 01	Production Assistant  a GAS INSPECTOR	TELEPHONE NO. 505	-632-3476 ext. 201	
TYPE OR PRINT NAME Amy M	lully Mackey				TELEPHONE NO. 505	·····	

## Plugging procedures for the State of New Mexico 16-21.

Surface casing:

8 5/8" 23# @ 259'. Cement to surface

**Production casing:** 5 ½", 14# @ 5508'. Cement to surface.

**Existing plugs:** CIBP @ 5011' w/ cement, 4976' to 5011' CIBP @ 1730'

Perforations: {1589'-1592'} {1595'-1599'} {1607'-1614'}
MV Plug, 2460'-2350' Chacraflug 2055-1965'

Plug 1) PC. Set cement retainer @ 1480'. Pump 75 sks of cement. Leave 2 sks on top.

KirHaul and 1170'-970' Plug 2) Ojo Alamo. Set a balanced plug from 840' to 940' (15 sks).

Plug 3) Surface shoe. Place a balanced plug from 209' – 309'. (15 sks)

**Plug 4)** 50' to surface. (8 sks.)

Cut off wellhead, place marker, and reclaim location.

(Attachment 1)