submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells		
	5.	Lease Number NMSF-03491
1. Type of Well GAS	6.	If Indian, All. or Tribe Name
2. Name of Operator BURLINGTON	7.	Unit Agreement Name
RESOURCES OIL & GAS COMPANY LPO70 FARMINGTON HM	8.	
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	Huerfanito Unit #22R API Well No. 30-045-30793
4. Location of Well, Footage, Sec., T, R, M 1620'FNL, 1010'FEL, Sec.4, T-26-N, R-9-W, NMPM		Field and Pool Ballard Pictured Cliff County and State San Juan Co, NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	OTHER	Пата
Casing Repair Water	utine 1 Shut o	Fracturing
3. Describe Proposed or Completed Operations It is intended to plug and abandon the subject well accord	ding to	the attached
procedure and wellbore diagram.		one accaonca
		o ene accaenca
	1004 Say.	
procedure and wellbore diagram.	Dog Silving	
procedure and wellbore diagram.	1004 1004	
Procedure and wellbore diagram. Nov 20 Nov 2	Po4	
procedure and wellbore diagram.	1004 2014 t	Date 10/18/04

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Huerfanito Unit #22R – Pictured Cliffs PLUG AND ABANDONMENT PROCEDURE

1620' FNL & 1010' FEL NE, Section 4, T026N, R009W Latitude: N36°31.338, Longitude: W107° 47.298 AIN83494001 10/14/04

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

All cement is ASTM Type III, mixed at 14.8 ppg with a 1.32 cf/sx yield.

- Set steel waste fluid tank. Comply with all NMOCD, BLM, and BR safety regulations.
 Conduct safety meeting for all personnel on location. NU relief line. Record casing and bradenhead pressures. Blow down well and kill with water as necessary. ND wellhead and install cementing valve.
- Connect pump line to the bradenhead valve and load with water, record volume to fill.
 Pressure test the BH annulus to 300#. If the BH annulus does not hold pressure, then modify the following procedure as appropriate with approval from the BLM representative.
- 3. Establish rate down 2-7/8" casing with 20 bbls water, record pump rate and pressure. If the BH annulus did not test, then monitor the bradenhead for flow. If no flow or blow, then pump 10 7/8" RCN balls in additional water and monitor pressure, rate and volumes pumped, to confirm perforations are taking water and there is not a casing leak. If the bradenhead flows water or there are other indications of a casing leak, then MO and RU pulling unit to use 1-1/4" IJ tubing workstring to plug the well.
- 4. Plug #1 (Pictured Cliffs perforations and Fruitland, Kirtland, Ojo Alamo tops, 2360' Surface): After establishing rate down the 2-7/8" casing with water, then mix and pump total of 76 sxs cement (long plug, 30% excess) and bullhead the down 2-7/8" casing: first pump 10 sxs cement, then drop 10 RCN balls, then pump 66 sxs cement, do not displace. Double valve and shut in well. WOC. Tag cement.
- 5. ND cementing valves and cut off wellhead. Fill 2-7/8" casing with cement as necessary. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

Recommended:

perations Engineer

Approved: Julian Superintendent

Engineer: Julian Carrillo Office - (599-4043)

Office - (599-4043) Cell - (320-0321)

Sundry Required:

ON C

Approved:

Lease Operator: Randy Smith Specialist: Johnny Cole

Foreman: Joel Lee

Cell: 320-2611 Pager: 324-7533

Cell: 320-2521 Pager: 326-8349 Office: 324-6109 Cell- 320-2490

Huerfanito Unit #22R

Proposed P&A

Ballard Pictured Cliffs / AIN #83494001

1620' FNL & 1010' FEL, Section 4, T-26-N, R-9-W, San Juan County, NM Long: N: 36[^] 31.338 / Lat: W: 107[^] 47.298 / API #30-045-30793

Today's Date: 10/14/04

Spud: 2/18/02 Completed: 3/7/02

Elevation: 6425' GL 6437' KB

9-7/8" hole

Circulate 65 bbls Cement to Surface

7" 20# J-55 Casing set @ 142' Cement with 41cf (Circulated to Surface)

Plug #1: 2360' - 0' Type III cement, 76 sxs (30% excess, long plug)

Ojo Alamo @ 1272'

Kirtland @ 1434'

Fruitland @ 1839'

Pictured Cliffs @ 2175'

6-1/4" Hole

Pictured Cliffs Perforations: 2177' - 2360'

2-7/8" 6.5#, J-55 Casing set @ 2417', Cement with 439 sxs (849 cf) Circulate 65 bbls of cement to surface

TD 2428' **PBTD 2386'**

Huerfanito Unit #22R

Current

Ballard Pictured Cliffs / AIN #83494001

1620' FNL & 1010' FEL, Section 4, T-26-N, R-9-W, San Juan County, NM Long: N: 36^ 31.338 / Lat: W: 107^ 47.298 / API #30-045-30793

Today's Date: 10/14/04

Spud: 2/18/02 Completed: 3/7/02

Elevation: 6425' GL 6437' KB 9-7/8" hole

Circulate 65 bbls Cement to Surface

7" 20# J-55 Casing set @ 142' Cement with 41cf (Circulated to Surface)


Ojo Alamo @ 1272'

Kirtland @ 1434'

Fruitland @ 1839'

Pictured Cliffs @ 2175'

6-1/4" Hole



Pictured Cliffs Perforations: 2177' – 2360'

2-7/8" 6.5#, J-55 Casing set @ 2417', Cement with 439 sxs (649 cf) Circulate 65 bbls of cement to surface

TD 2428' PBTD 2386'