RECEIVED

OIL CONS. DIV DIST. 3

APR 0 5 2017

OCT 2 7 2017

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Part Man

Farmington Field Office

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

		bule	au oi Lanu Managen	ease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS				NMSF 078767	
Do not use this abandoned well	1 4	6. If Indian, Allottee or Tribe Name			
SUE		7. If Unit of CA/Agreement, Name and/or No.			
1. Type of Well			N	MNM 78407E	
Oil Well		Well Name and No. osa Unit 116			
Name of Operator WPX Energy Production, LL		9. API Well No. 30-039-23484			
3a. Address PO Box 640 Aztec, NM 87410		3b. Phone No. (include area code) 505-333-1808		Field and Pool or Exploratory Area asin Mancos	
4. Location of Well (Footage, Sec., T.,R,M., or Survey Description) 1050' FNL & 790' FEL Sec 24, T 31N, R6W				County or Parish, State tio Arriba, NM	
12. CHECK	THE APPROPRIATE BOX	(ES) TO INDICATE NATU	JRE OF NOTICE, REPOR	RT OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTIO					
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		
Subsequent Report	Change Plans	Plug and Abandon	Temporarily	y	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disp	osal of any proposed work and approximate	
requirements, including recla	mation, have been completed /PX Energy notified & requesting to perfor	l and the operator has deten received verbal apportunity n a Mechanical Integ	roval on 4/4/17 from rity Test (MIT) to pla edure and wellbore BLM'S APPROVAL O ACTION DOES NOT	William Tambekou (BLM) & ace the following well in diagram attached. OR ACCEPTANCE OF THIS RELIEVE THE LESSEE AND OBTAINING ANY OTHER LEQUIRED FOR OPERATIONS	
14. I hereby certify that the foregoin	g is true and correct.		ON PEDEROLIAID		
Name (Printed/Typed)	Dame it Took				
Marie E. Jaramillo	Title Permit Tech				
Signature W	THIS SPACE F	OR FEDERAL OR	Date 4/4/17 STATE OFFICE US	E	
Approved by	/ Inis SPACE P	OR PEDERAL OR	Petroleum)E	
Conditions of approval, if any, are at the applicant holds legal or equitable applicant to conduct operations there	title to those rights in the subj		Title Engin	eer Date 4/6/2017	
Title 18 U.S.C. Section 1001 and Tit United States any false, fictitious or				nake to any department or agency of the	

OCT 2 7 2017



MECHANICAL INTEGRITY TEST PROCEDURE

ROSA UT #116 SAN JUAN BASIN, NEW MEXICO 04 APR, 2017

Ensure fuel used during job & estimate of vented gas is reported in daily reports

Continuous personal H2S monitoring is required. Any H2S alarms or other indications above 10ppm will require work to stop and the situation to be evaluated.

OBJECTIVE:

1) Prepare well for and conduct MIT.

PRIOR TO PRIMARY JOB

1) Verify location is okay for rig and/or wireline operations.

 Ensure JSA, ECP's and lockout procedures are in place for the flowline and other energized piping or equipment.

SAFETY NOTICE

PERSONNEL SAFETY IS THE NUMBER ONE JOB.

NO EXCEPTIONS!!!

PLEASE FOLLOW APPROPRIATE WPX CONTRACTOR PROTOCOLS FOR THIS JOB PLAN


Please see your WPX Business Representative if you have any questions; Contrator protocols can be located in the WPX Energy Contractor Guide

PROCEDURE:

<u>Note:</u> A safety meeting shall be held each morning before work and subsequent "tailgate" safety meetings are to be held during the day when operation objectives shift in nature and intent (i.e. beginning/ending fishing operations, squeeze jobs, rigging down, etc.) Please ensure these are documented per the WPX Energy Contractor Guide

- 1. Notify BLM & NMOCD 24 hrs prior to start of work.
- 2. Spot equipment, MIRU.
- 3. Blow down csg to production tank, ensuring tank hatch is open, and load csg with produced water treated with biocide and corrosion inhibitor as needed to kill well.
- 4. RIH w/CIBP on wireline, setting between 6,716' 6,766' (within 50' of top perf of 6,766').
- 5. Load csg with produced water treated with biocide and corrosion inhibitor.
- 6. Pressure test csg to 500 psi surface pressure for 30 minutes.
 - a. Pressure drop cannot be greater than 10% over 30-minute period.
 - b. Monitor surface csg pressure and flow during test.
 - c. Top off csg after the test.
 - d. Record test on chart recorder with maximum 2-hr clock and maximum 1000-lb spring, which has been calibrated within 6 months prior to test.
 - e. Witnesses to test shall sign the chart.
- 7. Secure well.
- 8. RDMO.
- 9. Turn all data in to office.

ROSA UNIT #116 MV



HOLE SIZE	CASING	CEMENT CMT. TOP		
15"	11-3/4"	350 sx	Surface	
7-7/8"	4-1/2"	1855 ax	Surface	