

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROV	/ED
OMB NO. 1004-	0137
Expires: January 31	, 2018

#### SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMSF080565A

Do not use th abandoned we	is form for proposals to	drill or to re-enter an	and the second s		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.		6. If Indian, Allotte	If Indian, Allottee or Tribe Name     If Unit or CA/Agreement, Name and/or No.     Well Name and No.     LITTLE ANGEL 1		
SUBMIT IN TRIPLICATE - Other instructions on page 2  1. Type of Well  Oil Well  Gas Well Other					7. If Unit or CA/Ag
2. Name of Operator DUGAN PRODUCTION COR	Contact: PORATI <b>@M</b> ail: aliph.reena	ALIPH REENA @duganproduction.com	9. API Well No. 30-039-06102	2-00-S1	
Sa. Address FARMINGTON, NM 87499	3b. Phone No. (include area code) Ph: 505-325-1821	10. Field and Pool TAPACITO	10. Field and Pool or Exploratory Area TAPACITO		
Location of Well (Footage, Sec., 7	T R M or Survey Description		11. County or Paris	sh. State	
Sec 8 T25N R3W NENE 36.417536 N Lat, 107.161926 W Lon				RIO ARRIBA COUNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION		TYPE OF	ACTION		
- National Classic	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
■ Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	Reclamation	☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon		
68	Convert to Injection	☐ Plug Back	■ Water Disposal		
determined that the site is ready for	bandonment Notices must be file final inspection.	sults in a multiple completion or reco	ing reclamation, have been complete	ed and the operator has	
Dugan Production Corp. plan.  1) Set 4-1/2" CIBP @ 3686'.  2) Spot inside Plug I above C (15.6#/gal, 1.18 cu ft/sk) - Plu 3) Perforate @ 2450'. Set ins (15.6#/gal, 1.18 cu ft/sk) - Plu	bandonment Notices must be file final inspection.  s to plug and abandon the Pressure test casing to 60 IBP @ 3686' w/24 sks (28 ug I: PC-Fruitland-Kirtland- side/outside plug w/36 sks ug II: Nacimiento 2350'-248 te Plug III to surface from 1 Cl2 (15.6#/gal, 1.18 cu ft/sk ement in case needed. Cu	well as per the following proc 10 psi. Run CBL from 3686' to 13 cu ft) Class B neat cement Ojo Alamo: 3450'-3686'. (42.5 cu ft) Class B neat cem 50'. 170' (casing shoe @ 120') w/4 (x) - Surface, Plug III: 0-170'. ut wellhead.	edure: o surface. to 3450' ent to 2350' 0 sks (48 cu	ed and the operator has	
Dugan Production Corp. plan.  1) Set 4-1/2" CIBP @ 3686'.  2) Spot inside Plug I above C (15.6#/gal, 1.18 cu ft/sk) - Plu 3) Perforate @ 2450'. Set ins (15.6#/gal, 1.18 cu ft/sk) - Plu 4) Perforate @ 170'. Circulat ft) Class B cement w/2% CaC 5) Tag TOC at surface. Fill of	bandonment Notices must be file final inspection.  s to plug and abandon the Pressure test casing to 60 IBP @ 3686' w/24 sks (28 ug I: PC-Fruitland-Kirtland- side/outside plug w/36 sks ug II: Nacimiento 2350'-248 te Plug III to surface from 1 Cl2 (15.6#/gal, 1.18 cu ft/sk ement in case needed. Cu	well as per the following proc 10 psi. Run CBL from 3686' to 13 cu ft) Class B neat cement Ojo Alamo: 3450'-3686'. (42.5 cu ft) Class B neat cem 50'. 170' (casing shoe @ 120') w/4 c) - Surface, Plug III: 0-170'. 170' twellhead.	reclamation, have been complete sedure: surface. to 3450' ent to 2350' 0 sks (48 cu	ed and the operator has	
Dugan Production Corp. plan.  1) Set 4-1/2" CIBP @ 3686'.  2) Spot inside Plug I above C (15.6#/gal, 1.18 cu ft/sk) - Plu 3) Perforate @ 2450'. Set ins (15.6#/gal, 1.18 cu ft/sk) - Plu 4) Perforate @ 170'. Circulat ft) Class B cement w/2% CaC 5) Tag TOC at surface. Fill c 6) Install dryhole marker. Cu	bandonment Notices must be file final inspection.  s to plug and abandon the Pressure test casing to 60 IBP @ 3686' w/24 sks (28 Ig I: PC-Fruitland-Kirtland- side/outside plug w/36 sks Ig II: Nacimiento 2350'-248 Ie Plug III to surface from 10 Cl2 (15.6#/gal, 1.18 cu ft/sk ement in case needed. Cu t anchors. Clean location.  is true and correct.  Electronic Submission # For DUGAN PRODU	well as per the following proc 10 psi. Run CBL from 3686' to 13 cu ft) Class B neat cement 15 Class B neat cement 16 Class B neat cement 17 Class B neat cement 17 Class B neat cement 18 Class B neat cement 19 Class B neat cement 19 Class B neat cement 19 Class B neat cement 10 Class	ing reclamation, have been complete edure: surface. to 3450' ent to 2350' 0 sks (48 cu  JUL 2 3 hrs g	ed and the operator has	
Dugan Production Corp. plant 1) Set 4-1/2" CIBP @ 3686'. 2) Spot inside Plug I above C (15.6#/gal, 1.18 cu ft/sk) - Plu 3) Perforate @ 2450'. Set ins (15.6#/gal, 1.18 cu ft/sk) - Plu 4) Perforate @ 170'. Circulat ft) Class B cement w/2% CaC 5) Tag TOC at surface. Fill c 6) Install dryhole marker. Cu	bandonment Notices must be file final inspection.  s to plug and abandon the Pressure test casing to 60 IBP @ 3686' w/24 sks (28 Ig I: PC-Fruitland-Kirtland- side/outside plug w/36 sks Ig II: Nacimiento 2350'-245 te Plug III to surface from 1 Cl2 (15.6#/gal, 1.18 cu ft/sk ement in case needed. Cu t anchors. Clean location.  is true and correct. Electronic Submission # For DUGAN PRODU particular formation of the company of	well as per the following processing by JACK SAVAGE on 00  Notify NMOCD 24  Prior to beginning operations	ing reclamation, have been complete edure: surface. to 3450' ent to 2350' 0 sks (48 cu  JUL 2 3 hrs g	ed and the operator has	
Dugan Production Corp. plant 1) Set 4-1/2" CIBP @ 3686'. 2) Spot inside Plug I above C (15.6#/gal, 1.18 cu ft/sk) - Plu 3) Perforate @ 2450'. Set ins (15.6#/gal, 1.18 cu ft/sk) - Plu 4) Perforate @ 170'. Circulat ft) Class B cement w/2% CaC 5) Tag TOC at surface. Fill c 6) Install dryhole marker. Cu  4. I hereby certify that the foregoing in  Co	bandonment Notices must be file final inspection.  s to plug and abandon the Pressure test casing to 60 IBP @ 3686' w/24 sks (28 Ig I: PC-Fruitland-Kirtland- side/outside plug w/36 sks Ig II: Nacimiento 2350'-245 te Plug III to surface from 1 Cl2 (15.6#/gal, 1.18 cu ft/sk ement in case needed. Cu t anchors. Clean location.  is true and correct. Electronic Submission # For DUGAN PRODU particular formation of the company of	well as per the following processing by JACK SAVAGE on 00  Notify NMOCD 24  Prior to beginning operations	ing reclamation, have been complete edure: surface. to 3450' ent to 2350' 0 sks (48 cu  JUL 2 3 hrs g IInformation System o the Rio Puerco 7/18/2018 (18JWS0006SE) ICTION ENGINEER	ed and the operator has	
Dugan Production Corp. plant 1) Set 4-1/2" CIBP @ 3686'. 2) Spot inside Plug I above C (15.6#/gal, 1.18 cu ft/sk) - Plu 3) Perforate @ 2450'. Set ins (15.6#/gal, 1.18 cu ft/sk) - Plu 4) Perforate @ 170'. Circulat ft) Class B cement w/2% CaC 5) Tag TOC at surface. Fill c 6) Install dryhole marker. Cu  4. I hereby certify that the foregoing in  Co	bandonment Notices must be file final inspection.  s to plug and abandon the Pressure test casing to 60 IBP @ 3686' w/24 sks (28 ug l: PC-Fruitland-Kirtland- side/outside plug w/36 sks ug ll: Nacimiento 2350'-245 ug ll: Nacimiento 2350'-245 ug ll: Nacimiento 2350'-245 ug ll: Nacimiento 2350'-245 us Plug III to surface from 1022 (15.6#/gal, 1.18 cu ft/sk ement in case needed. Cu t anchors. Clean location.  is true and correct.  Electronic Submission # For DUGAN PRODU Dommitted to AFMSS for proc EENA  Submission)	well as per the following process of the second of the sec	ing reclamation, have been completed by the complete sedure: a surface. to 3450' ent to 2350' on sks (48 cu  JUL 23 description of the surface of the surfac	ed and the operator has	
Dugan Production Corp. plan.  1) Set 4-1/2" CIBP @ 3686'.  2) Spot inside Plug I above C (15.6#/gal, 1.18 cu ft/sk) - Plu 3) Perforate @ 2450'. Set ins (15.6#/gal, 1.18 cu ft/sk) - Plu 4) Perforate @ 170'. Circulat ft) Class B cement w/2% CaC 5) Tag TOC at surface. Fill c 6) Install dryhole marker. Cu	bandonment Notices must be file final inspection.  s to plug and abandon the Pressure test casing to 60 IBP @ 3686' w/24 sks (28 ug l: PC-Fruitland-Kirtland- side/outside plug w/36 sks ug ll: Nacimiento 2350'-245 ug ll: Nacimiento 2350'-245 ug ll: Nacimiento 2350'-245 ug ll: Nacimiento 2350'-245 us Plug III to surface from 1022 (15.6#/gal, 1.18 cu ft/sk ement in case needed. Cu t anchors. Clean location.  is true and correct.  Electronic Submission # For DUGAN PRODU Dommitted to AFMSS for proc EENA  Submission)	well as per the following processor of the processor of t	ing reclamation, have been completed by the complete sedure: a surface. to 3450' ent to 2350' on sks (48 cu  JUL 23 description of the surface of the surfac	ed and the operator has	

(Instructions on page 2) \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

# P&A Surface Reclamation Plan Little Angel #1

30-039-06102

A-08-25N-03W


790 FNL 790 FEL

Dugan Production Corp. will plug and abandon the Little Angel #1. The well resides on a federal mineral lease but the surface of this well location is privately owned. Dugan Production Corp. will work with the land owner to rehabilitate this well pad as the land owner directs.

If there are questions or concerns please contact Kevin Smaka with Dugan Production Corp. at (505) 325-1821.

## **Current Wellbore Schematic**

Little Angel # 1 Sec 8 T25N R3W 790' FNL & 790' FEL Rio Arriba NM



7-5/8" 26.4# casing @ 120'. Cemented with 50 sks Cement. Hole size  $9\text{-}3\,^{\prime}4\text{''}$ 

4 1/2" 9.4 # casing @ 3800'. Hole size: 6-3/4"

Cement production casing w/ 100 sks.


Top of cement from Cement Volume @ 3160'

Pictured cliffs Perforated @ 3736' - 3772'

PBTD @ 3770', TD @ 3800'

## Planned Wellbore Schematic

Little Angel # 1 Sec 8 T25N R3W 790' FNL & 790' FEL Rio Arriba NM



7-5'8" 26.4# casing @ 120'. Cemented with 50 sks Cement. Hole size 9-3'4"

Perforate @ 170'. Circulate plug to surface w/ 40 sks Class B Cement (47.6 cu.ft) (Plug III, Surface -170')

4 1/2" 9.4 # casing @ 3800'. Hole size: 6-3/4"

Cement production casing w/ 100 sks.

Set Inside Plug @ 2450' with 36 sks (42.5 cu.ft) @ 2350'-2450' Class B cement. (Plug II, Nacimento, 2350'-2450')

Top of cement from Cement Volume @ 3160'

CIBP @ 3686'. Set Inside Plug with 24 sks (28 cu.ft) @ 3686' Class B cement. (Plug I, Pictured Cliff-Fruitland-Kirtland-Ojo Alamo, 3450'-3686')

Pictured cliffs Perforated @ 3736' - 3772'

PBTD @ 3770', TD @ 3800'

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Little Angel #1

### CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
  - a) Set plug #1 (3686 3232) ft. to cover the Fruitland, Kirtland, and Ojo Alamo tops. BLM picks top of Fruitland at 3539 ft. BLM picks top of Kirtland at 3492 ft. BLM picks top of Ojo Alamo at 3282 ft.
  - b) Set plug #2 (2097 1997) ft. inside/outside to cover the Nacimiento top. BLM picks top of Nacimiento at 2047 ft.

Operator will run CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.