Office	State of New Me		Form C-103
District I	Energy, Minerals and Natur	al Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240		[	WELL API NO.
District II	OIL CONSERVATION	DIVISION	30-045-32301
1301 W. Grand Ave., Artesia, NM 88210	1220 South St. Fra		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE   FEE
District IV	Santa Fe, NM 8	/303	
1220 S. St. Francis Dr., Santa Fe, NM 87505		ĺ	6. State Oil & Gas Lease No.
SUNDRY NOTICE	S AND REPORTS ON WEL	LS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	ALC TO DOLL OD TO DEEDEN O	D DI LIC DACK TO A	FEDERAL GAS COM E
1. Type of Well:	کم	Jo i GAN	8. Well Number
Oil Well Gas Well X	Other		#3
2. Name of Operator		20 Policy 20	9 OGRID Number
·	(sm	005	L
XTO Energy Inc.	28.	<u> </u>	167067
3. Address of Operator		0/10/10/10	₹0. Pool name or Wildcat
2700 Farmington Ave., Bldg.	K. Ste 1 Farmington & M	87401	BASIN FRUITLAND COAL
4. Well Location	W.	Ps	7
Unit Letter I:1,	980' feet from the FS	L CZ lingland	660' feet from the FEL line
One Letter	leet from the	o Company	leet from the Fig.
Section 30	Township 30N	Range 12W	NMPM County SAN JUAN
	11. Elevation (Show whether I		
	•	56' GL	
新元・安徽  日本村市社会の大阪(東京)		20. Gri	14 所に対して、発しまた。その、1940年の日本の開発の対象を開発を開発しまり
Pit or Below-grade Tank Application .	or Closure L.L.		
Pit type Depth to Groundwater	Distance from nearest fresh	water well Disc	tance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume_	bbls: Constructio	on Material
-	propriate Box to Indicate		- ·
NOTICE OF INTEL			SEQUENT REPORT OF:  ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK			☐ ALTERING CASING ☐
PERFORM REMEDIAL WORK	PLUG AND ABANDON   CHANGE PLANS  MULTIPLE	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND	ALTERING CASING  PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON  CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLI	ALTERING CASING  PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON   CHANGE PLANS  MULTIPLE	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND	ALTERING CASING   NG OPNS.  PLUG AND  ABANDONMENT
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deperations. (Clearly state all per	REMEDIAL WORK COMMENCE DRILLI CASING TEST AND CEMENT JOB OTHER: PT PROD C	ALTERING CASING   NG OPNS.  PLUG AND  ABANDONMENT
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS COMPLETION COMPLETION CPERATIONS. (Clearly state all per SEE RULE 1103. For Multiple	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD C  tinent details, and give Completions: Attach	ALTERING CASING AND ABANDONMENT  CSG  E pertinent dates, including estimated date
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Operations. (Clearly state all per SEE RULE 1103. For Multiple ested 5-1/2" production care	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and give completions: Attach	ALTERING CASING ABANDONMENT  CSG  E pertinent dates, including estimated date a wellbore diagram of proposed completion
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Operations. (Clearly state all per SEE RULE 1103. For Multiple ested 5-1/2" production care	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and give completions: Attach	ALTERING CASING ABANDONMENT  CSG  E pertinent dates, including estimated date a wellbore diagram of proposed completion
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Operations. (Clearly state all per SEE RULE 1103. For Multiple ested 5-1/2" production care	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and give completions: Attach	ALTERING CASING ABANDONMENT  CSG  E pertinent dates, including estimated date a wellbore diagram of proposed completion
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Operations. (Clearly state all per SEE RULE 1103. For Multiple ested 5-1/2" production care	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and give completions: Attach	ALTERING CASING ABANDONMENT  CSG  E pertinent dates, including estimated date a wellbore diagram of proposed completion
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Operations. (Clearly state all per SEE RULE 1103. For Multiple ested 5-1/2" production care	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and give completions: Attach	ALTERING CASING ABANDONMENT  CSG  E pertinent dates, including estimated date a wellbore diagram of proposed completion
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Operations. (Clearly state all per SEE RULE 1103. For Multiple ested 5-1/2" production care	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and give completions: Attach	ALTERING CASING ABANDONMENT  CSG  E pertinent dates, including estimated date a wellbore diagram of proposed completion
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Operations. (Clearly state all per SEE RULE 1103. For Multiple ested 5-1/2" production care	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and give completions: Attach	ALTERING CASING ABANDONMENT  CSG  E pertinent dates, including estimated date a wellbore diagram of proposed completion
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). Sor recompletion.  XTO Energy Inc. pressure to 1800	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deparations. (Clearly state all persected 5-1/2" production capsing for 5 minutes. Held	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD C  tinent details, and give Completions: Attach  asing on 3/15/05 to	ALTERING CASING AND ABANDONMENT  CSG E pertinent dates, including estimated date a wellbore diagram of proposed completion  CO 1500 psig for 30 minutes w/chart.
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to Increased pressure to 3800	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deparations. (Clearly state all persected 5-1/2" production capsing for 5 minutes. Helpoperation to the state of the structure of the state of the structure	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD C  tinent details, and give Completions: Attach  asing on 3/15/05 to i or.	ALTERING CASING AND ABANDONMENT  CSG E pertinent dates, including estimated date a wellbore diagram of proposed completion  CO 1500 psig for 30 minutes w/chart.
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to 1800  I hereby certify that the information abording the constructed or close the	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deparations. (Clearly state all persected 5-1/2" production capsing for 5 minutes. Hele  Department of the production of	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and gives a completions: Attach  assing on 3/15/05 to a completions.  best of my knowledges   , a general permit [	ALTERING CASING ABANDONMENT  PLUG AND ABANDONMENT  ABANDONMENT  Experiment dates, including estimated date a wellbore diagram of proposed completion  To 1500 psig for 30 minutes w/chart.  Experiment dates and belief. I further certify that any pit or below—  or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to Increased pressure to 3800	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deparations. (Clearly state all persected 5-1/2" production capsing for 5 minutes. Heldon be sed according to NMOCD guideline TIT	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD C  tinent details, and give Completions: Attach  assing on 3/15/05 to d OK.  best of my knowledges , a general permit [ LE	ALTERING CASING ABANDONMENT  PLUG AND ABANDONMENT  Experiment dates, including estimated date a wellbore diagram of proposed completion  To 1500 psig for 30 minutes w/chart.  The and belief. I further certify that any pit or belowing and (attached) alternative OCD-approved plan COMPLIANCE TECH DATE 4/4/2005
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to 1800  I hereby certify that the information abording the constructed or close the	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deparations. (Clearly state all persected 5-1/2" production capsing for 5 minutes. Held  Department of the sed according to NMOCD guideline  TIT  E-n	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD C  tinent details, and give Completions: Attach  assing on 3/15/05 to d OK.  best of my knowledges , a general permit [ LE	ALTERING CASING ABANDONMENT  PLUG AND ABANDONMENT  ABANDONMENT  Experiment dates, including estimated date a wellbore diagram of proposed completion  To 1500 psig for 30 minutes w/chart.  Experiment dates and belief. I further certify that any pit or below—  or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to Increased pressure to 3800  I hereby certify that the information aborgrade tank has been/will be constructed or closs SIGNATURE	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deparations. (Clearly state all persected 5-1/2" production capsing for 5 minutes. Held  Department of the sed according to NMOCD guideline  TIT  E-n	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and gives Completions: Attach  assing on 3/15/05 to i OK.  best of my knowledges , a general permit [ LE	ALTERING CASING ABANDONMENT  PLUG AND ABANDONMENT  Re pertinent dates, including estimated date a wellbore diagram of proposed completion  To 1500 psig for 30 minutes w/chart.  Re and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan OMPLIANCE TECH DATE 4/4/2005  Regulatory®ctoenergy.com Telephone No. 505-324-1090
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to Increased pressure to 3800  I hereby certify that the information abordance tank has been/will be constructed or closs SIGNATURE  Type or print name HOLLY C. PERKIN	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deparations. (Clearly state all per SEE RULE 1103. For Multiple steed 5-1/2" production capsing for 5 minutes. Hele  Exercise the end complete to the sed according to NMOCD guideline  TIT  E-n	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and give completions: Attach  assing on 3/15/05 to a ok.  best of my knowledge is, a general permit [ LE	ALTERING CASING ABANDONMENT  PLUG AND ABANDONMENT  Re pertinent dates, including estimated date a wellbore diagram of proposed completion  To 1500 psig for 30 minutes w/chart.  Re and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan OMPLIANCE TECH DATE 4/4/2005  Regulatory@xtoenergy.com Telephone No. 505-324-1090  STRICT # 3 APR - 8 2005
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). So or recompletion.  XTO Energy Inc. pressure to Increased pressure to 3800  I hereby certify that the information aborgade tank has been/will be constructed or closs SIGNATURE  Type or print name HOLLY C. PERKIN	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Deparations. (Clearly state all per SEE RULE 1103. For Multiple steed 5-1/2" production capsing for 5 minutes. Hele  Exercise the end complete to the sed according to NMOCD guideline  TIT  E-n	REMEDIAL WORK  COMMENCE DRILLI  CASING TEST AND CEMENT JOB  OTHER: PT PROD Continent details, and gives Completions: Attach  assing on 3/15/05 to i OK.  best of my knowledges , a general permit [ LE	ALTERING CASING ABANDONMENT  PLUG AND ABANDONMENT  Re pertinent dates, including estimated date a wellbore diagram of proposed completion  To 1500 psig for 30 minutes w/chart.  Re and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan OMPLIANCE TECH DATE 4/4/2005  Regulatory®ctoenergy.com Telephone No. 505-324-1090