

30-045-27478

Release Notification and Corrective Action

OPERATOR

☐ Initial Report

☒ Final Report

|  |                        |                                      |
|--|------------------------|--------------------------------------|
| Name<br>Conoco Inc.                                  |                        | Contact<br>Gary Ledbetter            |
| Address<br>3315 Bloomfield Hwy ; Farmington,NM 87401 |                        | Telephone No.<br>505-324-5837        |
| Facility Name<br>FC State Com #4                     |                        | Facility Type<br>Production Facility |
| Surface Owner<br>NMOCD                               | Mineral Owner<br>NMOCD | Lease No.<br>B-11240-75              |

| LOCATION OF RELEASE |               |                 |              |                       |                         |                       |                       |                    |
|---------------------|---------------|-----------------|--------------|-----------------------|-------------------------|-----------------------|-----------------------|--------------------|
| Unit Letter<br>N    | Section<br>36 | Township<br>31N | Range<br>09W | Feet from the<br>1340 | North/South Line<br>FNL | Feet from the<br>800' | East/West Line<br>FEL | County<br>SAN JUAN |

NATURE OF RELEASE

type of release  
PRODUCED WATER

volume of release  
80 BBLS

time of recovery  
75 BBLS

PRODUCED WATER TANK

6/5/00 7:15 PM

6/5/00 11:00PM

☐ Yes

☒ No

☐ Not Required

By Whom?

Date and Hour

as a watercourse tank

time impacting as a watercourse

Yes

X No

If a Watercourse was Impacted, Describe Fully. (Attach additional Sheets If Necessary)

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

The high level alarm switch was not properly adjusted. This allowed the tank to fill up and spill over because the operator didn't have adequate time to respond. Picked up 75 bbls with vacuum truck.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Spill occurred inside the Berm area. The small amounts of water that wasn't picked up was left to evaporate. The immediate and written notice to the NMOCD was not given because of Human error. (New employee to SHEAR position and/or very little verbal communication)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations

Signature:

Printed Name: G Ledbetter

SHEAR Specialist

505-324-5837

OIL CONSERVATION DIVISION

Approved by: *Larry Tom*

District Supervisor: *for Tank CL 142*

Approval Date: *11/16/00*

Expiration Date:

Conditions of Approval:

Attached

nJK1217856324