F	ORM A	ΑPI	PRO	VEL
O	MB N	o. 1	004-	013
			2.1	~~.

NOV 26 2012 BU Farmington Field Office Page of Land ManagerSUNDF Do not use the abandoned week  SUBM Type of Well Oil Well Name of Operator Burlington a. Address PO Box 4289, Farmington,	nis form for proposals ell. Use Form 3160-3 ( IIT IN TRIPLICATE - Other in  Gas Well	ANAGEMENT  PORTS ON WELLS  to drill or to re-enter an  (APD) for such proposals.  Instructions on page 2.	OMB No. 1004-0137 Expires: July 31, 2010  5. Lease Serial No.  SF-079148  6. If Indian, Allottee or Tribe Name  7. If Unit of CA/Agreement, Name and/or No.  San Juan 32-9 Unit  8. Well Name and No.			
Farmington Field Office Bau of Land ManagerSUNDF Do not use the abandoned we submed to be submed to be submediated by the submediate of Operator  Burlington a. Address PO Box 4289, Farmington,	RY NOTICES AND REP his form for proposals ell. Use Form 3160-3 (A BIT IN TRIPLICATE - Other in Gas Well Other	PORTS ON WELLS to drill or to re-enter an (APD) for such proposals. estructions on page 2.	5. Lease Serial No.  SF-079148  6. If Indian, Allottee or Tribe Name  7. If Unit of CA/Agreement, Name and/or No.  San Juan 32-9 Unit  8. Well Name and No.			
Red of Land ManagerSUNDF Do not use the abandoned we submit the submit to submit the submit	nis form for proposals ell. Use Form 3160-3 ( IIT IN TRIPLICATE - Other in  Gas Well	s to drill or to re-enter an (APD) for such proposals.	SF-079148  6. If Indian, Allottee or Tribe Name  7. If Unit of CA/Agreement, Name and/or No. San Juan 32-9 Unit  8. Well Name and No.			
Rau of Land Wanagers UNDF Do not use the abandoned we submit the control of the c	nis form for proposals ell. Use Form 3160-3 ( IIT IN TRIPLICATE - Other in  Gas Well	s to drill or to re-enter an (APD) for such proposals.	6. If Indian, Allottee or Tribe Name  7. If Unit of CA/Agreement, Name and/or No.  San Juan 32-9 Unit  8. Well Name and No.			
Do not use the abandoned we submit the submit to submit the submit	nis form for proposals ell. Use Form 3160-3 ( IIT IN TRIPLICATE - Other in  Gas Well	s to drill or to re-enter an (APD) for such proposals.	7. If Unit of CA/Agreement, Name and/or No. San Juan 32-9 Unit 8. Well Name and No.			
Address PO Box 4289, Farmington,	ell. Use Form 3160-3 (A	(APD) for such proposals.  Instructions on page 2.	San Juan 32-9 Unit 8. Well Name and No.			
SUBM Type of Well Oil Well  Name of Operator  Burlington Address PO Box 4289, Farmington,	Gas Well Other	nstructions on page 2.	San Juan 32-9 Unit 8. Well Name and No.			
Name of Operator  Burlington  Address  PO Box 4289, Farmington,	Gas Well Other		San Juan 32-9 Unit 8. Well Name and No.			
Name of Operator  Burlington  Address  PO Box 4289, Farmington,						
Name of Operator  Burlington  Address  PO Box 4289, Farmington,						
Burlington  Address PO Box 4289, Farmington,	1 Resources Oil & Gas		San Juan 32-9 Unit 282S			
. Address ∠ PO Box 4289, Farmington,	า Resources Oil & Gas		9. API Well No. <b>30-045-32253</b>			
PO Box 4289, Farmington,		Burlington Resources Oil & Gas Company LP				
<del>-</del>	NR/ 07/00	3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area  BASIN FRUITLAND COAL			
I and a continue of Wall (Cartain Cartain Cart	PO Box 4289, Farmington, NM 87499 (505) 326-9700  4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)					
urface UNIT P (SE	11. Country or Parish, State  San Juan , New Mexico					
		,, rowin, room	, Hotelson			
12. CHECK THE	APPROPRIATE BOX(ES	S) TO INDICATE NATURE OF N	OTICE, REPORT OR OTHER DATA			
TYPE OF SUBMISSION		CTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resume) Water Shut-Off			
1 1.0000 or men	Alter Casing	Fracture Treat	Reclamation Well Integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete Other			
subsequent Report	Change Plans	Plug and Abandon X	Temporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
			f any proposed work and approximate duration thereof.			
following completion of the involved of Testing has been completed. Final Abadetermined that the site is ready for final Burlington Resources requestattached procedure and current	operations. If the operation result andonment Notices must be filed al inspection.) ests permission to Tem	ts in a multiple completion or recompletion of donly after all requirements, including recomporary Abandon the subject w	ired subsequent reports must be filed within 30 days on in a new interval, a Form 3160-4 must be filed once clamation, have been completed and the operator has well until gas prices improve per the			
		Notify NMOCD 2 prior to beginn	24 hrs OIL CONS. DIV.			
		operations				
			ther defend it is "full"			

THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Date DEC 0 3 2012 Original Signed: Stephen Mason Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

## ConocoPhillips SAN JUAN 32-9 UNIT 282S Expense - TA

Lat 36° 56' 13.164" N

Long 107° 46' 43.824" W

## **PROCEDURE**

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact engineer to review complete BH history and get a gas analysis done.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure.
- 5. Pressure test tubing to 1000 psi before unseating the pump, release pressure. Kill well with water, if necessary.
- 6. TOOH with rods and LD (per pertinent data sheet).
- 7. ND wellhead and NU BOPE. Pressure and function test BOP. PU and remove tubing hanger and tag for fill, adding additional joints as needed. Record fill depth in Wellview.
- 8. TOOH with tubing (per pertinent data sheet).

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of coal fines if they have plugged up any parts of the tubing string.

- 9. Round trip guage ring with wireline for 7", 20#, J-55 casing.
- 10. Use wireline to set CIBP for 7", 20#, J-55 casing. Set CIBP at 3116' (100' above top FTC perforations 3216').
- 11. Performs MIT (Mechanical Integrity Test) above the CIBP to 600 psig for 30 minutes on a 2 hour chart. If pressure test fails, test CIBP and notify engineer.
- 12. If MIT is good, TIH and displace KCL with packer fluid. TOOH and LD tubing.
- 13. ND BOP, NU wellhead, and notify engineer, lead, and specialist that the operation is complete. RDMO.

