District I 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

	and to the second to the second to		Rele	ase Notific	catio	n and Co	orrective A	ction	<u> w - 12w </u>	And the second second		!
7						OPERATOR Initia			l Report	⊠ F	inal Report	
			es, a Wholly Company		Contact Ashley Maxwell							
Address 34	101 E. 30 ^t	^h St., Farm	NM 87402		Telephone No. 505-324-5169							
Facility Na	me Jillson	Federal #1				Facility Type Salt Water Disposal						
Surface Ow	ner Feder	al	Mineral (Owner	Federal API No. 3003925465 Lease No. SF - 080472					. '		
				LOC	ATIO	N OF REI	LEASE					
Unit Letter	Section	Township Range Feet from the North/South Line Feet from the East/West Line Cou				County						
F	08	024N	003W	2305'	1	North 2415'			est	R	Rio Arriba	
			Lat	itude 36.32567	′00 ° N	Longitue	de-107.1801400	0 ° W	1			
				NAT	ΓURE	OF REL	EASE					
Type of Rele							ecovered 10 BBL					
Source of Re	elease Pit T	ank				Date and Hour of Occurrence			Date and Hour of Discovery 7/7/2012 @ 7:00AM			
Was Immedi	ate Notice (Given?				If VES. To Whom?						
☐ Yes ☐ No ☒ Not Required										CVD NOV		•
By Whom?						Date and Hour OIL COWS. DIV.						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. DIST. 3						
If a Waterco	urse was Im	pacted, Descr	ibe Fully.*	:								
Heavy rain	runoff caus	em and Reme ed 10 BBL o r from the cr	f produced		low the	pit tank. Pit	is lined and the	over flow	remained	in the crib	bing. Re	covered
The spill wa clean-up, if	s limited to necessary. A	third party	Exterior of contracto i	pit and interior of	ssess th		shed. COPC will the liner and ob					
regulations a public health should their or the enviro	all operators n or the envi operations h onment. In a	are required to ronment. The nave failed to	to report ar e acceptanc adequately OCD accep	nd/or file certain ce of a C-141 reprinted investigate and	release rort by the remedia	notifications a ne NMOCD m te contaminat	knowledge and ond perform correlated as "Final Fion that pose a the operator of	ective action Report" do reat to gro	ns for rele es not reli und water	eases which eve the oper , surface wa	may endatator of liter, huma	anger ability an health
							OIL CON	ISERV	ATION	DIVISIO	<u>N</u>	:
Signature: Printed Name: Ashley Maxwell						Approved by Environmental Specialist: Kelly						
							11/20/0	12(7)		_		
Title: Envir	onmental Sp	ecialist				Approval Date: 1/30/2012 Expiration Date:						
E-mail Address: ashley.p.wethington@conocophillips.com						Conditions of Approval: Attached			:			
Date: Nover	nber 20, 201	2	Phone: 50	5-324-5169	}							

AES ST

Animas Environmental Services, LLC

www.animasenvironmental.com

624 E. Comanche Farmington, NM 87401 505-564-2281

> Durango, Colorado 970-403-3274

November 16, 2012

Ashley Maxwell ConocoPhillips San Juan Business Unit Office 216-2 5525 Hwy 64 Farmington, New Mexico 87401

RE: Produced Water Release Report

Jillson Federal SWD

Rio Arriba County, New Mexico

Dear Ms. Maxwell:

Animas Environmental Services, LLC (AES) is pleased to provide the final report associated with the 10 barrel (BBL) produced water release at the ConocoPhillips (CoP) Jillson Federal SWD, located in Rio Arriba County, New Mexico. The release, caused by overfilling of the pit tank, was fully contained within the pit liner.

1.0 Site Information

1.1 Location

Site Name - Jillson Federal SWD

Legal Description—SE¼ NW¼, Section 8, T24N, R3W, Rio Arriba County, New Mexico SWD Latitude/Longitude—N36.32567 and W107.18014, respectively Release Latitude/Longitude—N36.32525 and W107.18044, respectively Land Jurisdiction — Bureau of Land Management (BLM)

Figure 1. Topographic Site Location Map

Figure 2. Aerial Site Map, September 2012

1.2 NMOCD Ranking

Prior to site work, the New Mexico Oil Conservation Division (NMOCD) database was reviewed, and a C-144 form dated April 2011 reported the depth to groundwater as greater than 100 feet below ground surface (bgs). The New Mexico Office of the State Engineer (NMOSE) database was reviewed for nearby water wells, and no registered water wells were reported to be located within 1,000 feet of the location. Additionally, Google Earth and the New Mexico Tech Petroleum Recovery Research Center online

mapping tool (http://ford.nmt.edu/react/project.html) were accessed to aid in the identification of downgradient surface water.

Once on site, AES personnel further assessed the ranking using topographical interpretation, Global Positioning System (GPS) elevation readings, and visual reconnaissance. AES personnel concluded that depth to groundwater at the site was greater than 100 feet bgs. A tributary to Leeson Canyon is located on the north edge of the location. Based on this information, the location was assessed a ranking score of 20 per NMOCD *Guidelines for Leaks, Spills, and Releases* (August 1993).

1.3 Produced Water Release Assessment

AES was initially contacted by Ashley Maxwell, CoP representative, on August 21, 2012, and on September 27, 2012, Zach Trujillo of AES traveled to the location. Based on site conditions, it was not possible for AES personnel to collect a composite soil sample at the release location because the release had been full contained within the pit liner, and there was not enough soil/sediment present to collect a sample. All water from the release had been hydro-vacuumed during release abatement activities. AES visually evaluated the integrity of the liner, and no punctures, tears, cracks, thinning, or indentations were observed.

2.0 Conclusions and Recommendations

Lelay Chrodium

AES assessed the integrity of the liner at the Jillson Federal SWD on September 27, 2012, subsequent to a release caused by the overfilling of a below grade tank in August 2012. The liner was observed to be in good condition, with no signs of wear, holes, leaks, etc. Release liquids had been fully removed by CoP contractors, and there was not enough sediment/soil present to collect a sample for laboratory analysis. Based on completion of cleanup activities and assessment of the integrity of the liner, no further work is recommended.

If you have any questions about this report or site conditions, please do not hesitate to contact Deborah Watson at (505) 564-2281.

Sincerely,

Kelsey Christiansen Environmental Scientist Ashley Maxwell Jillson Federal SWD Produced Water Release Report November 16, 2012 Page 3 of 3


Elizabeth McNally, P.E.


Attachments:

Figure 1. Topographic Site Location Map

Figure 2. Aerial Site Map, September 2012

R:\Animas 2000\2012 Projects\Conoco Phillips\Jillson Federal SWD secondary spill\Jillson Federal SWD Assessment Report 111612.docx







Animas Environmental Services: LLC

build the management over According an endoughered	CALINDRALISE WITHOUT SERVICE THE TANKS WITH VISITED
DRAWN BY:	DATE DRAWN:
C. Lameman	October 30, 2012
REVISIONS BY:	DATE REVISED:
C. Lameman	October 30, 2012
CHECKED BY:	DATE CHECKED:
D. Watson	October 30, 2012
APPROVED BY:	DATE APPROVED:
E. McNally	October 30, 2012

AERIAL SITE MAP

ConocoPhillips
JILLSON FEDERAL SWD
RIO ARRIBA COUNTY, NEW MEXICO
SE¼ NW¼, SECTION 8, T24N, R3W
N36.32567, W107.18014