

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API# 30-039-26474

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company:	Energen Resources	Contact:	Kellie Campbell
Address:	2010 Afton Place	Telephone No.	505-324-4152
Facility Name:	Carracas 2 A 11	Facility Type:	On shore gas well

Surface Owner: Federal	Mineral Owner: Federal	Lease No. NM68762
------------------------	------------------------	-------------------

LOCATION OF RELEASE

Unit Letter K	Section 2	Township 31N	Range 5W	Feet from the 2405	North/South Line FSL	Feet from the 1880	East/West Line FWL	County Rio Arriba
------------------	--------------	-----------------	-------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------------

Latitude 36.92774 Longitude -107.33368

NATURE OF RELEASE

Type of Release: Spill of Produced water	Volume of Release < 20 bbls	Volume Recovered approx. 18-19 bbls
Source of Release: Tank over flow	Date and Hour of Occurrence 10-8-2009	Date and Hour of Discovery 10-8-09 @1230
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



RCVD NOV 8 '09

If a Watercourse was Impacted, Describe Fully.* NA	OIL CONS. DIV. DIST. 3
---	---------------------------

Describe Cause of Problem and Remedial Action Taken.* Lease operator discovered during routine inspections of well locations that the tank on location was over flowing. Tank mechanics were repaired immediately and a vacuum truck employed to remove free liquids.
--

Describe Area Affected and Cleanup Action Taken.* Produced water was vacuumed up with a vacuum truck and hauled to a disposal facility. Impacted secondary containment area was sampled to ensure no remedial efforts were required. Results are attached to report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kellie J. Campbell	Approved by District Supervisor:  For CP	
Title: Environmental/Safety Coordinator	Approval Date: 11/9/09	Expiration Date:
E-mail Address: kellie.campbell@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-19-2009	Phone: 505-324-4152	

* Attach Additional Sheets If Necessary

Incident # NMOCD 0931630847