Form 3160-5 (August 2007)

Subsequent Report

(Instruction on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010 5. Lease Serial No.

Farmington Field			SF-079382
SUNDRY NOTICES AND REPORTS ON WELLS Land Ma	63 If Indian, Allottee o	r Tribe Name	

Casing Repair

Change Plans

	e this form for proposals well. Use Form 3160-3 (A	to drill or to re-enter an APD) for such proposals.			
su	BMIT IN TRIPLICATE - Other in	structions on page 2.	7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well			San Juan 30-6 Unit		
Oil Well	Gas Well Other		8. Well Name and No. San Juan 30-6 Unit 1 POW		
2. Name of Operator			9. API Well No.		
Burlington Resources Oil & Gas Company LP		30-039-24530			
3a. Address		3b. Phone No. (include area code)	10. Field and Pool or Exploratory Area		
PO Box 4289, Farmington, NM 87499		(505) 326-9700	Basin Fruitland Coal		
4. Location of Well (Footage, Sec., T.,R.M., or Survey Description) Surface UNIT E (SWNW), 1485' FNL & 795' FWL, Sec. 24, T30N, R7W		11. Country or Parish, State Rio Arriba , New Mexico			
12. CHECK T	HE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NO	OTICE, REPORT OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent	Acidize	Deepen	Production (Start/Resume) Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation Well Integrity		

New Construction

Plug and Abandon

Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Burlington Resources intends to perform an MIT test on subject well as per the NMOCD regulations requiring MIT every 5 years. The last MIT was performed 7/8/2008. Procedure is attached.

> RCVD MAY 15'13 OIL CONS. DIV. DIST. 3

Pressure Observation

Notify NMOCD 24 hrs prior to beginning operations

Recomplete

Water Disposal

Temporarily Abandon

		\					
14. I hereby certify that the	he foregoing is true and correct. Name (Printed/Typed)						
	DENISE JOURNEY	Title		REGULTORY TECHNICIAN			
Signature	Denosi Journey	Date		5/8/2013			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by							
	Original Signed: Stephen Mason		Title	Date MAY 1 0 2013			
that the applicant holds le	f any, are attached. Approval of this notice does not warran egal or equitable title to those rights in the subject lease who anduct operations thereon.		Office				
	001 and Title 43 U.S.C. Section 1212, make it a crime for a lent statements or representations as to any matter within its		ngly and willfully to make to any	department or agency of the United States any			

ConocoPhillips SAN JUAN 30-6 UNIT 1 POW Expense - MIT

Lat 36°48' 4.392" N

Long 107°31'39.9" W

PROCEDURE

Notify NMOCD 48 hours in advance to witness MIT testing

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations.
- 2. MIRU pump truck. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact engineer to review complete BH history and get a gas analysis done.
- 3. RU hose from pump truck and connect to the casing. Verify that casing is filled with proper fluid.
- 4. MIT casing to 560# for 30 minutes on a 2 hour chart with a 1000# spring maximum. If the test passes, SI the well. RD pump and MOL. Bring the chart to the Production Engineer. If the test fails, contact the Rig Superintendent and Production Engineer.

