<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Form C-141

Revised August 8, 2011

Release Notification and Corrective Action												
						OPERATOR			X Initial Report			
Name of Company: Parko, Inc						Contact: Dr. Floyd Parker						
Address: P.O. 1655, Los Lunas, NM 87031						Telephone No. 505-259-1787						
Facility Name: Chapman No. 001						Facility Type: Production						
Surface Owner: BLM Mineral Owner:						: BLM			API No. 30-043-05185			
LOCATION OF RELEASE												
Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Li							est Line					
N	. 20	23W	6W_	660		South 1980 West Sandoval						
<u> </u>		<u> </u>	I o	titude	<u> </u>	Longitu	do.	.1	R	CVD OCT	17:1	
			La						DIL CONS. DIV.			
NATURE OF RELEASE DIST. 3												
Type of Rele	ase: Hydro	carbons and f				Volume Recovered Approx. 75 bbls						
Source of Re	lease: Well	head, separato	Date and Hour of Occurrence			Date and Hour of Discovery						
						9/30/2013 6:00 A.M. and			9/30/2013 at 6AM and			
						2 <sup>nd</sup> release between 6 PM and 6 AM on 10/1/2013			10/1/2013 at 6 AM			
Was Immediate Notice Given?						If YES, To Whom?						
✓ Yes ☐ No ☐ Not Required						d Jonathan Kelly NMOCD & Mark Kelly BLM						
By Whom? Johnnie Aragon, Parko and Frank McDonald						Date and Hour 9/30/2013 8 AM to NMOCD and BLM at 10 AM						
Was a Watercourse Reached?  ✓ Yes ☐ No						If YES, Volume Impacting the Watercourse. Approximately 20 bbls						
If a Watercourse was Impacted, Describe Fully.*  Two plumes left location. The North plume impacted a small water course at the end of the plume for approximately 165 feet. The south plume exited the												
southwest side of location and entered a small water course traveling approximately 650 feet.												
Describe Cause of Problem and Remedial Action Taken.*												
Two releases	occurred b	ack to back. T	he first re	lease was due to	the high	n pressure reli	ef valve located o	n the sep	arator on t	he morning	of 9/30	)/2013. The
							cond release overf					
		nead. Wellhea are being mon		e during the morn	ing of 1	10/01/2013 wa	as 2200 psi A flo	ow back	line and ta	nk nave bee	n attaci	nea to the
		<del>-</del>								<u>.</u>		
		and Cleanup			vater co	sureae couthw	est of the well pac	i Mech	mized eau	inment ac w	all ac la	aborers with
							avation, will be w					
	· · · · · · · · · · · · · · · · · · ·	· c			1	.1 1 . 6	1 11 1		1.1	NIN .	IOCD	11
							y knowledge and a and perform corre					
public health	or the envi	ironment. The	acceptan	ce of a C-141 rep	ort by t	he NMOCD 1	narked as "Final I	Report" d	loes not re	lieve the ope	erator c	of liability
should their	operations l	have failed to	adequately	y investigate and a	remedia	ate contamina	tion that pose a the we the operator of	reat to gr	ound water	er, surface w	ater, h	uman health
		ws and/or reg		plance of a C-141	тероп	does not rene	we the operator of	гезронз	ionity ioi i	comphance	with ai	iy omei
			$\overline{\mathcal{L}}$	11			OIL CON	ISERV	ATION	DIVISION	NC	
Signature:	1.1	M/ 4								,	1	
Orginatore.			·/	Approved by Environmental Specialist:								
Printed Nam	e: Frank M	cDonald		Tipploted by Entholmental Speci			yonan U- Kelly					
Title: Enviro	nmental Sp	ecialist		Approval Date: 10/17/2013 Expiration Date:								
F-mail Adde	ass fmod k	oest@hotmail.			Conditions of Approval:							
L-man Audi	cos. micu_t	<u>~st@notmall.</u>						Attached				
Date:			e:505-486-0058									

\* Attach Additional Sheets If Necessary

NJK 1329041044