Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	FOR	МΛ	PPR	OVED
(ЭМВ	NO.	100	4-013:
E	xoire	es: Ju	ılv 3	1, 201

SUNDRY SUNDRY Do not use thi abandoned wel	5. Lease Serial No. NMSF079602 6. If Indian, Allottee or Tribe Name								
SUBMIT IN TRII	7. If Unit or CA/Agreement, Name and/or No.								
Type of Well Oil Well	8. Well Name and No. L L MCCONNELL 11								
Name of Operator FOUR STAR OIL AND GAS C	Contact: COMPANE-Mail: APRIL.POR	HL N.COM		9. API Well No. 30-039-05830-00-S1					
3a. Address HOUSTON, TX 77252	3b. Phone No. (include area code) Ph: 505-333-1941 Fx: 505-334-7134			10. Field and Pool, or Exploratory BLANCO					
4. Location of Well (Footage, Sec., T	R. M. or Survey Description				11. County or Parish, a	nd State			
Sec 29 T25N R3W NWNW 11 36.372933 N Lat, 107.173758	90FNL 990FWL			RIO ARRIBA COUNTY, NM					
12. CHECK APPE	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF N	NOTICE, RE	PORT, OR OTHER	RDATA			
TYPE OF SUBMISSION	SUBMISSION TYPE OF ACTION								
Notice of Intent ■	☐ Acidize	- □ Dee	pen	☐ Producti	on (Start/Resume)	□ Water Shut-Off			
	☐ Alter Casing	☐ Fra	ture Treat	Reclama	ntion	□ Well Integrity			
☐ Subsequent Report	Casing Repair	□ Nev	v Construction	☐ Recomp	lete .	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans 🛛 Plu		g and Abandon	☐ Temporarily Abandon					
b/	Convert to Injection Plug		g.Back	☐ Water Disposal					
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give substrict locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) PROCEDURE IS TENTATIVELY SCHEDULED FOR LATE OCTOBER 2013 MIRU WORKOVER RIG. POOH WITH 2" TUBING. RIH WITH WORKSTRING AND TAG FOR FILL CLEANOUT TO BOTTOM PERF @ 3751'. SET CEMENT RETAINER @ 3700'. MIRU CEMENT PROVIDER, ESTABLISH INJECTION DOWN THE WORKSTRING AND THROUGH THE RETAINER. SQUEEZE THE P.C. PERFS FROM 3751'-3809', WITH 25 SACKS OF CEMENT. STINGOUT OF RETAINER AND SPOT 12 SACKS OF CEMENT ON RETAINER. PULL UP HOLE 700' AND CIRCULATE WELLBORE CLEAN WITH 2% KCL EQUIVALENT WATER. 10.1. PERFORATE @ 2066', USING 4 SPF, 90 DEG PHASE FOR SQUEEZE HOLES. MIRU CEMENT PROVIDER, SQUEEZE 25 SACKS OF CEMENT. TOH. PERFORATE @ 500', USING 4 SPF, 90 DEG PHASE FOR SQUEEZE HOLES. MIRU CEMENT PROVIDER, SQUEEZE 25 SACKS OF CEMENT. TOH. PERFORATE @ 500', USING 4 SPF, 90 DEG PHASE FOR SQUEEZE HOLES. MIRU CEMENT PROVIDER, SQUEEZE 25 SACKS OF CEMENT. TOH.									
14. I hereby certify that the foregoing is Cor Name (Printed/Typed) JAMIE EL	#Electronic Submission #2 For FOUR STAR OIL nmitted to AFMSS for proc	_ AND GAS C	OMPANY, sent to EVE MASON on 0	the Rio Puer	SXM0032SE)				
Signature (Electronic S	Date 09/24/20	013							
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	BE				
Approved By_STEPHEN_MASON_	TitlePETROLE	TitlePETROLEUM ENGINEER Date 09/25							
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the	Office Rio Puerco							
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to mal	ke to any department or a	gency of the United			

Additional data for EC transaction #220951 that would not fit on the form

32. Additional remarks, continued

and are grown to the following to the fo


PERFORATE #264', (50 ' BELOW CSG SHOE) USING A 4 SPF, 90 DEG PHASE FOR SQUEEZE HOLES.
MIRU CEMENT PROVIDER. OPEN BRADENHEAD VALVES. ESTABLISH INJECTION DOWN WORKSTRING AND REAINTER
AND ATTEMPT TO CIRCULATE UP SURFACE CASING. SQUEEZE THE SURFACE CASING SHOWS WITH 93 SACKS CEMENT.
STING OUT OF RETAINER AND 5-1/2" CASING WITH 32 SACKS CEMENT. CIRCULATE BOP CLEAN WITH WATER. IF
UNABLE TO CIRCULATE, SET A CEMENT RETAINER ABOVE THE PERFORATIONS AND FILL CASING WITH CEMENT TO
SURFACE.

TOH AND LAY DOWN WORKSTRING.
ND BOP. CUT OFF WELLHEAD, TOP FILL WITH CEMENT. WELD ON DRY HOLE MARKER.
RDMO WORKOVER RIG AND EQUIPMENT, CLEAN LOCATION.

PLEASE BE ADVISED TO CONTACT BOTH THE BLM AND NMOCD 48 HOURS PRIOR TO BEGINNING PROJECT TO SCHEDULE WITNESSING BY AGENCY REPRESENTATIVES.



LL McConnell #11 Rio Arriba County, New Mexico Current Well Schematic



Prepared by: Date: Jamie Elkington


9/20/2013

Revised by:

Date:



LL McConnell #11 Rio Arriba County, New Mexico PROPOSED WELLBORE



٠

Date:

Prepared by:

Jamie Elkington 9/20/2013 Revised by: Date:

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: 11 McConnell

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
- a) Bring the top of the Pictured Cliffs/Fruitland/Kirtland/Ojo Alamo plug to 3230'.
- b) Place the Nacimiento plug from 2106'- 2006' inside and outside the 5 1/2" casing.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.