Form 3160-5 (August 2007)	UNITED STAT DEPARTMENT OF THE BUREAU OF LAND MAI	ES EINTERIOR		) OMB N	APPROVED o. 1004-0137 July 31, 2010
SUN Do not use	IDRY NOTICES AND REP(	۲ ORTS ON WELLS to drill or₅to∖re=ent	)7 2013 Feiriahd Off	5. Lease Serial No. S 6. If Indian, Allottee or Tribe	F-076465
abandoned	well. Use Form 3160-3 (A	APD) <sub>f</sub> for <sub>f</sub> such <sup>f</sup> prop	oosalsාස්ථ්		
1. Type of Well	IBMIT IN TRIPLICATE - Other ins	structions on page 2.		7. If Unit of CA/Agreement, i	Name and/or No.
	X Gas Well Other			8. Well Name and No. Co	rnell B 100
Burling	ton Resources Oil & Gas			30-0	)45-30198
3a. Address         3b. Pho           PO Box 4289, Farmington, NM 87499         3b. Pho		3b. Phone No. (include at (505) 326-9		10. Field and Pool or Exploratory Area Basin Fruitland Coal	
4. Location of Well <i>(Footage, Sec., T.,</i> Surface UNIT A (N	R.,M., or Survey Description) ENE), 1075' FNL & 1315' F	EL, Sec. 14, T29N	l, R12W	11. Country or Parish, State San Juan	, New Mexico
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATU	RE OF NO	TICE, REPORT OR OTH	IER DATA
TYPE OF SUBMISSION	· .	TYF	PE OF AC	TION	
X Notice of Intent	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction X Plug and Abandon	F	roduction (Start/Resume) Reclamation Recomplete 'emporarily Abandon	Water Shut-Off Well Integrity Other
Final Abandonment Notice	Convert to Injection	Plug Back	\	Vater Disposal	· · · · · · · · · · · · · · · · · · ·
Attach the bond under which the v following completion of the involv Testing has been completed. Fina determined that the site is ready for <b>Burlington Resources</b>	requests permission to P	Bond No. on file with BLN s in a multiple completion of only after all requirements, <b>&amp;A the subject we</b>	measured and M/BIA. Requi or recompletio , including rec	red subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure	e filed within 30 days 50-4 must be filed once and the operator has , current and propos
Attach the bond under which the v following completion of the involv Testing has been completed. Fina determined that the site is ready for <b>Burlington Resources</b> wellbore schematics.	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.)	Bond No. on file with BLM s in a multiple completion of only after all requirements, <b>2&amp;A the subject we</b> <b>Visit was held on</b>	measured and M/BIA. Requi or recompletio , including rec	true vertical depths of all pertired subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure r/Bob Switzer, BLM F	e filed within 30 days 50-4 must be filed once 1 and the operator has 5, current and propose 7, Representative. The l
Attach the bond under which the v following completion of the involv Testing has been completed. Fina determined that the site is ready for <b>Burlington Resources</b> wellbore schematics.	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site	Bond No. on file with BLM s in a multiple completion of only after all requirements, <b>2&amp;A the subject we</b> <b>Visit was held on</b>	measured and M/BIA. Requi or recompletio , including rec	true vertical depths of all pertired subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure r/Bob Switzer, BLM F	e filed within 30 days 50-4 must be filed once and the operator has , current and propose
Attach the bond under which the v following completion of the involv Testing has been completed. Fina determined that the site is ready for <b>Burlington Resources</b> wellbore schematics.	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site	Bond No. on file with BLM s in a multiple completion of only after all requirements, <b>2&amp;A the subject we</b> <b>Visit was held on</b>	measured and M/BIA. Requisor recompletion including recompletion all per the 11/1/13 w	true vertical depths of all pertired subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure r/Bob Switzer, BLM F	e filed within 30 days 50-4 must be filed once 1 and the operator has 5, current and propose 7, Representative. The 1
Attach the bond under which the v following completion of the involv Testing has been completed. Fina determined that the site is ready for <b>Burlington Resources</b> wellbore schematics.	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site ched. A Closed Loop Sys	Bond No. on file with BLN s in a multiple completion of only after all requirements, 2&A the subject we Visit was held on tem will be used. Notify NMOCI Prior to begin Operation	measured and M/BIA. Requisor recompletion including recompletion all per the 11/1/13 w	true vertical depths of all pertired subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure r/Bob Switzer, BLM F	e filed within 30 days 50-4 must be filed once 1 and the operator has 6 current and propose 7 Representative. The 1 8 DIV DIST. 3
Attach the bond under which the v following completion of the involve Testing has been completed. Fina determined that the site is ready for <b>Burlington Resources</b> wellbore schematics. Vegetation Plan is atta	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site ched. A Closed Loop Sys	Bond No. on file with BLN s in a multiple completion of only after all requirements, <b>2&amp;A the subject we</b> Visit was held on tem will be used. Notify NMOCI Prior to begin operation	measured and M/BIA. Requisor recompletion including recompletion all per the 11/1/13 w	true vertical depths of all perti red subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure t/Bob Switzer, BLM F OIL CON NOV	e filed within 30 days 50-4 must be filed once 1 and the operator has 6 current and propose 7 Representative. The 8 DIV DIST. 3
Attach the bond under which the v following completion of the involve Testing has been completed. Final determined that the site is ready for <b>Burlington Resources</b> wellbore schematics. Vegetation Plan is atta	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site ched. A Closed Loop Sys	Bond No. on file with BLN s in a multiple completion of only after all requirements, <b>2&amp;A the subject we</b> Visit was held on tem will be used. Notify NMOCI Prior to begin operation	measured and M/BIA. Requisor recompletion, including rec all per the 11/1/13 w 0 24 hrs mning 15	true vertical depths of all perti red subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure t/Bob Switzer, BLM F OIL CON NOV	e filed within 30 days 50-4 must be filed once 1 and the operator has 6 current and propose 7 Representative. The 1 8 DIV DIST. 3 2.5 2013
Attach the bond under which the v following completion of the involve Testing has been completed. Final determined that the site is ready for <b>Burlington Resources</b> wellbore schematics. Vegetation Plan is atta	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site ched. A Closed Loop Sys	Bond No. on file with BLN s in a multiple completion of only after all requirements, <b>2&amp;A the subject we</b> <b>Visit was held on</b> tem will be used. <b>Notify NMOCI</b> <b>Prior to begin</b> <b>Operation</b> (ped)	measured and M/BIA. Requisor recompletion including recompletion including recompletion and the second second second second and the second sec	true vertical depths of all perti red subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure r/Bob Switzer, BLM F OIL CON NOV	<ul> <li>and the operator has</li> <li>current and propose</li> <li>current and propose</li> <li>cepresentative. The</li> <li>S. DIV DIST. 3</li> <li>2.5 2013</li> </ul>
Attach the bond under which the v following completion of the involve Testing has been completed. Final determined that the site is ready for Burlington Resources wellbore schematics. Vegetation Plan is atta	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site ched. A Closed Loop Sys	Bond No. on file with BLN s in a multiple completion of only after all requirements, <b>2&amp;A the subject we</b> Visit was held on tem will be used. Notify NMOCL Prior to begin Operation (ped) Title Re	measured and M/BIA. Requisor recompletion including recompletion including recompletion and the second second second second and the second sec	true vertical depths of all perti red subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure r/Bob Switzer, BLM F OIL CON NOV	e filed within 30 days 50-4 must be filed once 1 and the operator has 6 current and propose 7 Representative. The 1 8 <b>S. DIV DIST. 3</b> <b>2.5</b> 2013
Attach the bond under which the v following completion of the involve Testing has been completed. Final determined that the site is ready for Burlington Resources wellbore schematics. Vegetation Plan is atta	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site ched. A Closed Loop Sys is true and correct. Name (Printed/Ty, THIS SPACE FO I Signed: Stephen Mason ched. Approval of this notice does not ble title to those rights in the subject le	Bond No. on file with BLN s in a multiple completion of only after all requirements, P&A the subject we Visit was held on tem will be used. Notify NMOCI Prior to begin Operation (ped) Title Re Date R FEDERAL OR S	measured and M/BIA. Requisor recompletion including recompletion including recompletion and the second second second second and the second sec	true vertical depths of all perti red subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure r/Bob Switzer, BLM F OIL CON NOV	e filed within 30 days 50-4 must be filed once 1 and the operator has 6 current and propose Representative. The 8 DIV DIST. 3 2.5 2013
Attach the bond under which the v following completion of the involve Testing has been completed. Final determined that the site is ready for <b>Burlington Resources</b> wellbore schematics. Vegetation Plan is atta 14. I hereby certify that the foregoing is Denise Journey Signature Approved by Origina Conditions of approval, if any, are attact	work will be performed or provide the ved operations. If the operation results I Abandonment Notices must be filed or final inspection.) requests permission to P The Pre-Disturbance Site ched. A Closed Loop Sys is true and correct. Name (Printed/Ty, THIS SPACE FO I Signed: Stephen Mason ched. Approval of this notice does not ble title to those rights in the subject le ons thercon. 43 U.S.C. Section 1212, make it a cri	Bond No. on file with BLN s in a multiple completion of only after all requirements, P&A the subject we Visit was held on tem will be used. Notify NMOCI Prior to begin Operation (ped) Title Re Date R FEDERAL OR S	measured and M/BIA. Requisor recompletion, including recompletion, including recompletion, and the second second second second and the second	true vertical depths of all pertired subsequent reports must be n in a new interval, a Form 310 lamation, have been completed attached procedure t/Bob Switzer, BLM F OIL CON OIL CON NOV 'echnician 11/6/2013 FICE USE	e filed within 30 days 50-4 must be filed once 1 and the operator has current and propos Representative. The S. DIV DIST. 3 2.5 2013

. . . .

# ConocoPhillips CORNELL B 100 Expense - P&A

Long 108°3' 48.636" W

#### PROCEDURE

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.

2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.

Lat 36° 43' 49.08" N

3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.

4. RU blow lines from casing valves and begin blowing down casing pressure. Préssue test tubing to 1000 psi. Unseat pump. Kill well with water. TOH and lay down 3/4" rod string and pump. (See Pertinent Data Sheet)

Rods: Size: 3/4"

5. ND wellhead and NU BOPE. Function and pressure test BOP. Use a test range of 200-300 psi for a low pressure test and 1500 psi for a high pressure test. PU and remove tubing hanger.

6. TOOH with tubing (per pertinent data sheet). **Tubing:** Size: 2-3/8" 4.7 ppf J-55

Set Depth: 1,891'

1.888'

Set Depth:

Round trip with a 3-7/8" bit and watermelon mill to the top perf @ 1,652' or as deep as possible above the perfs.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ClassB/ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

7. Plug #1 (Perforations, Fruitland formation top: 1,297' - 1,606', 28 sacks Class B cement)

TIH and set 4-1/2" CR on tubing at 1,606'. Pressure test tubing to 1000 psi. Sting out of CR and load and circulate casing clean, pressure test casing to 800 psi. If casing does not test, cement plugs may need to be tagged as necessary. Mix 28 sx Class B cement and spot a balanced plug inside casing to isolate the perforations and Fruitland formation top. PUH.

4801


### 8. Plug #2 (Kirtland, Ojo Alamo tops: 490' - 740', 28 sacks Class B cement)


Mix 28 sx Class B cement and spot a balanced plug inside casing to isolate the Kirlland and Ojo Alamo Formation tops. POOH.

#### 9. Plug #3 (Surface casing shoe and surface; surface -190', 36 sacks Class B cement)

Note: TOC on production string @ 126' per CBL run 4/7/01. RIH with wireline and perf 3 HSC squeeze holes at 120'. TIH with tubing to 190'. Establish circulation through squeeze holes. Mix 36 sxs Class B cement. Sqz Class B cement into HSC holes and circulate cement to surface through bradenhead to isolate the surface casing & bradenhead. Shut in well and WOC. Tag cement top and top out cement as necessary.

10. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.





# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 100 Cornell B

## **CONDITIONS OF APPROVAL**

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

a) Bring Ojo Alamo & Kirtland plug to 480' (740'-480')

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.