

Office Energy, Minerals and Nati	exico Form C-103 ural Resources Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283	WELL API NO.	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION	5 Indicate Type of Lease	
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	ncis Dr. STATE \boxtimes FEE \square	
<u>District IV</u> – (505) 476-3460 Santa Fe, NM 8	o. State office Gus Ebuse 140.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	E-291-3	
SUNDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) F PROPOSALS.)	OR SUCH	
1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other	8. Well Number 201	
2. Name of Operator	9. OGRID Number 241333	
Chevron Midcontinent L.P. 3. Address of Operator	10. Pool name or Wildcat Largo Gallup	
Attn: Regulatory Specialist 332 Road 3100 Aztec NM 87410	(8000)	
4. Well Location		
Unit LetterG_:1690_feet from theN line and	1725feet from theEline	
Section 2 Township 26N Range 7W	NMPM County Rio Arriba, NM	
11. Elevation (Show whether DF 6661' GL		
12. Check Appropriate Box to Indicate Nat	ure of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲	REMEDIAL WORK	
TEMPORARILY ABANDON		
PULL OR ALTER CASING	CASING/CEMENT JOB OIL CONS. DIV DIST. 3	
DOWNHOLE COMMINGLE 🛛 DHC 2355-A		
CLOSED-LOOP SYSTEM	JUN 1 2 2014	
	pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMA		
proposed completion or recompletion.		
Job Scope – Complete the Largo Gallup and Install Artificial Lift . Procedure:	wellback MULDON's Tac for fill with we detained DOOU with taking the	
MIRU workover rig. MIRU BOP tester. Test BOP's. Spot and fill frac tanks. ND down tubing order out new or vellow hand $2-3/8^{\circ}$ to be used as production st		
	down tubing order out new or yellow band 2-3/8" to be used as production string. PU workstring. PU and RIH with bit and watermelon mill on workstring. I CO to 7562'. Proposed perforations are 6760'-6775'. POOH and lay down bit and watermelon mill. MIRU wireline unit. PU and RIH with	
CBP on wireline .Run CCL and set CBP @ ~ 6860' (100' below proposed perforations). Correlate to GR/CCL logs. Perforate – proposed perforations		
	ations). Correlate to GR/CCL logs. Perforate – proposed perforations	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 516	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 516 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 516	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout.	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5163 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24 hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA.	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5163 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24 hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosion	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5163 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24 hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosion casing chase each with 5 bbls of water. RIH with pump on rod string. Space o	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5163 equipment. MIRU Frac company . Frac. RDMO frac equipment. Flow well baboms on slick line for 24 hr test. SI well for 24 hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosion casing chase each with 5 bbls of water. RIH with pump on rod string. Space o clean location. Install pumping unit. Turn well over to production.	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5163 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24 hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosion casing chase each with 5 bbls of water. RIH with pump on rod string. Space o	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and CBL and submit to ascencies prior to perfocutions	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5163 equipment. MIRU Frac company . Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24 hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosior casing chase each with 5 bbls of water. RIH with pump on rod string. Space o clean location. Install pumping unit. Turn well over to production. Fractor Spud Date: 11/06/1973 Rig Release D	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and CBL and submit to ascencies prior to perfocutions ate:	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5163 equipment. MIRU Frac company . Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosion casing chase each with 5 bbls of water. RIH with pump on rod string. Space o clean location. Install pumping unit. Turn well over to production. μ Rig Release D I hereby certify that the information above is true and complete to the b	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH a inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and CBL and submit to asencies prior to perfocutions ate:	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5162 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosior casing chase each with 5 bbls of water. RIH with pump on rod string. Space o clean location. Install pumping unit. Turn well over to production. Spud Date: 11/06/1973 Rig Release D	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and CBL and submit to ascencies prior to perfocutions ate:	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5163 equipment. MIRU Frac company . Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosion casing chase each with 5 bbls of water. RIH with pump on rod string. Space o clean location. Install pumping unit. Turn well over to production. μ Rig Release D I hereby certify that the information above is true and complete to the b	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and CBL and submit to ascencies prior to perfocutions rate:	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5162 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosior casing chase each with 5 bbls of water. RIH with pump on rod string. Space o clean location. Install pumping unit. Turn well over to production. Spud Date: 11/06/1973 Rig Release D I hereby certify that the information above is true and complete to the b SIGNATURE April E. Pohl E-mail address: April.Pohlo For State Use Only	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH a inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and CBL and submit to asencies prior to perfocutions ate:	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5162 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosior casing chase each with 5 bbls of water. RIH with pump on rod string. Space o clean location. Install pumping unit. Turn well over to production. Kan Spud Date: 11/06/1973 Rig Release D I hereby certify that the information above is true and complete to the b SIGNATURE April E. Pohl E-mail address: April.Pohlo For State Use Only	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH a inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and CBL and submit to ascencies prior to perfocutions ate:	
6760'-6775'. RDMO wireline unit. TIH with 2-7/8' frac liner and set from 5162 equipment. MIRU Frac company. Frac. RDMO frac equipment. Flow well ba bombs on slick line for 24 hr test. SI well for 24hrs. TIH with workstring and re Clean out to CBP, drill out CBP and attempt to cleanout to PBTD of 7562'. If s with workstring. RIH with production tubing and BHA. ND BOP and NU wellhead. Rig up Rig up Baker and pump ½ drum of corrosior casing chase each with 5 bbls of water. RIH with pump on rod string. Space o clean location. Install pumping unit. Turn well over to production. Spud Date: 11/06/1973 Rig Release D I hereby certify that the information above is true and complete to the b SIGNATURE April E. Pohl E-mail address: April.Pohlo For State Use Only	ations). Correlate to GR/CCL logs. Perforate – proposed perforations 3'-5365'. NU frac mandrel and install frac head or Y. MIRU flow back ck for 24 hrs or until well dies. MIRU slick line. PU and RIH with pressure lease frac liner. POOH with frac liner. MIRU air/foam unit for cleanout. cale is present during cleanout out consider an acid treatment. POOH a inhibitor down the tubing and ½ drum of corrosion inhibitor down the ut pump. Seat pump, load tubing and test. RDMO workover rig and CBL and submit to asencies prior to perfocutions ate:	



Prepared by: Date: Jamie Elkington

Revised by: Date:





Prepared by: Date: Jamie Elkington Revised by: Date: