Form 3160-5 September 2001)	UNITED STATES	L' Line	الاستا المسلم		FORM APPROVED OM B No. 1004-0135 Expires: January 31, 2004
1	DEPARTMENT OF THE I BUREAU OF LAND MANA				
SUNDR	Y NOTICES AND REPO		IN TT	21 15: Lease Serial JICARIL	INO. ILA CONTRACT 396
Do not use	this form for proposals to	drill or to re÷ente	r.an(=).	6. If-Indian,	Allottee or Tribe Name
abandoned	well. Use Form 3160-3 (Al	PD) for such propos	als.	JICARIL	L APACHE NATION
SUBMIT IN T	RIPLICATE- Other instru	ictions on reverse .	side.	7. If Unit or C	CA/Agreement, Name and/or
1. Type of Well Oil Well	Gas Well			8. Well Name	e and No.
2. Name of Operator SHORELINE OIL & GAS COMPANY			APACHE HILLS #3 9. API Well No.		
3a. Address	3b. Phone No. (include area			30-039-21600	
PO BOX 3470, FARMINGT	505-327-6908			Pool, or Exploratory Area	
	c., T., R., M., or Survey Description)			11. County or	
990' FSL & 790' FEL SEC.	7 T. 23N, R. 3W				RIBA COUNTY, NM
				- 	
	APPROPRIATE BOX(ES) TO I			REPORT, OR	UTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	7	(Start/Resume)	Water Shut-Off
— 3	Alter Casing	Fracture Treat	Reclamation	l I	Well Integrity
Subsequent Report	Change Plans	New Construction	Recomplete Temporarily	Abandon]Other
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dispos		i
Attach the Bond under whic following completion of the testing has been completed.	lirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil	give subsurface locations and the Bond No. on file with E sults in a multiple completion	d measured and BLM/BIA. Req n or recompletion	I true vertical depths uired subsequent rep on in a new interval,	ports shall be filed within 30 d a Form 3160-4 shall be filed o
Attach the Bond under whic following completion of the testing has been completed. determined that the site is re	lirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING	give subsurface locations and the Bond No. on file with E sults in a multiple completion led only after all requirements	d measured and BLM/BIA. Req n or recompletions, including rect	I true vertical depths uired subsequent rep on in a new interval, lamation, have been	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed completed, and the operator h
Attach the Bond under whic following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI	lirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY.	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements GOF WELL. A-PLUS W	d measured and BLM/BIA. Req a or recompletic s, including recl AS THE COI	I true vertical depths uired subsequent rep on in a new interval, lamation, have been	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed completed, and the operator h
Attach the Bond under whic following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI	lirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY.	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements GOF WELL. A-PLUS W	d measured and BLM/BIA. Req a or recompletic s, including recl AS THE COI	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed completed, and the operator h
Attach the Bond under whic following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI	lirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY.	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements GOF WELL. A-PLUS W	d measured and BLM/BIA. Req a or recompletic s, including recl AS THE COI	i true vertical depths uired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE	of all pertinent markers and z xorts shall be filed within 30 d a Form 3160-4 shall be filed completed, and the operator h ROVIDE THE REPORT
Attach the Bond under whic following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI	lirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY.	give subsurface locations and the Bond No. on file with E sults in a multiple completion led only after all requirements	d measured and BLM/BIA. Req a or recompletic s, including rect AS THE COI	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE JUN FARMINGT	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed completed, and the operator h ROVIDE THE REPORT
Attach the Bond under whic following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI	lirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY.	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements GOF WELL. A-PLUS W	d measured and BLM/BIA. Req a or recompletic s, including rect AS THE COI	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE JUN	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed of completed, and the operator h ROVIDE THE REPORT CO FOR RECORD 1 6 2014
Attach the Bond under whic following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI	lirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY.	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements GOF WELL. A-PLUS W	d measured and BLM/BIA. Req a or recompletic s, including rect AS THE COI	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE JUN FARMINGT	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed of completed, and the operator h ROVIDE THE REPORT CO FOR RECORD 1 6 2014
Attach the Bond under which following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI SHORELINE OIL & G	directionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY. (0)	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements GOF WELL. A-PLUS W	d measured and BLM/BIA. Req n or recompletic s, including recl AS THE COI	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE JUN FARMINGT	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed completed, and the operator h ROVIDE THE REPORT TO FOR RECORD 1 6 2014
Attach the Bond under which following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI SHORELINE OIL & G	tirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY. (0) (0) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements OF WELL. A-PLUS W L CONS. DIV DIS7 JUN 18 2014 Title PRES Date	d measured and BLM/BIA. Req n or recompletic s, including recl AS THE COI T 3 IDENT	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE JUN FARMINGT BY: 06/10/2014	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed completed, and the operator h ROVIDE THE REPORT TO FOR RECORD 1 6 2014
Attach the Bond under which following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI SHORELINE OIL & G 14. Thereby certify that the fa Name (<i>Printed/Typed</i>) TERESA D. M	directionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY. (0)	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements OF WELL. A-PLUS W L CONS. DIV DIS7 JUN 18 2014 Title PRES Date	d measured and BLM/BIA. Req n or recompletic s, including recl AS THE COI T 3 IDENT	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE JUN FARMINGT BY: 06/10/2014	of all pertinent markers and z ports shall be filed within 30 d a Form 3160-4 shall be filed of completed, and the operator h ROVIDE THE REPORT CO FOR RECORD 1 6 2014
Attach the Bond under which following completion of the testing has been completed. determined that the site is re ATTACHED ARE THIS SHORELINE OIL & G 14. Thereby certify that the for Name (<i>Printed/Typed</i>) TERESA D. M Signature	tirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) E DETAILS OF THE PLUGGING (AS COMPANY. (0) (0) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements OF WELL. A-PLUS W L CONS. DIV DIS7 JUN 18 2014 Title PRES Date	d measured and BLM/BIA. Req n or recompletic s, including recl AS THE COI T 3 IDENT	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE JUN FARMINGT BY: 06/10/2014	of all pertinent markers and z xorts shall be filed within 30 d a Form 3160-4 shall be filed of completed, and the operator h ROVIDE THE REPORT D FOR RECORD 1 6 2014 FON FIELD OFFICE Salvers
Attach the Bond under which following completion of the testing has been completed. determined that the site is re ATTACHED ARE THI SHORELINE OIL & G 14. I hereby certify that the for Name (<i>Printed/Typed</i>) TERESA D. M Signature Signature Conditions of approval, if any, a	tirectionally or recomplete horizontally, h the work will be performed or provide involved operations. If the operation re Final Abandonment Notices shall be fil ady for final inspection.) EDETAILS OF THE PLUGGING AS COMPANY. (0) CAS COMPANY. (0) COMPANY. (1) COMPA	give subsurface locations and e the Bond No. on file with E sults in a multiple completion led only after all requirements COF WELL. A-PLUS W L CONS. DIV DIST JUN 18 2014 Title PRES Date EDERAL OR STAT	d measured and BLM/BIA. Req n or recompletic s, including recl AS THE COI T 3 IDENT TE OFFIC	I true vertical depths juired subsequent rep on in a new interval, lamation, have been MPANY THAT P ACCEPTE JUN FARMINGT BY: 06/10/2014 E USE	of all pertinent markers and z xorts shall be filed within 30 d a Form 3160-4 shall be filed of completed, and the operator h ROVIDE THE REPORT D FOR RECORD 1 6 2014 FON FIELD OFFICE Salvers

:

l t

NMOCD \sim

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

M&M Productions/Shoreline Oil & Gas Company Apache Hills #3 May 5, 2014 Page 1 of 2

900' FSL and 790' FEL, Section 7, T-23-N, R-3-W Rio Arriba County, NM Lease Number: Jicarilla Contract 396 API #30-039-21600

Plug and Abandonment Report Notified NMOCD and BLM on 4/25/14

Plug and Abandonment Summary:

- Plug #1 with 50 sxs (59 cf) Class B cement with 2% CaCl inside casing from 3272' to 2613' to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops. Tag TOC at 2675'. ✓
- Plug #2 with CR at 1654' spot 49 sxs (57.82 cf) Class B cement inside casing from 1698' to 1258' with 4 sxs under; 30 sxs above and 15 sxs into annulus to cover the Nacimiento top. Tag TOC at 1278'.√
- Plug #3 with 16 sxs (18.88 cf) Class B cement inside casing from 189' to surface to cover the surface casing shoe. ✓
- Plug #4 with 40 sxs Class B cement found cement at surface and top off with poly pipe and install P&A marker.✓

Plugging Work Details:

- 4/29/14 Rode rig and equipment to location. Spot in and RU. Check well pressures: tubing and casing 12 PSI, bradenhead 0 PSI. RU relief lines. Screw on 8-5/8" flange. NU BOP and function test. Change out pipe rams. SI well. SDFD.
- 4/30/14 Travel to location. Check well pressures: tubing, casing and bradenhead 10 PSI. TOH and LD all tubing. No tally needed, OK by Bill Keetso, M&M rep. X-over from 1-/4" to 2-3/8" tubing equipment. PU GR 3-5/8" and RIH to 3300. POH. PU 4.5" CIBP and set at 3272'. PU 105 and tally A-Plus workstring 2-3/8", 4.7#, J-55, EUE, tag CIBP at 3272'. LD 1 jnt EOT at 3269'. Establish circulation. Attempt to pressure test casing to 800 PSI, no test. Pressured up to 600 PSI, lost 600 PSI in less than 20 seconds. Note: open pit will retest pressure when BLM rep is on location. SI well. SDFD.
- 5/1/14 Open up well; no pressures. RU A-Plus wireline. PU logging tool. Rand CBL from 3272' to surface, TOC at 2356' with surface ratty cement from 1432' to surface. Establish circulation. Attempt to pressure test casing to 800 PSI, no test. Lost 600 PSI in less than 20 seconds. Spot plug #1 with calculated TOC at 2613'. WOC. TIH and tag TOC at 2675'. Establish circulation. Attempt to pressure test casing to 800 PSI, no test. Lost 600 PSI in less than 20 seconds. Spot plug #1 with calculated TOC at 2613'. WOC. TIH and tag TOC at 2675'. Establish circulation. Attempt to pressure test casing to 800 PSI, no test. Lost 600 PSI in less than 20 seconds. Open casing. Sting into CR. Pump and establish rate of 1 bpm at 950 PSI. Spot plug #2 with calculated TOC at 1258'. SI well. SDFD.
- 5/2/14 Open up well; no pressures. TIH and tag, TOC at 1278'. Establish circulation. Attempt to pressure test casing to 800 PSI, no test lost 600 PSI in less than 20 seconds. Establish circulation. Spot plug #3 with TOC at surface. ND BOP. Dig out wellhead. Fill out Hot Work Permit. Monitor well for gas, no LEL. Cut off wellhead. Tag TOC at 20'. Spot plug #4 top off with poly pipe and install P&A marker. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

M&M Productions/Shoreline Oil & Gas Company Apache Hills #3 May 5, 2014 Page 2 of 2

Plugging Work Details (continued):

1.2

. .

5/1/14 Travel to location. RD and rode rig and equipment to A-Plus yard.

Bill Keetso, M&M representative, was on location. Bryce Hammond, Jicarilla BLM representative, was on location. ✓