

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ARP Production Company, LLC	Contact	Randy L. Madison
Address	309 Silver St., Raton, NM 87740	Telephone No.	Office 575-445-6706 Cell 575-420-1120
Facility Name	A-575	Facility Type	Gas Well

Surface Owner	Vermejo Park Ranch	Mineral Owner	APR Production Company, LLC	API No.	30-007-20984
---------------	--------------------	---------------	-----------------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	27	32N	19E	1510	North	368	West	Colfax

Latitude N 36 58 58.1 Longitude W 104 55 00.3

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	7 Barrels	Volume Recovered:	0
Source of Release	Wet tubing and hose connection coming loose	Date and Hour of Occurrence	8-12-14 @ 1323	Date and Hour of Discovery	8-12-14 @ 1323
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Daniel Sanchez		
By Whom?	Randy Madison	Date and Hour	8-12-14 @ 1340		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RCVD AUG 21 '14

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV.

DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

Tubing was being tripped out of the well during maintenance. This was wet tubing with a hose connecting it to a water truck. The connection came loose letting the water spill on to the ground. The hose was connected back together and they will monitor the connections in the future.

Describe Area Affected and Cleanup Action Taken.*

Not able to recover any of the water. The area will be monitored for TDS staining and soil excavated if need be.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Randy L. Madison		Approved by Environmental Specialist: 	
Title: EHS Specialist		Approval Date: 8/26/14	Expiration Date:
E-mail Address: rmadison@atlasenergy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/13/14	Phone: 575-445-6706	Tak Soil Samples 8021B 8015	

* Attach Additional Sheets If Necessary

NES 142384 0322 3 300.1