District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

						OPERATOR Initial Report						Final	l Report	
Name of Co	mpany: E	Energen Reso		Contact: Ed Hasely										
Address:			lace, Fari	nington, NM 87	Telephone No.: (505) 324-4131									
Facility Nar	ne: Sun	Facility Type: Oil / Gas Well												
Surface Ow	ner: Feder	al	Federal	API No.: 3004525707										
				LOCA	TIO	N OF REI	FACE						-	
Unit Letter	Section	Township	Range	Feet from the		n/South Line	Feet from the	Fast/\	West Line	County				
					1,010	rooun zine		i Dustr	West Eme	County				
C 34 29N 11W 330 Nort						1	1080	West		San Juan				
				Latitude36.6	<u>68810</u>	Longitude	-107.98026						•	
				NAT	URI	OF REL	EASE							
Type of Rele			Release: No Rel			Recovered:		· 						
Source of Re	lease: Sepa	arator		Date and Hour of Occurrence: Date and Hour of Discovery:										
Was Immedia	ata Notica (Given?		11/1/13; 12:30 pm										
was illineur	ate Notice (Yes [] No ☐ Not Re	If YES, To Whom? Brandon Powell - OCD Mark Kelly - BLM (left message)									
By Whom?	Ed Hasely			Date and Hour: 11/1/13; 1:30 pm										
Was a Water		ched?			lume Impacting t		ercourse.	NA						
			No .											
If a Watercou	ırse was Im	pacted, Descri	be Fully.	NA NA		"		÷		DOUG NO	1161	19		
RCVD NOV 6 '13														
OIL CONS. DIV.														
		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,								DIST	. ฮ			
Describe Cau	se of Probl	em and Remed	dial Actio	n Taken.*										
Investigation	s point to o	il getting into	the fuel g	as line on the sepa	rator a	nd catching fir	e when the oil go	t to the	pilot light.	The fuel gas	line w	as shut	t in	
	Investigations point to oil getting into the fuel gas line on the separator and catching fire when the oil got to the pilot light. The fuel gas line was shut in and a fire extinguisher was used to put the fire out.													
Describe Are	Describe Area Affected and Cleanup Action Taken.*													
Daniel Gran														
Damage from	Damage from the fire was limited to the flame arrester on the separator.													
	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability														
or the environ	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state,	or local la	ws and/or regu	ılations.										•	
	Cal	, ,					OIL CON	<u>SERV</u>	<u>'ATION</u>	DIVISIO	<u>N</u>	,		
Signature:	2/1	tase m-		•			^		.) .	al				
						Approved by	Environmental S	necialis	م کے ا)/,[ll ₁		
Printed Name	e: Ed Hase	ely				. ippiored by	Z romnomar o	Pecialis		W(V/-	W	M		
Title: Sr. Er	vironmenta	al Engineer	Approval Da	te: B/27/00	H	V Expiration	Date:		0					
F-mail Adde	aggr ad hoo	sely@energen.	com			Conditions o	f Approval:				_			
E-man Audit	.55. Cu.1145	ory (a) energen.				Conditions 0	·	,		Attached				
Date: 11. * Attach Addi	/1/13	ete If Nesses		one: (505) 330-35	84		40/11/	- 0-						
Auach Addi	nonal Sne	ets II Necess	ai y	•		•	NJK142	575	5337	10				