Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OIL	CONS.	DIV	DIST.	6
-----	-------	-----	-------	---

FORM APPROVED OMB No. 1004-0137

OMB NO. 10	JU4-	0137
Expires: July	31,	201

NUV

SF-080713

	SUNDRY NOTICES AND REPORTS ON WELLS			6. If Indian, Allottee or Tribe Name	
		posals to drill or to re-ente		٠ ،	
abandoned	well. Use Form 31	160-3 (APD) for sùch propo	osäls.)	
su	BMIT IN TRIPLICATE -	Other instructions on page 2.	7. If U	Jnit of CA/Agreement, N	ame and/or No.
. Type of Well		CIT	28 20 4	San	Juan 30-6 Unit
Oil Well	Gas Well	Other		Il Name and No.	
		F. C. wasses		າ San Jua	n 30-6 Unit 438S
. Name of Operator		Estate Child	عَلَيْهِ اللهُ الله	I Well No.	
	ton Resources Oil	& Gas Company LP		30-1	39-27752
Ba. Address		3b. Phone No. (include are		eld and Pool or Explorat	ory Area
PO Box 4289, Farmington, NM 87499 (505) 326-9700					Basin FC
Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State					
Surface UL O (S)	WSE), 1260' FSL &	. 715' FEL, Sec. 12, T30N, F	₹6₩	Rio Arriba	, New Mexico
12. CHECK T	HE APPROPRIATE I	BOX(ES) TO INDICATE NATU	RE OF NOTICE.	REPORT OR OTH	ER DATA
TYPE OF SUBMISSION		TYF	PE OF ACTION	1	
TYPE OF SUBMISSION X Notice of Intent	Acidize	TYF	PE OF ACTION	ion (Start/Resume)	Water Shut-Off
	Acidize Alter Casing		PE OF ACTION	ion (Start/Resume)	
	 	Deepen	PE OF ACTION	ion (Start/Resume)	Water Shut-Off
X Notice of Intent	Alter Casing	Deepen Fracture Treat	PE OF ACTION Product Reclama	ion (Start/Resume)	Water Shut-Off Well Integrity
X Notice of Intent	Alter Casing Casing Repair	Deepen Fracture Treat New Construction X Plug and Abandon	PE OF ACTION Product Reclama	ion (Start/Resume) ation olete arily Abandon	Water Shut-Off Well Integrity

Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Burlington Resources requests permission to P&A the subject well bore per the attached procedure, current & proposed well bore schematics. No Onsite was conducted an there is not a revegetation plan as this is a FEE surface well. A closed loop system will be utilized for this P&A.

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS Notify NMOCD 24 hrs Prior to beginning operations



H₂S POTENTIAL EXIST

SEE ATTACHED FOR CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)		
Kenny Davis	Title	Staff Regulatory Technician
Signature	Date	10/28/2014
	DERAL C	OR STATE OFFICE USE
Approved by Troy Salvers		Title Petroleum Eng. Date 10/29/2014
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office FFO
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any	y person kno	owingly and willfully to make to any department or agency of the United States any

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ConocoPhillips SAN JUAN 30-6 UNIT 438S Expense - P&A

Lat 36° 49' 23.916" N

Long 107° 24' 34.668" W

PROCEDURE

This project requires the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact the Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well as necessary. Ensure well is dead or on a vacuum.
- 4. TOOH w/ rod string and LD (per pertinent data sheet).

Size:

3/4"

Set Depth:

3,118

ft

- 5. ND wellhead and NU BOPE. Pressure and function test BOP to 250 psi low and 1000 psi over SICP high to a maximum of 2000 psi held and charted for 10 minutes as per COP Well Control Manual. PU and remove tubing hanger
- TOOH with tubing (per pertinent data sheet).

Tubing size:

2-3/8"

4.7# J-55 EUE

Set Depth:

3139

ftKB

KB:

12 ft

- 7. PU 6-1/4"" bit and watermelon mill and round trip as deep as possible above drop off liner top (2798')'.
- 8. PU 7" cement retainer on tubing, and set 2798'. Pressure test tubing to 1000 psi. Sting out of CR. Load hole, and pressure test casing to 800 psi. If casing does not test, then spot or tag subsequent plugs as appropriate. POOH w/ tubing.
- 9. RU wireline and run CBL with 500 psi on casing from cement retainer to surface to identify TOC. Adjust plugs as necessary for new TOC.

All cement volumes use 100 excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Class B mixed at 15.6 ppg with a 1.18 cf/sk yield.

Sec COA

10. Plug 1 (Fruitland, Kirtland, and O p Alamo Formation Tops, 2215-2798', 122 Sacks Class B Cement)

Mix cement as described above and spot balanced plug to isolate the Fruitland, Kirtland, and Ojo Alamo Formation Tops as well as the Fruitland perforations and liner top. Pull up hole.


See COA 11. Plug 2 (Nacimiento Formation Top, 1098-1198', 29 Sacks Class B Cement)


Mix cement as described above and spot balanced plug to isolate the Nacimiento Formation Top. Pull up hole.

12. Plug 3 (Surface Plug, 0-185', 46 Sacks Class B Cement)

Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 psi. Note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix 46 sx Class B cement and spot balanced plug inside casing from 185' to surface, circulating good cement out casing valve. TOOH and LD tubing. SI well and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface, filling the casing and the BH annulus to surface. Shut well in and WOC.

13. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.





UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: San Juan 30-6 Unit #438S

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Bring the top of plug #1 to 2117 ft. to cover the Fruitland, Kirtland and Ojo Alamo tops. Adjust cement volume accordingly
 - b) Set plug #2 (1007-907) ft. to cover the Nacimiento top.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: tsalyers@blm.gov Brandon.Powell@state.nm.us

Note: Low concentrations of H2S (24ppm GSV) have been reported in the NW/SE of section 11, 30N, 6W.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.