

District I*
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Lindsay Dumas
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 599-4089
Facility Name: San Juan 29-7 66A	Facility Type: Gas

Surface Owner: BLM	Mineral Owner: SF-078399	API No. 3003925664
---------------------------	---------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter F	Section 22	Township 29N	Range 7W	Feet from the 2040	North/South Line FNL	Feet from the 2175	East/West Line FWL	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	------------------------------	--------------------------------	------------------------------	------------------------------	-----------------------------

Latitude 36.71324 Longitude -107.55966

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release 250 MCF	Volume Recovered 0
Source of Release Rupture Disk on Separator	Date and Hour of Occurrence 12/17/14 12:14 AM	Date and Hour of Discovery 12/18/14 10:20 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Vendor noticed separator was leaking gas from rupture disk, notified MSO and shut the inlet ball valve. MSO arrived on location to find the low side vessel has blown out.



OIL CONS. DIV DIST. 3

JAN 08 2015

Describe Area Affected and Cleanup Action Taken.*

Install new rupture disc.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lindsay Dumas	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 2/6/15	Expiration Date:
E-mail Address: Lindsay.Dumas@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/29/2014	Phone: (505) 599-4089	

* Attach Additional Sheets If Necessary

#NCS 1503751 692

①