Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT♥♥

		-								1
-	M.	63	D. A. H	1-7				رش	ũ	7
, ,	į	r g	In C	1	021	亾	775	1)	E	1
•	l n	¥ !	11 3	1	HĀS	1	114	H	ű,	k.
T	(-7	1	57.74	ñ	5 14	· /1	5 75	il.	ëi i	711

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

Lease Serial No. NMNM 100807

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indi	an, Allottee or Tribe Name	
N/A		
. 3		
37		

SUBMI	TIN TRIPLICATE – Othe	r instructions on page 2.		1300	ment, Name and/or No.		
1. Type of Well		APR 01	2015	R-13857-A			
☐ Oil Well	'ell Other			8. Well Name and No. Pinion Unit D14-2410	0 02H		
2. Name of Operator Encana Oil & Gas (USA) Inc.		Farmington Fie	eld Office	9: API Well No. 30-045-35530			
3a. Address		3b. Phone No. The Alde and M	anagemer	10. Field and Pool or E	xploratory Area		
370 17th Street, Suite 1700 Denver, CO 80202		720-876-5867	,	Pinion Unit HZ (Oil)			
4. Location of Well (Footage, Sec., T., SHL: 1348' FNL and 436' FWL Section 14, T24	R.,M., or Survey Description	n)		11. County or Parish. State			
BHL: 2228' FNL and 292' FEL Section 16, T24				San Juan County, NM			
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	E OF NOTIO	CE, REPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION		Т	PE OF ACT	ION			
Notice of Intent	Acidize	Decpen	Prod	uction (Start/Resume)	Water Shut-Off		
Thorice of finein	Alter Casing	Fracture Treat	Reclamation		☐ Well Integrity		
Subsequent Report	Casing Repair			omplete	Other		
Subsequent report	Change Plans			porarily Abandon	Cement Remediation		
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Wate	er Disposal			
13. Describe Proposed or Completed O the proposal is to deepen direction	ally or recomplete horizonta	lly, give subsurface locations and	l measured a	nd true vertical depths of	f all pertinent markers and zones.		

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Please see attached sheet detailing the proposed cement remediation work to be performed on the Pinion Unit D14-2410 02H.

OIL CONS. DIV DIST. 3

APR 1 3 2015

CONDITIONS OF APPROVAL

Adhere to previously issued stipulations

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct. Name (Printed Typed)	
Cristi Bauer	Title Operations Technician
Signature CRDi BAUTR	Date 3/31/15
THIS SPACE FOR FEE	DERAL OR STATE OFFICE USE
Approved by William Tambekon	Title Petroleum Engineer Date 4-2-15
Conditions of approval, if any, are attached. Approval of this notice does not warrant of that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	or certify U

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Pinon Unit D14-2410 02H

API: 30-045-35530

Cement Remediation Procedure

Formation Tops: Ojo Alamo- 798' MD Pictured Cliffs- 1633' MD

- 1. DO frac plugs
- 2. Pull 4.5" frac string
- 3. MIRU Basin Wireline, RIH and set RBP in 7" intermediate CSG @ 2,000'. Dump 2 sxs sand on top of RBP
- 4. RIH w/ perf guns. Perf 4 holes @ 1620'. Establish circulation through squeeze holes to surface
- 5. PU Halliburton 7" packer and set @ 1100'
- 6. MIRU Halliburton cmt crew while RIH w/ packer
- 7. Pump 10 bbls fresh water to establish injection. Mix and pump: 360 sxs SqueezeCem 15.8 ppg cmt.
- 8. Displace w/ fresh water
- 9. Call NMOCD and BLM with update and WOC for 24 hours.
- 10. TIH w/ mill and scrapper and DO cmt. TOH with mill and scrapper
- 11. Pressure test to 1000# for 30min
- 12. If no cement returns RU Basin Wireline and run CBL
- 13. Call NMOCD and BLM with update
- 14. RIH with retrievable tool on 2 7/8" tbg @ 7" RBP @ 2000'. Circulate sand out. Release and TOH with RBP.
- 15. TIH with 2 3/8" & 2 7/8" production string with gas lift valves per gas lift install procedure.