Form 3160-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: October 31 20

SUNDRY NOTICES AND REPORTS ON WELLSRECEIVED

5. Lease Serial No. SF- 081100 - A

Do not use this form for proposals to drill or to abandoned well. Use Form 3160-3 (APD) for su		
SUBMIT IN TRIPLICATE – Other instructions of		
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Other ☐	Farmington Field Office 8. Well Name and No. Bureau of Land Manages Ram #2 FC	
2. Name of Operator Running Horse Production Company 9. API Well No. 3004528598		
3a. Address 3b. Phone No 14933 Hwy 172, P.O. Box 369 Ignacio, CO 81137 970-563-515	. (include area code) 10. Field and Pool or Exploratory Area Basin Fruitland Coal	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)	11. County or Parish, State	
995' FNL, 800' FEL, Sec 8, T26N, R12W, SWNENE	San Juan County	
12. CHECK THE APPROPRIATE BOX(ES) TO INI	DICATE NATURE OF NOTICE, REPORT OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Other Casing Repair New Construction Plug and Abandon Temporarily Abandon Temporarily Abandon Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Plug & Abandon well according to attached P&A procedure. Work planned for October 2015.		
OIL CONS. DIV DIST. 3		
JUL 22 2015 SEE ATTACHED FOR CONDITIONS OF APPROVAL	BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)		
Cindy Lewis	Title Senior Petroleum Engineer	

This space for Federal or State Office USE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office C

Date 7 17 2015

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Signature

Approved by

Walsh Engineering and Production

P & A Procedure for Running Horse Production Co. Ram #2

Location: NE/4 Sec 8 T26N R12W

San Juan County, NM API: 30-045-28598

Date: July 7, 2015

Field: Basin Fruitland Coal Elev: GL 5967'

Surface: BLM Minerals: BLM SF - 081100-A

4-1/2" @ 1922' PBTD: 1258' KB

FTC Perfs: 1161' - 1170'

Procedure:

- Move on location and rig up a well service unit. Hold a safety meeting and explain the procedure to the crew.
- Pull and lay down the polished rod and liner, 4' and 8' pony rods, 43 $\frac{3}{4}$ " rods (15 with guides), three 1-1/4" sinker bars, and a 2" X 1-1/2" X 10' 2. RWAC pump. Nipple down the well head and nipple up the BOP. Lay down 1168' (36 joints) of 2-3/8" tubing.
- Nipple down the BOP and remove the tubinghead. Screw a 4-1/2" X 2" swedge 3. directly to the 4-1/2" casing. Install a 2" ball valve to the top of the swedge.
- Load the casing and establish an injection rate into the Fruitland Coal 4. perfs with 25 bbls of fresh water. Mix and pump 100 sx (118 cu.ft.) of neat cement. Add 10 #/sk celloflake and drop 50 7/8" ball sealers in the first 4 bbls of cement. Continue pumping cement until the well holds 500 psi pressure. Close the ball valve on the swedge and WOC overnight.
- Cut the wellhead off 4' below the ground level. Install a dryhole marker with a weep hole. Reclaim location as per surface owner specifications.

Paul C. Thompson, P.E.

RED WILLOW PRODUCTION CO.

Proposed Wellbore

Name: Ram #2

API #: 3004528598

Date: 16-Jul-15

Spud Date: 11/8/1991

Status: SI

Location: NE/4 S. 8, T26N - R12W


County, State: San Juan, NM

TD: 1300'

PBTD: 1258'

GL: 5967'

KB:



Tops:

Fruitland

983'

Pictured Cliffs:

1,187'

7/19/1994 PC, replace 300' tbg

11/28/1994 HIT; no mention of replacing pump

10/4/1995 HIT; no mention of replacing pump

12/26/2001 replace tbg string, new pump.

2/4/2002 HIT; no mention of replacing pump

12/15/2004 pump change

8/21/2008 tag fill 11' under EOT; press test tbg 500#; plan on clean out to PBTD w/bailer next day, but no report

RED WILLOW PRODUCTION CO.

Current Wellbore

Name: Ram #2

API #: 3004528598 Spud Date: 11/8/1991 Date: 18-Jul-12


Status: Marginal Prod

TD: 1300'

PBTD: 1258'

Location: NE/4 S. 8, T26N - R12W

County, State: San Juan, NM



Tops:

Fruitland

983'

Pictured Cliffs:

1,187'

7/19/1994 PC, replace 300' tbg

11/28/1994 HIT; no mention of replacing pump

10/4/1995 HIT; no mention of replacing pump

12/26/2001 replace tbg string, new pump.

2/4/2002 HIT; no mention of replacing pump

12/15/2004 pump change

8/21/2008 tag fill 11' under EOT; press test tbg 500#; plan on clean out to PBTD w/bailer next day, but no repor

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Ram #2

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.