RECEIVED

Form 3160-5 (August 2007) SEP 0 9 2015

Oil Well

PO Box 4289, Farmington, NM 87499

4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)

1. Type of Well

2. Name of Operator

3a. Address

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE - Other instructions on page 2.

Burlington Resources Oil & Gas Company LP

Other

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

	ı	5.	Lease	Serial	No
--	---	----	-------	--------	----

6. If Indian, Allottee or Tribe Name

SF-078092

Farmington Field SUNDRY NOTICES AND REPORTS ON WELLS
Bureau of Landpornot use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

X Gas Well

7. If Unit of CA/Agreement, Name and/or No.
8. Well Name and No.
Douthit C Federal 100
9. API Well No. 30-045-30184
10. Field and Pool or Exploratory Area
Basin FC
11. Country or Parish, State

Surface Unit K (NESW), 1330' FSL & 1800' FWL, Sec. 34, T27N, R11W San Juan **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Acidize Deepen Water Shut-Off Production (Start/Resume) Well Integrity Alter Casing Fracture Treat Reclamation Subsequent Report Casing Repair **New Construction** Recomplete Other Conduct Change Plans Plug and Abandon Temporarily Abandon MIT for TA extension Final Abandonment Notice Convert to Injection Plug Back Water Disposal

3b. Phone No. (include area code)

(505) 326-9700

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was TA'd on 12/10/10. Burlington Resources requests permission to conduct a MIT so that the TA status can be extended per OCD requirements.

Notify NMOCD 24 hrs prior to beginning operations OIL CONS. DIV DIST. 3
SEP 1 1 2015

and

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Patsy Clugston				
Signature Falsy Clust	Date	9/8/	/2015	
THIS SPACE FOR FEI	DERAL OR	STATE OFFICE USE		
Abdelgadi Elmadani		Title PE	Date 09/09/15	
Conditions of approval, if any, are attached. Approval of this notice does not warrant of that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.	Office FFO			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any	y person knowin	gly and willfully to make to any departme	ent or agency of the United States any	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD A

ConocoPhillips DOUTHIT C FEDERAL 100 Expense - MIT

Lat 36° 31' 41.999" N

Long 107° 59' 35.999" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COP safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. Check casing and bradenhead pressures and record them in WellView. If there is pressure on the BH, contact Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure.
- 4. Load casing with water & corrosion inhibitor, as necessary. Perform MIT (Mechanical Integrity Test) above the bridge plug at 1588' to 560 psig for 30 minutes on a 2 hour chart with 1000 lb. spring. If the test passes, SI the well. RD pump truck and MOL. If the test fails, contact the Rig Superintendent and Wells Engineer.

SEP 1 1 2015

