



### Gallegos Canyon Unit 77

Fruitland Coal

API # 30-045-08235

T-29N, R-12-W, Sec. 18 Unit M  
San Juan County, New Mexico

#### Wellwork History

Spud Date 1/26/1957

6/23/59: Cemented PC formation; Completed Fruitland Coal

8/18/80: Pulled 57 jts 1.25 lin pipe, 10' perforated jt.

CO to 1327'. Ran SN, 1 jt tubing, 5 1/2" Baker tension Packer, 36 jts 2 3/8" tubing. SN @ 1167.8'. Pkr @ 1134.05'

4/27/1990: Pulled packer and 2 3/8" tbg. No record of anything ran in hole.

#### Formation Tops

Surf sand & sha	surface
Kirtland	260'
Fruitland sand	1135'
Pictured Cliffs	1428'

GL 5524'

Plunger Well

Hole size?

8-5/8", 32# @ 268'

Cmt w/ 150 sks cement  
(circulated to surface)

#### Fruitland Coal Perfs (1959)

1161' - 1191' @ 4 spf

Sand water frac'd using 21,000 gals water & 30,000 lbs sand

#### Pictured Cliffs Perforations (1/1957)

1435' - 1448' unknown density

6/1959 cemented PC perfs  
w/ 50 sacks cement  
TOC cement plug @ 1376'

Hole size ?

5 1/2", 24#, @ 1500'

Cmt w/ 75 sks cement

PBTD: 1376'  
TD: 1500'