

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-045-34484
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. Fee
7. Lease Name or Unit Agreement Name 78407E
8. Well Number 185C
9. OGRID Number 120782
10. Pool name or Wildcat Blanco MV
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
WPX Energy Company LLC

3. Address of Operator
P.O. Box 640, Aztec, NM 87410

4. Well Location

Unit Letter F, 1740 feet from the N line and 2190' feet from the W line
Section 16 Township 31N Range 6W NMPM San Juan County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

WPX previously spud/set surface casing only on 10/26/11.

WPX proposes to plug and abandon the above well per the Plug and Abandonment procedure below:

MOL. Prep wellhead for cement work. RU cement equipment.

Spot Plug #1 from 304' to surface with 120 sxs cement.

SI well. Cut off wellhead. Top off casings if necessary. Set P&A marker.

Record GPS and take photo of marker. RD and MOL.

OIL CONS. DIV DIST. 3

OCT 23 2015


Spud Date:

10/24/11

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE Permit Tech III DATE 10/23/15

Type or print name Lacey Granillo

E-mail address: lacey.granillo@wpxenergy.com

PHONE: 505-333-1816

For State Use Only

DEPUTY OIL & GAS INSPECTOR

APPROVED BY: 

TITLE

DISTRICT #3

DATE 11/2/15

Conditions of Approval (if any):

2
KC

ROSA UNIT #185C

Proposed P&A

MV/DK
(page 1)

Spud: 10/24/11

SHL: 1740' FNL & 2190' FWL
SE/4 NW/4 Section 16 (F), T31N, R6W

BHL: 1550' FSL & 2550' FEL
NW/4 SE/4 Section 16 (J) 31N 6W

SAN JUAN NM
API: 30-045-34484



Run 13 jts 9-5/8", 36#, K-55, LT&C casing, set @ 304'.
Surface Casing -Hole Size: 12-1/4"

Plug #1: 304' - 0'
Class B Cement, 120 sxs

HOLE SIZE	CASING	CEMENT	VOLUME	CMT TOP
12-1/4"	9-5/8"	101sx	161cu.ft.	Surface

Lg 10/13/15