OP1 30-045-08413



#### **BRUINGTON GC B 001-DK**

Dakota API #: 300450841300 Unit A - Sec 15 - T29N - R12W San Juan County, NM

#### Well History

1/5/64 Spud date
2/3/64: Completion date
6/21/93: Reparied bradenhead
Tagged fill at 6237'
Ran CBL from 6012' -100'. TOC @ 1220'
Perf at 1200'. Pumped 301 sx cmt.
Pressure tested repair to 500 psi.
Cleaned out to 6237'
12/14/11: Changed master valve.
Tagged fluid at 5400'.
Tagged fishing neck at 6142'.
9/11/12: Braden head test
Casing pressuer = 499 psi
Bradenhead = 33 psi
Blew down to zero. Built to 14 psi in 5 min.

***			THE .	
FO	rma	tion	1 1 0	D


Pictured Clif	1670
Lewis Shale	1830
Mesaverde	3215
Mancos	4368
Gallup	5285
Lower Manc	5637
Greenhorn	6020
Graneros Sha	6082
Graneros DK	6,126
Main Dakota	6,195

SN F collar

Tubing Depth 6191'

#### Ground Eleveation 5700' 5625' KB

TD:6310'



Stage 2: 1000 sx cmt

## OIL CONS. DIV DIST. 3

DEC 1 8 2015



GL 5482' KB 5495' DEL 1

### **Gallegos Canyon Unit 536**

Pictured Cliffs
API # 30-045-29046
T-29N, R-13-W, Sec. 13
San Juan County, New Mexico

Well History

Spud Date: 02/1994

Completion Date: 5/7/1994

Well Svc (1997) - C/O fill; Run pump & rods Well Svc (1998) - C/O fill; pull plugged pump Well Svc(1999) - Changed entire tubing string

Well Svc (2002) - C/O fill. Replace holey tubing

Well Svc (2003) - Replace holey tubing

Well Svc. (2004) - Hole in tubing in Joint #33

Well Svc. (2004) - Hole in tubing in Joint #33

Well Svc. (2004) - Hole in tubing in Joint #45

Well Svc. (2005) - Hole in tubing in Joint #39

Well Svc(2007) - Hole in tubing Joint # 38

Well Svc (2008) - Pump change

Well Svc (2008) - Pump stuck in scale

4/29/10: Switched from steel rods to continuous fiberglass rods. Changed out pump. Found hole in 47th jt of tubing. 3/15/2011: No fill, severe corrosion and rod wear on bottom 3 jts, Run 3 jts boronized tubing.

6/12/2012: change out down-hole pump, pump and mule shoe scaled up

2/12/2013: Pull fiberod and pump. No scale, pump full of coal fines. Run new pump.

#### **Formation Tops**

Ojo Alamo Surface Kirtland 124' Fruitland 1,103' Coal 1,150 PC 1,394'


NIPPLE, PROFILE, "F", 2.375 OD, 1.780 ID @ 1461'

#### Deviation

Depth: 154' - 1/4 degrees Depth: 625' - 1/2 degrees Depth: 1,121' - 3/4 degrees Depth: 1,592' - 2-3/4 degrees

EOT@ 1480'

updated 4/4/2013



PBTD 1542' TD 1593'

# ΓΟC: Circulated to surface

#### Surface Casing Data

8-3/4" Hole 7", 20#, J-55 @ 151' Cmt w/ 100 sks (class 'B' cement) w/ 3% CaCl2 & 1/4#/sk celloseal

TOC @ 750' (of the 4-1/2" CSG) CBL

Rod Details	Length	
PUMP, RHAC, 2.0" X 1.25" X 9'	9'	
Sinker Bars, K, 1.5" x 25' (3jt)	75'	
Fiberglass Rods .5"	1350'	
Pony Rod .75" x 8' (1)	8'	
Pony Rod .75" x 6' (1)	6'	
ROD, POLISHED: 1.25 X 16 FT	16'	

lubing Details	Length
MULE SHOE, 2.375 4.7# J-55	18'
NIPPLE, PROFILE, "F", 2.375 OD, 1.780 ID	1'
TUBING, 2.375, 4.7#, N-80 (3jts)	93'
TUBING, 2.375, 4.7#, J-55 (42jts)	1323'
Tubing Pup Jt, 2.375" 4.7# J-55 (1jt)	2'
TUBING, 2.375, 4.7#, J-55, EUE	31'

#### Perforation Data (PC)

1,394' - 1,414' w/ 4 SPF 1,418' - 1,432' w/ 4 SPF

#### Frac'ed

20# gel, 70Q foam 129,000# of Brady Sand

#### **Production Casing Data**

6 1/4" Hole 4 1/2", 10.5#, @ 1588' Cmt w/ 250 sks of 50/50 poz, 2% gel 10% salt & 25 sx Class B cmt