

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-31-05266
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. Fee
7. Lease Name or Unit Agreement Name Farris
8. Well Number 001
9. OGRID Number
10. Pool name or Wildcat Seven Lakes
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6540' GI

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Farris Mines

3. Address of Operator
419 Palomino Lane, Bloomfield, NM 87413 505-632-8438

4. Well Location

Unit Letter P, 490 feet from the S line and 990' feet from the E line
Section 18 Township 18N Range 10W NMPM McKinley

County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Farris Mines proposes to plug and abandon the above well as follows:

MO and RU. TOH with tubing and rods. Pressure test casing to 500#.

Plug #1: Mix and pump 50 sxs and fill casing from 390' to surface. WOC. Top off as necessary.

Set P&A marker. RD and MOL.

* Provide information showing circulation on original casing or perform CBL prior to cementing.

Notify NMOCD 24 hrs
prior to beginning
operations

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Jonnie L. Smith

TITLE

Manager

DATE

12/29/15

Type or print name

Lyndell Smith

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

Red Bell

TITLE

DEPUTY OIL & GAS INSPECTOR

DISTRICT #3

DATE

2/8/16

Conditions of Approval (if any):