

GCU 268 PC

Pictured Cliffs API# 30-045-22239 Unit P - Sec 32 - T28N - R12W San Juan County, New Mexico

8/17/2015

Formation Tops

 Ojo Alamo
 50'

 Kirtland
 150'

 Fruitland
 1000'

 Pictured Cliffs
 1285'

3/4" Rods 2x1.25x9 RHAC

2-3/8" Tubing 1.875" XN Nipple @ 1324' 1.78" F Nipple @ 1329' EOT @ 1347'

KB: 5688' GL: 5679'

OIL CONS. DIV DIST. 3
DEC 1 8 2015

9-7/8" Hole 7", 23#, K-55 @ 90' Cmt w/ 60 sx Class A w/ 3% CaCl2 Circulated to surface

Dakota Perforations

1306'-1320' w/ 4 spf 1320'-1330' w/ 1 spf 1363'-1367' w/ 1 spf 1372'-1378' w/ 1 spf

Frac'd w/ 10,000 gal foam carrying 10,500 lbs 20/40

6-1/4" hole 4-1/2" 10.5#, J-55 @ 1442' Cmt with 110 sx Class A Circulated to surface

PBTD: 1353' TD: 1443'