Form 3160-5 (March 2012) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			and the second sec	NM-93255 6. If Indian, Allottee or Tribe Name MAY 0.2 2015 Navajo Indian Tribe	
SUBMI	TIN TRIPLICATE - Other instructions	7. If Unit of CA/Agree	7. If Unit of CA/Agreement, Name and Wington Field Office Bureau of Land Managemen		
1. Type of Well Oil Well Gas W	/ell Other	8. Well Name and No.			
2. Name of Operator Running Horse Production Company	y	9. API Well No. 30-045-35490	9. API Well No. 30-045-35490		
3a. Address P.O. Box 369 Ignacio, CO 81137	o. (include area code) 52		10. Field and Pool or Exploratory Area Gallegos Wash, Farmington, West		
4. Location of Well (Footage, Sec., T.,)		11. County or Parish, State			
809' FSL & 897' FWL Section 8, 26N, 12W		San Juan County, N	San Juan County, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA					
TYPE OF SUBMISSION TYPE OF ACTION					
Notice of Intent	Acidize Dee Alter Casing Frac	pen	Production (Start/Resume) Reclamation	Water Shut-Off Well Integrity	
Subsequent Report		v Construction	Recomplete	Other	
Final Abandonment Notice		g and Abandon	Temporarily Abandon Water Disposal		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If					
testing has been completed. Final A determined that the site is ready for Running Horse Production Company In response to the BLM's 30 day der 1) A NOIA, a plugging and abandonn 2) Running Horse Production compa	y proposes to P&A the above well per the nand letter please accept the following: ment procedure, a current wellbore ske my proposed plugging the Tenneco Fed	ther all requirements, incluents in the attached procedure the attached procedure the attached proposed point of the surface o	uding reclamation, have been ost P&A welbore sketch. mer or fall of 2016. Runnin	completed and the operator has g Horse has a number of other	
wells that are candidates to be plugged and abandoned in 2016. As this candidate field is narrowed, this well will be included in our 2016 P&A campaign which I expect to be completed prior to December 1, 2016.					
ACTION DOES NOT RELIEVE THE LESSEE AND				TTACHED FOR NS OF APPROVAL OIL CONS. DIV DIST. 3	
14. I hereby certify that the foregoing is tr	ue and correct Name (Printed/Typed)	1		JUL 22 2016	
R. Andrew Parker	\cap	Title Senior Product	tion Engineer		
Signature R.A.	aler	1	8/2016		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
that the applicant holds legal or equitable in entitle the applicant to conduct operations the	opproval of this notice does not warrant or the othose rights in the subject lease which w hereon.	ould Office FF	FO	ate 7/19/16	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					
(Instructions on page 2)					
NMOCD					

PLUG AND ABANDONMENT PROCEDURE


April 15, 2016

Tenneco Federal #1R Basin Fruitland Coal 809' FSL, 897' FWL, Section 8, T26N, R12W, San Juan County, NM API #30-045-35490


Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

This project will use of an A-Plus steel waste tank to contain waste fluids circulated from the well and cement wash up.

- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
- Rods: Yes___, No_X_, Unknown___. Tubing: Yes X_, No ___, Unknown___, Size <u>2-3/8</u>", Length <u>1243</u>'.
 Packer: Yes___, No_X_, Unknown___, Type ____. If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
- Plug #1 (Fruitland Coal perforations and Pictured Cliffs top, 1228' 1011'): TIH with open ended tubing. Load casing with water and circulate well clean. Mix 87 sxs Class B cement (100% excess) and spot a plug to cover the Fruitland Coal perforations and Pictured Cliffs top. PUH and WOC. TIH and tag cement; top off if necessary.
- Plug #2 (Fruitland top, 896' 796'): Mix 56 sxs cement and spot a balanced plug inside the casing to cover the Fruitland top. PUH.
- Plug #3 (13-3/8" casing shoe, 460' 360'): Mix 56 sxs cement and spot a balanced plug inside the casing to cover the 13-3/8" casing shoe top. PUH.
- 6. Plug #4 (Kirtland and Surface, 182' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 70 sxs cement and spot a balanced plug from 182' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 182' and the annulus from the squeeze holes to surface. Shut in well and WOC.
- ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. Cut off anchors and clean up location. Restore location per BLM stipulations.



TD 6000' PBTD 5964'



TD 6000' PBTD 5964'

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD, FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Tenneco Federal #1R

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

a) Set plug #4 (259-0) ft. to cover the Kirtland top. BLM picks top of Kirtland at 209 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.