Form 3160-5 (February 2005)

# UNITED STATES DEPARTMENT OF THE INTERIOR

RECEIVED

OCT 05 2016

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

BUREAU OF LAND MANAGEMENT 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS Farmington Field SE-078762 Do not use this form for proposals to drill or to re-enter an Land Managerindian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. Rosa Unit 1. Type of Well 8. Well Name and No. OIL CONS. DIV DIST. 3 Rosa Unit #382 Oil Well Gas Well Other 2. Name of Operator 9. API Well No. OCT 07 2016 WPX Energy Production, LLC 30-039-29364 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 3a. Address PO Box 640 505-333-1806 **Basin Fruitland Coal** Aztec, NM 87410 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State 95' FSL & 1415' FEL, Section 12, T31N, R 5W Rio Arriba, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deepen Production (Start/Resume) Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other MIT/TA Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonmer Convert to Injection Plug Back Water Disposal Notice 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) WPX requests to conduct a MIT in order to keep the well in TA status per attached procedure and wellbore diagram. The last MIT was done on 10/26/11. WPX would like to save the well for possible future development. BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND **OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS 14. I hereby certify that Name (Printed/Typ Lacey Granillo Title Permitting Tech III Signature Date 10/5/16 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.

(Instructions on page 2)

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



## **Legacy MIT Procedure**

Well: Rosa 382 API: 30-039-29364

Location: Rio Arriba County, New Mexico

S-T-R: 12-31N-5W Date: 40ct16

Objective: Conduct Mechanical Integrity Test (MIT)

AFE: N/A

#### **EH&S Notes:**

✓ Personnel Safety is the number one job, no exceptions.

- ✓ Please follow appropriate WPX Energy contractor protocols for this job plan. (Please see your WPX Energy Business Representative if you have any questions; Contractor protocols can be found in the WPX Energy Contractor Guide.)
- ✓ Continuous personal H2S monitoring is required. Any H2S alarms or other indications above 10 ppm will require work to stop and the situation to be evaluated
- ✓ A Safety meeting shall be held each morning before work and subsequent "tailgate" safety meetings are to be held during the day when operation objectives shift in nature and intent. Please ensure these are documented per the WPX Contractor Guide.

#### Prior to Job:

- Notify BLM and NMOCD 24-48 hours prior to MIT such they can witness if they choose.
- Arrange for pump truck with chart recorder for MIT based on NMOCD witness availability.

Current Wellbore Status: Well is TA'd, CIBP @ 2,949'.

- Casing
  - o 7" 23# K-55 LTC set @ 3,645'
  - Top of Cement @ surface.

#### Procedure:

- Ensure BLM and NMOCD is present to witness or has given authorization to proceed with MIT w/o witness.
- Tie pump onto casing. Load hole as needed to perform MIT-hole should be full. Conduct 500-550 psi MIT for at least 30 minutes, recording pressure with a chart recorder per regulatory requirements. Turn chart into NMOCD as required.

#### Notes:

Ensure all JSA's, ECP's and Lockout procedures are in place for energized piping or equipment.

### ROSA UNIT #382 BASIN FRUITLAND COAL

Location:


SHL: 95' FSL and 1415' FEL SW/4 SE/4 Sec 12(O), T31N, R05W

BHL: 1093' FSL and 1843' FEL SW/4 SE/4 Sec 12(O), T31N, R05W Rio Arriba, New Mexico

Elevation: 6671' GR API # 30-039-29364

Тор	Depth
Ojo Alamo	2867
Kirtland	2976'
Fruitland	3320'
Base of Coal	3497'

Landed 94 jts 7", 23#, K-55, LT&C csg @ 3645' TMD (3472' TVD). Float @ 3605'. Cemented with 600 sx cmt.



Landed 4-1/2" liner @ 4415' as follows: liner hanger, 1 jt 4 ½", 10.5#, J-55 non-perfed csg, 33 jts, 4 ½", 11.5#, J-55 perfed csg & shoe on bottom. Liner perfs are from 3056' to 4411'. Did not cement

Spud date: 9/20/05

Completed: 10/07/05

Hole Size	Casing	Cement	Volume	Top of CMT
12-1/4"	9-5/8",36#	255 sx	354 cu ft.	surface
8-3/4"	7", 23#	600 sx	1144 cu ft.	surface
6-1/4"	4-1/2",11.6#	Did Not Cmt	N/A	N/A