RECEIVED

Form 3160-5 (June 2015)

UNITED STATES

SEP 0 7 2017

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

5. Lease Serial No. **701-02-0014**

SUNDRY NOTICES AND REPORTS of WELLS Field Office
Do not use this form for proposals to drill or to re-enter an

6. If Indian, Allottee or Tribe Name Jicarilla Apache

abandoned w	vell. Use Form 3160-3 (A	PD) for such proposa	ls.			
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit of CA/Agreement, Name and/or No.			
Type of Well	☐Gas Well ☐Other			8. Well Name and No. Jaeco 26-3 22 1A		
2. Name of Operator WPX Energy Production, LLC				9. API Well No. 30-039-30050		
3a. Address 3b. Phone No. (include area code) PO Box 640 Aztec, NM 87410 3b. Phone No. (include area code) 505-333-1808		de)	10. Field and Pool or Exploratory Area Blanco Mesaverde			
4. Location of Well (Footage, Sec., T.,R,M., or Survey Description) SHL: 790' FSL & 1850' FEL Sec 22 T26N R3W Unit: O BHL: 982' FSL & 2049' FEL Sec 22 T26N R3W Unit: O				11. Country or Parish, State Rio Arriba, NM		
12.	CHECK THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	E OF NOTIO	CE, REPORT OR OTHER DATA		
TYPE OF SUBMISSION		TYPE OF ACTION				
☑Notice of Intent	☐Acidize ☐Alter Casing	☐Deepen ☐Hydraulic Fracturing	□Prod	uction(Start/Resume) amation	□Water S	
☐Subsequent Report	Casing Repair	☐ New Construction	Reco	omplete	Other	2 nd MIT & TA
☐Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon ☐ Ten	□Tem	nporarily Abandon		Request
BP	☐Convert to Injection	□Plug Back	□Wate	r Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)

SEP 1 2 2017

Per further evaluations, WPX Energy request to perform another Mechanical Integrity Test (MIT) to continue a Temporary Abandon (TA) status with CIBP previously set @ 5577' on 10/26/12 per MIT/TA procedure and wellbore diagram attached.

Notify NMOCD 24 hrs prior to beginning operations

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

BLM'S APPROVAL OR ACCEPTANCE OF THIS
ACTION DOES NOT RELIEVE THE LESSEE AND
OPERATOR FROM OBTAINING ANY OTHER
AUTHORIZATION REQUIRED FOR OPERATIONS
ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	
Marie E. Jaramillo	Title: Permit Tech
Signature Way & Owall	Date: 9/7/17
THE SPACE FOR FED	ERAL OR STATE OFICE USE
Approved by Lilliam Tambekon	Title Petroleum Engineer Date 9/8/2017
Conditions of approval, if any, are attached. Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.	t or Office FFO

NMOCDAY



MECHANICAL INTEGRITY TEST

JAECO 26-3 22 #1A RIO ARRIBA, NEW MEXICO SEPTEMBER 2017

Ensure fuel used during job & estimate of vented gas is reported in daily reports

Continuous personal H2S monitoring is required. Any H2S alarms or other indications above 10 ppm will require work to stop and the situation to be evaluated

OBJECTIVE:

1) Prepare well for and conduct mechanical integrity test.

PRIOR TO PRIMARY JOB:

- 1) Verify location is okay for testing operations.
- 2) Ensure JSA, ECP's and lockout procedures are in place for the flowline and other energized piping or equipment.

SAFETY NOTICE

PERSONNEL SAFETY IS THE NUMBER ONE JOB.

NO EXCEPTIONS!!!

PLEASE FOLLOW APPROPRIATE WPX CONTRACTOR PROTOCOLS FOR THIS JOB PLAN

Please see your WPX Representative if you have any questions; Contrator protocols can be located in the WPX Contractor Guide.

PROCEDURE:

Note: A safety meeting shall be held each morning before work and subsequent "tailgate" safety meetings are to be held during the day when operation objectives shift in nature and intent (i.e. beginning/ending fishing operations, squeeze jobs, rigging down, etc.) Please ensure these are documented per the WPX Contractor Guide

- 1) Notify BLM and NMOCD 24hrs prior to start of work.
- 2) Spot equipment, MIRU.
- 3) CIBP is set at 5577'.
- 4) Load csg with produced water treated with biocide and corrosion inhibitor as required.
- 5) Pressure test csg to 500psi surface pressure for 30 minutes.
 - a) Pressure drop cannot be greater than 10% over 30-minute period.
 - b) Monitor surface csg pressure and flow during test.
 - c) Top off csg after the test.
 - d) Record test on chart recorder with maximum 2-hr clock and maximum 100-lb spring, which has been calibrated within 6 months prior to test.
 - e) Witnesses to test shall sign the chart
- 6) Secure well and return to TA status.
- 7) RDMO.
- 8) Turn all data in to office.

JAECO 26-3 22 #1A BLANCO MESA VERDE

Location: 790' FSL & 1850' FEL SW/4 SE/4 Section 22 (O), T26N, R3W

Rio Arriba Co., NM

Note: Due to crooked hole the final BHL is 982' FSL & 2049' FEL

Elevation: 7362' GR API#: 30-039-30050

Tops	Depth		
Ojo Alamo	3580'		
Kirtland	3768'		
Fruitland	3810'		
Pictured Cliffs	3936'		
Lewis	4140'		
Cliff House	5667'		
Menefee	5812'		
Point Lookout	6123'		
Mancos	6396'		
Dakota	8210'		

 $\begin{tabular}{ll} $CliffHouse/Menefee & 5677' - 5932' (58, 0.34" holes) - Frac $w/1500\#\ 20/40$ brown sand followed $w/3000\#\ 100$ mess $Mono\ Prop.. \end{tabular}$


 $\frac{Point\,Lookout}{w/1500\#\,20/40}\;6014'-6266'(49,\,0.34"\,holes)-Frac\\ w/1500\#\,20/40\;brown\;sand\;followed\;w/7000\#\,100\;mesh\\ Mono\;Prop$

<u>3rd Mancos:</u> 7133'-7238' (45, 0.36" holes) – Pump test only – NO FRAC

2ns Mancos: 7300'-7438' (60, 0.34" holes) – Frac w/8440# 100 mesh white sand followed w/88664# 40/70 white sand

 1^{st} Mancos: 7460'-7642' (78, 0.34" holes) – Frac w/9160# 100 mesh white sand followed w/120760# 40/70 white sand

<u>Dakota</u>: 8214' - 8390' (69, 0.34" holes) – Frac w/8020# of 100 mesh white sand followed w/120420# 40/70 white sand



Spud Date 10-31-08 Completed 02-23-09

8 jts of 10-3/4", 40.5#, J-55, ST&C csg. Set @ 318'

110 jts of 7-5/8", 26.4#, J-55, LT&C csg. Set @ 4391'. Float @ 4349'

191 jts of 5-1/2", 17#, N-80, LT&C csg. Set @ 8650'. Float collar @ 8603'. Marker jts @ 3724'

CIBP @ 5577'

P&A Mancos 2-7-09 as follows: Set 5.5" Cmt Rtr @ 7025' - Finish RU Halliburton Services squeeze manifold & hardline, HTGSM w/ all contractors on loc - Psi test lines to 4000 psi, pump 20 bbls FW, pump 21 bbls 15.3# cmt slurry (100 sks) @ 2.4 bph @ EOC Psi = 72 psi, Displacement to end of retainer = 40.7 bbls, cut displacement short 1.5 bbls to leave 50' of cmt on top of retainer, sting out of retainer - LD 3 jts 2 7/8" tbg & reverse out w/ 50 bbls FW

P&A Dakota 1-8-09 as follows: Set 5-1/2" cement retainer @ 8075', P&A Dakota perfs 8214'-8390' w/ 100 sxs type-3 neat cmt + .2% R-3 @ 14.6 ppg, 1.39 yield, inj rate 3 bpm @ 1100#, pump 25 bbls cmt @ 14.6 ppg 2 bpm @ 930#, displ w/ 45.5 bbls water 3 bpm @ 470#, final press 2330#, ISDP=2000#, sting out of ret, PU to 8013', rev out w/ 170 bbls 2% kcl water, rev. out 1.5 bbls cmt,

TD @ 8652'
PBTD @ 6936'

HOLE SIZE	CASING	CEMENT	CU. FT.	CMT TOP
14 3/4"	10 3/4"	250 sx	350 cu.ft.	surface
9 7/8"	7 5/8"	810 sx	1637 cu.ft.	surface
6 3/4"	5 1/2"	195 sx	454 cu.ft.	5200' (CBL)